



1. Approving Civil Aviation Authority/Company FAA/United States	2.	3. Form Tracking Number: 175505
--	----	---

AUTHORIZED RELEASE CERTIFICATE
FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

4. ORGANIZATION: Name and Address  Med-Craft, Inc.	2450 N.W. 110th Avenue Miami, Florida 33172 Tel.: (305) 594-7444 Fax: (305) 594-9080 F.A.A. Repair Station N° LZ4R354M	5. Work Order / Contract / Invoice Number: FP-J41946
---	--	--

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1.	Door Damper Actuator	FE240-004	1	890	OVERHAULED

12. Remarks:
Work Order 175505 prescribing the actual work performed is attached. Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number: EASA.145.4663.
The work started in Block 11 was accomplished IAW CMM 52-11-05 Rev Date: 03/04/20 Rev No: 9

13a. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input type="checkbox"/> Other regulations specified in Block 12 Certified that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.	14a. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input type="checkbox"/> Other regulations specified in Block 12 Certified that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.
13b. Authorized Signature:  CS	14b. Approval/Certificate Number: LZ4R354M
13c. Date (dd/mm/yyyy): 29 SEP 2023	14c. Date (dd/mm/yyyy): 29 SEP 2023

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.
Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in block 1.
Statements in Block 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

WORK ORDER

Work Order :175505
Part Number :FE240-004
Serial Number :890
ATA Number :52-11-05
Service Req. :Test

Repair Order :FP-T41946
Description :Door Damper Actua
Manufacturer :UTC Aerospace Sys
Revision Date :03/04/20
Date :09/06/23

FAA REPAIR STATION LZ4R354M

PRELIMINARY VISUAL INSPECTION

VISUAL INSPECTION APPEARS NORMAL

HIDDEN DAMAGE INSPECTION

N/A

Receiving Clerk: Giovanni Acosta

DATE: 09/06/2023

CONDITION REPORTED

NONE

REMARKS

NONE

AD NOTES, Customer Specs

THERE ARE NO A.D. NOTES FOR THIS UNIT

Verified by: *Carl Zang*

DATE: 29 SEP 2023



WORK ORDER

Work Order :175505
Part Number :FE240-004
Serial Number :890
ATA Number :52-11-05
Service Req. :Test

Repair Order :FP-T41946
Description :Door Damper Actua
Manufacturer :UTC Aerospace Sys
Revision Date :03/04/20
Date :09/06/23

FAA REPAIR STATION LZ4R354M

PRELIMINARY FUNCTIONAL TEST/TEARDOWN REPORT

***Pretest**

Upon pretest found:

1. Unit failed holding pressure test.



***Disassembly**

Upon disassembly and inspection, the following discrepancies were found:

1. Set and compressed packings.
2. Corroded hardware.
3. Plating will be performed.
4. Heavy nicks and scratches on body and nitrogen tank.
5. Damaged placard.
6. Worn seals.
7. Missing pin assembly upon arrival.
8. Unit will require overhaul.

TECHNICIAN: Robinson Montas

SUPERVISOR: _____

WORK ORDER

Work Order : 175505
Part Number : FE240-004
Serial Number : 890
ATA Number : 52-11-05
Service Req. : Test

Repair Order : FP-T41946
Description : Door Damper Actua
Manufacturer : UTC Aerospace Sys
Revision Date : 03/04/20
Date : 09/06/23

FAA REPAIR STATION LZ4R354M

CORRECTIVE ACTION

1. Replaced all worn and damaged parts.
2. Reassembled and tested in accordance with the manufacturer's specifications.
3. Unit passed all functional tests.

Unit overhauled and certified for return to service

Tech : Daniel Ruiz Spvrs :  Date : 29 SEP 2023

SERVICE PERFORMED

Overhauled

FINAL INSPECTION/RETURN TO SERVICE

Issued with respect to job performed as checked above.
The component identified above was inspected in accordance with current regulations of the F.A.A. and is approved for return to service. Pertinent details of the repair are on file at this agency under

W.O.# 175505 Date 29 SEP 2023

Signed 



WORK ORDER

Work Order :175505
Part Number :FE240-004
Serial Number :890
ATA Number :52-11-05
Service Req. :Test

Repair Order :FP-T41946
Description :Door Damper Actua
Manufacturer :UTC Aerospace Sys
Revision Date :03/04/20
Date :09/06/23

FAA REPAIR STATION LZ4R354M

Removed Components

Part Number

Serial Number

FE240-500-10

21757

Installed Components

Part Number

Serial Number

FE240-500-10

21757

TECHNICIAN: Robinson Montas

DATE: 09/12/23