Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown. country specified. Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the This certficate does not constitute authority to install the part 13a. Certifies the items identified above were manufactured in conformity to: 4. Organization Name and Address 13d. Name (Typed or Printed) 13b. Signature: 12. REMARKS . Item: 7. Description: Saint-Laurent QC H4S-2B7 Canada 7055, rue Alexander Fleming AJW Technique Inc Approved design data and are in a condition for safe operation Non-approved design data specified in Block 12 UNIT CLEANED, REPAIRED AND TESTED SERVICEABLE IN ACCORDANCE WITH CMM 21-63-45, REVISION No. 05 DATED SEP 01/2012. FOR MORE INFORMATION REFER TO MAINTENANCE REPORT. Transport Canada Approving Civil Aviation Authority/Country CONTROLLER-ZONE TEMPERATURE 13e. Date 13c. Approved Organization Number **AUTHORIZED RELEASE CERTIFICATE** 8. Part Number: 978B0000-02 FORM ONE AJW technique Installer Responsibilities 14a. 14b. Signature 14d. Name (Typed or Printed) Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations. 9. Quantity: Other regulation specified in Block 12 CAR 571.10 Maintenance Release Hassan Boudemlij 1.00 10. Serial/Batch Number: 978B00LI000452 Maintenance performed in accordance with FAR 43.17 930 14e. Date (dd/mmm/yyyy) 14c. Approval Organization Number EASA Approval No.: EASA.145.7260 25/Sep/2019 Status/Work: WO88090 3. Form Tracking Number. Invoice Number: 5. Work Order, Contract or REPAIRED R365771-1



7055 Alexander-Fleming st, Suite 100, Saint-Laurent, QC, Canada, H4S 2B7 www.ajw-group.com

## Tear Down/Inspection Report

Work Order: WO88090 Date Printed: 9/25/2019 Customer RO: R365771-1

Page: 1

To:

A J Walter Aviation Ltd. THE HEADQUARTERS MAYDWELL AVENUE SLINFOLD, WEST SUSSEX RH13 0AS UNITED KINGDOM

Code: AJW01

Fax:

Descr: CONTROLLER-ZONE TEMPERATURE

Phone:

Email:

P/N: 978B0000-02

Qty: 1

S/N: 978B00LI000452

Mfg: LIEBHERR TOULOUSE

TSN: 0

**TSO**: 0

TSR: 0

CSN: 0

CSO: 0

CSR: 0

P/N Out: 978B0000-02

S/N Out: 978B00Ll000452

Symptoms:

CODE:

**REASON FOR REMOVAL** 

DETAILS:

Cabin temp control XX on ECAM.

Faults:

CODE:

**INITIAL TEST FAILURE** 

DETAILS:

Initial test failed intermittent ( after warming up ) chapters :

6: INPUT MODULE 1 TEST 7 : INPUT MODULE 2 TEST 9: POWER MODULE 1 TEST 10 : POWER MODULE 2 TEST.

CODE:

CUSTOMER REASON FOR REMOVAL CONFIRMATION

**DETAILS:** 

Reason for removal is confirmed.

CODE:

DISASSEMBLY / INSPECTION FINDINGS

**DETAILS:** 

During disassembly and inspection of the unit the following anomalies were found:

unit dusty needs cleaning.

found some cold soldering joints on boards:

POWER BOARD 1 ( R7-Ř10, C16-C17, C30-C31, RN8-RN13.. ).

POWER BOARD 2 ( R6, R9, R16-R17..... ).

CODE:

**CLEANING** 

**DETAILS:** 

Cleaning is required due to contaminated with dust and dirt from ventilation duct

CODE:

DETAILS:

**PCBR** 

Pcb level 3 repair required on boards: POWER BOARD 1 P/N: 978A2000-03 POWER BOARD 2 P/N: 978B2200-01.

CODE:

**REPAIR** 

DETAILS:

Unit will be repaired in accordance with cmm.

Corrective Actions:



7055 Alexander-Fleming st, Suite 100, Saint-Laurent, QC, Canada, H4S 2B7 www.ajw-group.com

## Tear Down/Inspection Report

Work Order: WO88090
Date Printed: 9/25/2019
Customer RO: R365771-1

Page: 2

CODE: REPAIRED

DETAILS: UNIT CLEANED, REPAIRED AND TESTED SERVICEABLE IN ACCORDANCE WITH CMM 21-63-45.