

AJW AVIATION LTD

SR NUMBER: 5018029660

Honeywell International Inc. 23500 W 105th Street Olathe KS 66061

SR NUMBER: 501802	29660 3	48649321		FAA: PR2R093L	EASA: EASA.145.4140
PO: R418832	SETTINGE STREET	CUSTOMER PART NUMBER:	de acti	CONTRACT NUMB 440098719	ER:
DATE REJECTED: 18 OCT 2023		DATE RECEIVED: 25 OCT 2023		DATE COMPLETED 21 DEC 2023	D:
A/C TYPE: BOEING B737-800		A/C TAIL NUMBER: TC-CPL		A/C SERIAL NUMB 40010	BER:
PACKING STATUS: No		SEALS INTACT: Intact		PHYSICAL DAMAG	SE: HIW search To
REASON FOR REMOVAL: REMOVAL A/C REG: TC-CP into AJW Stock after repair ar	L REASON FO nd release. REF	R REMOVAL: BOTH GPS FAIL REMO PAIR UNDER FP CONTRACT CW265	OVAL D. 55877	ATE 10/10/2023 Th	nis unit will be coming back
	AS RECEIVED	:	AS RE	LEASED:	
PART NUMBER	066-50029-12	201	066-5	0029-1201	en Pragonal tenas has fillas
DESCRIPTION:		SEMBLY MULTI-MODE RECEIVER,	OUTL	INE ASSEMBLY M	ULTI-MODE RECEIVER,
SERIAL NUMBER	RMA55B-056	03	RMA5	5B-05603	
UID(MFR/SPL PNO SER/UCN)					
HW MOD STATUS:	1-8	bos best	1-8	Service tests Production States	or metoFillis absalta words
SW MOD STATUS:	01/02		01/02	under traper and in	A sterimown, the sees 1901 is thavide acim bertari
SOFTWARE LOAD:	NA	naileri Pamovaet Pemove	NA	beilateni j	5 5 5 1 Meinsetzia
REASON FOR REMOVAL CONF	I IRMED: Rejecti	on Confirmed	ESTIM	ATE SUPPLIED: No	
PRIMARY SHOP FINDING: Soft	ware Fault Fou	nd	WARR	ANTY: Warranty Ac	ccepted
TYPE OF SERVICE: REPAIRED)		TECHN	NICIAN: Curtis Walk	er
MAINTENANCE STATEMENT: PAGE DETAILING WORK PER	RFORMED, ALOI	NG WITH MATERIALS USED, IS ATTACH	ED IN PA	GE 2.	
SIGNATURE BELOW REQUIRE	ONLY WHEN F	RETURN TO SERVICE IS NOT ISSUED:	DATE:		
SIGNATURE OF AUTHORIZED F	PERSON:				
Complied With CMM/Eng Documentation: 34- Service Bulletins: Customer Manuals/Document		ev Date 07 MAY 2020;			
SHOULD YOU REQUIRE ANY FURTH RESPONSE CENTER AT 1-800-601-3	IER INFORMATION 099 OR VISIT OUR	REGARDING THIS SERVICE REPORT, OR HACUSTOMER PORTAL AT www.MyAerospace.co	AVE ANY (QUESTIONS, PLEASE C	CONTACT OUR CUSTOMER

3. Form Tracking Number: 20230014078320Y15 348649321
5. Work Order/Contract/Invoice Number: R418832 348456901 Page 1 of 1
11. Status / Work:
REPAIRED
SEE ATTACHED DOCUMENTS AS APPLICABLE FOR WORK PERFORMED CERTIFIES THAT THE WORK SPECIFIED IN BLOCK 11/12 WAS CARRIED OUT IN ACCORDANCE WITH EASA PART 145 AND IN RESPECT TO THAT WORK THE COMPONENT IS CONSIDERED READY FOR RELEASE TO SERVICE UNDER EASA PART 145 APPROVAL NO. EASA 145.4140 13a. Cedifies the items identified above were manufactured in conformity to: Approved design data and are in a condition for safe operation. Non-approved design data specified in Block 12. Non-approved design data specified in Block 12. Regulations, part 45 and in respect to that work, the items are approved for return to service.
A PART 145 AND IN RESPECT TO THAT WORK THE COMPONENT IS CONSIDERED READY FOR RELEAS 14a. 14 CFR 43.9 Return to Service Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service. 14b. Authorized Signature:
CONSIDERED READY FOR RELEAS pecified in Block 12 ntified in Block 11 and le 14, Code of Federal proved for return to service. 14c. Approval/Certificate No.: PR2R093L
3. Form Track 2023001407 348649321 5. Work Order R418832 348456901 Page 1 of 1

AJW AVIATION LTD

Honeywell International Inc. 23500 W 105th Street Olathe KS 66061

TO BE APART SERVED HED	348649321	FAA:	EASA:
PO:	CUSTOMER PART NUMBER:	PR2R093L	EASA.145.4140
R418832	TOO TOWNER PART NOWIBER:	CONTRACT NUMBER:	
DATE REJECTED:	DATE RECEIVED:	440098719	
18 OCT 2023	25 OCT 2023	DATE COMPLETED:	
A/C TYPE:	A/C TAIL NUMBER: TC-CPL	21 DEC 2023	
BOEING B737-800	TC-CPL	A/C SERIAL NUMBER:	
PACKING STATUS:	SEALS INTACT:	40010	
No	Intact	PHYSICAL DAMAGE:	HOUSE AND THE STATE OF THE STAT
REASON FOR REMOVAL: REMOVAL A/C REG: TC-CPL REASON FO ato AJW Stock after repair and release. RE	OR REMOVAL: BOTH GPS FAIL REM PAIR UNDER FP CONTRACT CW26	MOVAL DATE 10/10/2023 This ur 655877	nit will be coming L

PART NUMBER	AS RECEIVED:	AS RELEASED:
DESCRIPTION:	066-50029-1201	066 F0000 1001
SERIAL NUMBER	OUTLINE ASSEMBLY MULTI-MODE RECEIVER, RMA55B-05603	OUTLINE ASSEMBLY MULTI-MODE RECEIVER
UID(MFR/SPL PNO SER/UCN)	T 11/1/100E-00003	RMA55B-05603
HW MOD STATUS:	1-8	1-8
SW MOD STATUS:	01/02	01/02
SOFTWARE LOAD:	NA	NA
REASON FOR REMOVAL CONF		
REASON FOR REMOVAL CONF		ESTIMATE SUPPLIED: No
PRIMARY SHOP FINDING: Soft	ware Fault Found	
		WARRANTY: Warranty Accepted
TYPE OF SERVICE: REPAIRED		TECHNICIAN: Curtis Walker
MAINTENANCE STATEMENT: PAGE DETAILING WORK PER	RFORMED, ALONG WITH MATERIALS LISED, IS ATTACHED	

PAGE DETAILING WORK PERFORMED, ALONG WITH MATERIALS USED, IS ATTACHED IN PAGE 2.

SIGNATURE BELOW REQUIRED ONLY WHEN RETURN TO SERVICE IS NOT ISSUED: DATE:

SIGNATURE OF AUTHORIZED PERSON:

Complied With

CMM/Eng Documentation: 34-55-51/Rev 6/Rev Date 07 MAY 2020;

Service Bulletins:

Customer Manuals/Documentation:

SHOULD YOU REQUIRE ANY FURTHER INFORMATION REGARDING THIS SERVICE REPORT, OR HAVE ANY QUESTIONS, PLEASE CONTACT OUR CUSTOMER RESPONSE CENTER AT 1-800-601-3099 OR VISIT OUR CUSTOMER PORTAL AT www.MyAerospace.com TO SUBMIT AN INQUIRY.

AJW AVIATION LTD

Aerospace-Olathe Honeywell International Inc. 23500 W 105th Street Olathe KS 66061

	EASA.145.4140
PO: R418832 CUSTOMER PART NUMBER: CONTRAC 44009871	T NUMBER:

Previously Complied With

CMM/Eng Documentation:

Service Bulletins:

Customer Manuals/Documentation:

Evaluation Findings

D7 fault triggered during testing indicating LRU Software errors. LRU requires software reload.

Work performed / Comments to Customer

Flashed LRU SWM 01/02 and loop tested.

D7 fault no longer triggered during testing.

LRU now passes all Return to Service tests. Product repaired and

tested per shop standard to ensure proper functionality,

reliability, and airworthiness. All equipment calibration dates

confirmed to be current at the time of repair and testing.

LRU now passes all Return to Service tests. Product repaired and

tested per shop standard to ensure proper functionality,

reliability, and airworthiness. All equipment calibration dates

confirmed to be current at the time of repair and testing.

DISPOSITION	REF DSG	P/N Installed	S/N Installed	P/N Removed	S/N Removed	Qty	Primary Failure	SB
ÿ								

Honeywel

Aerospace-Olathe Honeywell International Inc. 23500 W 105th Street Olathe KS 66061

SERVICE REPORT

AJW AVIATION LTD

SR NUMBER: 5018029660		FAA: PR2R093L	EASA: EASA.145.4140
PO:	CUSTOMER PART NUMBER:	CONTRACT NUM 440098719	IBER:
R418832	105	MED IN STANS	

Previously Complied With

CMM/Eng Documentation:

Service Bulletins:

Customer Manuals/Documentation:

D7 fault triggered during testing indicating LRU Software errors. LRU requires software reload.

Work performed / Comments to Customer

Flashed LRU SWM 01/02 and loop tested.

D7 fault no longer triggered during testing.

LRU now passes all Return to Service tests. Product repaired and

tested per shop standard to ensure proper functionality,

reliability, and airworthiness. All equipment calibration dates

confirmed to be current at the time of repair and testing.

LRU now passes all Return to Service tests. Product repaired and

tested per shop standard to ensure proper functionality,

reliability, and airworthiness. All equipment calibration dates

ofirmed to be curre	REF DSG	P/N Installed	S/N Installed	P/N Removed	S/N Removed	Qty	Primary Failure	SE
							44	

AJW AVIATION LTD

SR NUMBER: 5018029660

Honeywell International Inc. 23500 W 105th Street Olathe KS 66061

PO:		348649321		FAA: PR2R093L	EASA: EASA.145.4140
R418832	TRACT HUMBER ORFT IS	CUSTOMER PART NUMBER:	TOMES P	CONTRACT NUMBER	the state of the s
DATE REJECTED: 18 OCT 2023	200	DATE RECEIVED: 25 OCT 2023		DATE COMPLETED: 21 DEC 2023	
A/C TYPE: BOEING B737-800		A/C TAIL NUMBER: TC-CPL		A/C SERIAL NUMBER:	
PACKING STATUS: No		SEALS INTACT:		40010 PHYSICAL DAMAGE:	WHITE CO.
REASON FOR REMOVAL: REMOVAL A/C REG: TC-CI into AJW Stock after repair a	PL REASON FO and release. REF	R REMOVAL: BOTH GPS FAIL REM PAIR UNDER FP CONTRACT CW26	IOVAL D 55877	ATE 10/10/2023 This u	nit will be coming bac
DADT NUMBER	AS RECEIVED:		AS RE	LEASED:	
PART NUMBER	066-50029-12			0029-1201	KIND NV BELIE JESE
DESCRIPTION:	OUTLINE ASS	SEMBLY MULTI-MODE RECEIVER,		INE ASSEMBLY MULTI	MODE DECEMEN
SERIAL NUMBER	RMA55B-0560	03	RMA5	5B-05603	-MODE RECEIVER,
UID(MFR/SPL PNO SER/UCN)			1111111111111	OD-00000	n distriction of the second
HW MOD STATUS:	1-8	bus pair	1-8	Thus at Eg.	urafi in dasaka wana
SW MOD STATUS:	01/02		01/02	oniscultura i de la companio del companio del companio de la companio del companio de la companio de la companio del companio de la companio de la companio de la companio de la companio del compani	solideavois hor sidha a travisci ad at kome
SOFTWARE LOAD:	NA	years percent notice	NA	reliation trans	J don sonate
REASON FOR REMOVAL CONF			ESTIMA	ATE SUPPLIED: No	
PRIMARY SHOP FINDING: Soft			WARRA	NTY: Warranty Accepte	ed
TYPE OF SERVICE: REPAIRED)		TECHN	CIAN: Curtis Walker	
IAINTENANCE STATEMENT: PAGE DETAILING WORK PER	RFORMED, ALONG	WITH MATERIALS USED, IS ATTACHE	D IN PAG	9F 2	
				4L E.	
IGNATURE BELOW REQUIRED IGNATURE OF AUTHORIZED P		TURN TO SERVICE IS NOT ISSUED:	DATE:_		
omplied With MM/Eng Documentation: 34-5 ervice Bulletins: ustomer Manuals/Documenta	55-51/Rev 6/Rev	Date 07 MAY 2020;			

348649321

SHOULD YOU REQUIRE ANY FURTHER INFORMATION REGARDING THIS SERVICE REPORT, OR HAVE ANY QUESTIONS, PLEASE CONTACT OUR CUSTOMER

RESPONSE CENTER AT 1-800-601-3099 OR VISIT OUR CUSTOMER PORTAL AT www.MyAerospace.com TO SUBMIT AN INQUIRY.

AJW AVIATION LTD

Honeywell International Inc. 23500 W 105th Street Olathe KS 66061

SR NUMBER: 5018029	3000	FAA:	EASA:
PO: R418832	CUSTOMER PART NUMBER:	PR2R093L	EASA.145.4140
11410032	or they are	CONTRACT NUN 440098719	BER:

Previously Complied With

CMM/Eng Documentation:

Service Bulletins:

Customer Manuals/Documentation:

Evaluation Findings

DISPOSITION

D7 fault triggered during testing indicating LRU Software errors. LRU requires software reload.

Work performed / Comments to Customer

Flashed LRU SWM 01/02 and loop tested.

D7 fault no longer triggered during testing.

LRU now passes all Return to Service tests. Product repaired and

tested per shop standard to ensure proper functionality,

reliability, and airworthiness. All equipment calibration dates

confirmed to be current at the time of repair and testing.

LRU now passes all Return to Service tests. Product repaired and

P/N

tested per shop standard to ensure proper functionality, reliability, and airworthiness. All equipment calibration dates

REF DSG

confirmed to be current at the time of repair and testing.

	Installed	Installed	Removed	S/N Removed	Qty	Primary Failure	SB
7							

P/N

S/N