

1. Approving National Aviation
Authority/Country
FAA/United States

2.


AUTHORIZED RELEASE CERTIFICATE

FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:

102702

4. ORGANIZATION:
Name and Address



Med-Craft, Inc.

2450 N.W. 110th Avenue
Miami, Florida 33172
Tel.: (305) 594-7444
Fax: (305) 594-9080
F.A.A. Repair Station N° LZ4R354M

5. Work Order / Contract /
Invoice Number:

TM-162544

6. Item:	7. Description:	8. Part Number:	9. Eligibility: *	10. Qty.:	11. Serial/Batch Number:	12. Status/Work:
1.	Actuator	65-17819-8	N/A	1	DA1369	OVERHAULED

13. Remarks:

Work Order 102702 prescribing the actual work performed is attached. Certifies that the work specified in block 12/13 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number: EASA.145.4663.
The work stated in Block 12 was accomplished IAW CMM 32-30-31 Rev Date: 11/01/10 Rev No.: 21

14. * Certifies the items mentioned above were manufactured in conformity to:
* * * * * Approved design data and are in a condition for safe operation * * * * *
* * * * * Approved design data as specified in Block 1 * * * * *

19. x 14 CFR 43.9 Return to Service x Other regulations specified in Block 13
Certified that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

15. Authorized Signature:
* * * * *

16. Approval/Authorization No.:
* * * * *

20. Authorized Signature:

Oscar UZ
OSCAR UZ

21. Approval/Certificate Number:

LZ4R354M

17. Name (Typed or Printed):
* * * * *

22. Name (Typed or Printed):

OSCAR UZ

23. Date (mm/dd/yy):

OCT 12 2011

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly.

Where the user/installer work in accordance with national regulations of an airworthiness authority different than the airworthiness authority of the country specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in block 1.

Statements in Block 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

WORK ORDER

Work Order :102702
Part Number :65-17819-8
Serial Number :DA1369
ATA Number :32-30-31
Service Req. :Repair

Repair Order :TM-162544
Description :Actuator
Manufacturer :Boeing
Revision Date :11/01/10
Date :09/26/11

FAA REPAIR STATION LZ4R354M

CONDITION REPORTED - NOT CONFIRMED

Hits hard to low and up the nose gear.

CONDITION AS RECEIVED

VISUAL INSPECTION APPEARS NORMAL

HIDDEN DAMAGE INSPECTION

NONE FOUND

REMARKS

Please quote and hold.


Receiving Clerk: Jesus Antonio Valencia

DATE: 09/26/2011

AD NOTES, Customer Specs

THERE ARE NO A.D. NOTES FOR THIS UNIT

Signature: _____



DATE: _____

09/26/2011

FORM MC-10 1 OF 4 REV 940617

WORK ORDER

Work Order :102702
Part Number :65-17819-8
Serial Number :DA1369
ATA Number :32-30-31
Service Req. :Repair

Repair Order :TM-162544
Description :Actuator
Manufacturer :Boeing
Revision Date :11/01/10
Date :09/26/11

FAA REPAIR STATION LZ4R354M

TEARDOWN REPORT

*Pretest

Upon pretest found:

1. High internal leakage.
2. Unable to confirm condition reported.


*Disassembly

Upon disassembly and inspection, the following discrepancies were found:

1. All packings and seals are set and compressed.
2. Bearings 4 and 20 are worn (excessive end play).
3. NDT is required.
4. Rod End requires cad plating.
5. ID plate is damaged (faded).
6. Unit requires overhaul due to worn and damaged parts.

TECHNICIAN: Luis M Rodriguez

SUPERVISOR: 



WORK ORDER

Work Order :102702
Part Number :65-17819-8
Serial Number :DA1369
ATA Number :32-30-31
Service Req. :Repair

Repair Order :TM-162544
Description :Actuator
Manufacturer :Boeing
Revision Date :11/01/10
Date :09/26/11

FAA REPAIR STATION LZ4R354M

CORRECTIVE ACTION

1. All worn and damaged parts were replaced.
2. Unit was assembled in accordance with the manufacturer's specifications.
3. Unit passed all functional tests.

Unit overhauled and certified for return to service.

Tech : Luis M Rodriguez Spvsr : Date : 10/12/11

SERVICE PERFORMED

Overhauled

MAINTENANCE RELEASE

Issued with respect to job performed as checked above.
The component identified above was inspected in accordance with current regulations of the F.A.A. and is approved for return to service. Pertinent details of the repair are on file at this agency under

W.O.# 102702 Date OCT 12 2011 Signed

WORK ORDER

Work Order :102702
Part Number :65-17819-8
Serial Number :DA1369
ATA Number :32-30-31
Service Req. :Repair

Repair Order :TM-162544
Description :Actuator
Manufacturer :Boeing
Revision Date :11/01/10
Date :09/26/11

FAA REPAIR STATION LZ4R354M

PARTS REPLACED

1	65-17819-3	Strap	LOT196059/3
1	66-12156-19	Lockwshr	LOT196059/1
1	7211MT-952-T	Seal Assy	LOT196058/4
1	BAC27DHY127	Name Plate	LOT196059/2
1	BACS11AA113A	Seal	LOT140769/3
1	BACS34A2A	Scraper	LOT124304/6/1
2	MS14101-8	Bearing	LOT196060/1
2	MS28782-19	Back-Up Ring	LOT193838/4/1
1	NAS1611-113	Packing	LOT194966/11/1
1	NAS1611-211	Packing	LOT190766/25/1
1	NAS1611-214	O Ring	LOT193396/26
2	NAS1612-4	O-Ring	LOT195694/4
2	SP	Shipping Plug	LOT5055

STOCKROOM : Miguel Rigüero

PAGE : 1