

61388448



1. Approving Competent Authority / Country

2.

3. Form Tracking Number

LBA / Germany

AUTHORISED RELEASE CERTIFICATE
EASA FORM 1

19540002 00000001

4. Organisation Name and Address:



Lufthansa Technik

Lufthansa Technik AG
Weg beim Jäger 193
22335 Hamburg
Germany

5. Work Order/Contract/Invoice

61388448

6. Item

7. Description

8. Part No.

9. Qty.

10. Serial No.

11. Status / Work

01 PASSENGER SERVICE UNIT

Z313H02AA020

1

313H02375999

REPAIRED

12. Remarks

A.J. Walter (Aviation) Ltd. R326980

ATA 2373

TP R

MK-No. 20

Pack Code 00

Resp. Workshop 32322012

Workshop Station FRA025

Opr. Hours Cycle Opr. Day
TT UNKNOWN UNKNOWN UNKNOWN
TSO UNKNOWN UNKNOWN UNKNOWN
TSC UNKNOWN UNKNOWN UNKNOWN
TSF 0 0 0
TASK PERFORMED IN ACCORDANCE WITH CMM 25-27-00
REV 7 / CMDS 25-27-00 ISSUE 008

13a. Certifies that the items identified above were manufactured in conformity to:

☐ approved design data and are in a condition for safe operation☐ non-approved design data specified in block 1214a. ☒ Part-145, A.50 Release to Service

Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.

☒ Further details of work performed are attached either in a Workshop Report (reference number: see blocks 3 and 5) or in other applicable documents.

FAA Certificate No. DLA225D

TCCA Approval No. 897-08

13b. Authorised Signature

13c. Approval / Authorisation Number

14b. Authorised Signature

446448

13d. Name

13e. Date (dd mmm yyyy)

14d. Name

Florian Langer

14c. Certificate / Approval Ref. Number

DE.145.0001

14e. Date (dd mmm yyyy)

09 Oct 2017

EASA FORM 1 - Issue 2
USER/INSTALLER RESPONSIBILITIES

Note: This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an airworthiness authority different from the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Workshop Report

61390636



Customer Order No.



Lufthansa Technik

Lufthansa Technik AG
Weg beim Jäger 193
22335 Hamburg
Germany

Certificate Ref. No.

19548977 00000001

Work Order/Contract/Invoice

61390636

Part. No. as received

Z310H2310111

Serial No. as received

310H23008261

Description

PISA PASSENGER SERVICE UNIT

Part No. as dispatched

Z310H2310111

Serial No. as dispatched

310H23008261

Responsible Workshop

32322012

Reason for removal

REMOVED FROM NEXT HIGHER ASSY PSU,
PN:Z312H02AA020
SN:313H02375999

Modification Status according to Mod-Label

Findings

NO FUNCTION DUE TO DEFECTIVE C110 AND C111.
FOUND BAD SOLDERING JOINTS ON PCB.

See Unit Mod-Label if equipped

Action

REPLACED CAPACITORS C110 AND C111.
RESOLDERED BAD SOLDERING JOINTS.
UNIT PASSED ALL TESTS IN ACCORDANCE TO CMM SEVERAL
TESTS PERFORMED IN WARM AND COLD CONDITION

Name

446448, Florian Langer

Date (dd mmm yyyy)


09 Oct 2017

The work specified above has been performed subject to Lufthansa Technik's Standard conditions for Technical Services which, if not superseded by another agreement or not yet agreed upon before, are acknowledged by the customer with acceptance of the part(s) hereunder.

Workshop Report

61388448



| | | | | |
|---|--|--|--|---|
| Customer Order No. R326980 | |  Lufthansa Technik Lufthansa Technik AG Weg beim Jäger 193 22335 Hamburg Germany | | Certificate Ref. No. 19540002 00000001 |
| Part. No. as received Z313H02AA020 | | Serial No. as received 313H02375999 | | Work Order/Contract/Invoice 61388448 |
| Part No. as dispatched Z313H02AA020 | | Serial No. as dispatched 313H02375999 | | Description PASSENGER SERVICE UNIT |
| Reason for removal READING LIGHT 35A U/S | | | | Responsible Workshop 32322012 |
| Findings READING LIGHT DEFECTIVE. PISA REQUIRES REPAIR. C110 AND C111 ON PISA PCB DEFECTIVE. FURTHER WE FOUND SOME COLD SOLDERING JOINTS ON PCB. | | | | Modification Status according to Mod-Label |
| Action PISA PCB REMOVED AND INSTALLED / REPAIRED. FOR DETAILED INFORMATION ABOUT FINDINGS AND ACTIONS OF INSTALLED PISA SEE ATTACHED WORKSHOP REPORT. REPLACED READING LIGHT. UNIT PASSED ALL TEST ACCORDING CMM IN COLD AND WARM CONDITION. | | | | See Unit Mod-Label if equipped |
| The work specified above has been performed subject to Lufthansa Technik's Standard conditions for Technical Services which, if not superseded by another agreement or not yet agreed upon before, are acknowledged by the customer with acceptance of the part(s) hereunder. | | | | Name 446448, Florian Langer Date (dd mmm yyyy) 09 Oct 2017 |