

1. Approving Competent Authority/Country
**Civil Aviation Authority
United Kingdom**

2. **AUTHORISED RELEASE CERTIFICATE
EASA FORM 1**

3. Form Tracking Number
26690

4. Approved Organisation Name and Address

REHEAT INTERNATIONAL LTD
Riverside, Omega Park, Alton, Hampshire GU34 2UF
Tel +44 (0)1420 594000 Fax: +44 (0)1420 594001

5. Work Order/Contract/Invoice

027270/00

6. Item

7. Description

8. Part Number

9. Qty

10. Serial/Batch No.

11. Status/Work

01

OCM

HE64102

1

EA

130020

Repaired

12. Remarks

The Unit has been disassembled, cleaned, inspected, repaired as necessary and reassembled, it has been tested in accordance with approved standards and technical data

REPAIRED IAW CMM 25-30-134 REV NIL DATED 04/MAR/83
FOR AJ WALTER REPAIR ORDER: 164222

Transport Canada

CAR 571 Maintenance Release

Certifies that unless otherwise specified in block 12, the work identified in block 11 was performed in accordance with CAR 571

14 CFR 43.9 Return to Service

Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12 was accomplished in accordance with Title 14, Code of Federal Regulations Part 43 and in respect to that work, the items are approved for return to service

Authorised Signature

Certificate/Approval.
Ref No.

Authorised Signature

Certificate/Approval.
Ref No.

Name

Date (d/m/y)

Name

Date (d/m/y)

P. VINCE RHI 11

03 NOV 2011

P. VINCE RHI 11

03 NOV 2011

14a. ☒ Part-145A.50 Release to Service ☒ Other Regulation specified in block 12

Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12 was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service

14b. Authorised Signature

14c. Certificate/Approval Ref No.

P. VINCE

UK.145.00472

13b. Authorised Signature

13c. Approval /Authorisation Number

13d. Name

13e. Date(d/m/y)

P. VINCE

RHI 11

14e. Date (d/m/y)

03 NOV 2011

Note: USER/INSTALLER RESPONSIBILITIES

1. This certificate does not automatically constitute authority to install the item(s)
2. Where the user/installer performs works in accordance with regulations of an airworthiness authority different from the airworthiness authority specified in Block 1 it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1
3. Statements in 13a and 14a do not constitute installation certification. In all cases aircraft maintenance record must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown

Reheat INSPECTION RECORD CARD

WORKSHOP WORKSHEET

MAINTENANCE RELEASE EASA: UK.145.00472

CERTIFIES THAT THE WORK SPECIFIED EXCEPT AS OTHERWISE SPECIFIED WAS CARRIED OUT IN ACCORDANCE WITH EASA PART 145 AND WITH RESPECT TO THAT WORK THE AIRCRAFT COMPONENT IS CONSIDERED READY FOR RELEASE TO SERVICE

AUTHORISED SIGNATURE

REHEAT INTERNATIONAL APPROVAL STAMP

NAME:

DATE:

RHI 07

28 OCT 2011

MAINTENANCE RELEASE FAA: RHUY491X

THE AIRCRAFT/ENGINE/PROPELLER OR APPLIANCE IDENTIFIED HEREWITH WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION AND IS APPROVED FOR RETURN TO SERVICE WITH RESPECT TO THE WORK CARRIED OUT. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER RHI ORDER NUMBER

AUTHORISED SIGNATURE

REHEAT INTERNATIONAL APPROVAL STAMP

NO:

RHI 07

DATE:

28 OCT 2011

TRANSPORT CANADA MAINTENANCE RELEASE TCCA: 807-12

CERTIFIES THAT THE WORK SPECIFIED UNLESS OTHERWISE SPECIFIED WAS CARRIED OUT IN ACCORDANCE WITH CAR 571 AND WITH RESPECT TO THAT WORK THE AIRCRAFT COMPONENT IS CONSIDERED READY FOR RELEASE TO SERVICE

AUTHORISED SIGNATURE:

REHEAT INTERNATIONAL APPROVAL STAMP

NO:

RHI 07

NAME:

DATE:

28 OCT 2011

CARD 1 OF 4

CUSTOMER NAME/ OWNERSHIP
AJ WALTER
AVIATION

MOD STATUS

ML M205

SPECIAL INSTRUCTIONS

None

FAA REF NOT APPLICABLE

REASON FOR REMOVAL

OVER TURN DOGS
NOT OPERATE AND
NOT NO MARKS ON SIDE
CONFIRMED

RELEASE REQUIRED
SCRAP UNCONFIRMED

EASA

FAA

TCCA

NOTES:

ADDITIONAL DATA

MANUFACTURER'S PART NO

HE64102

SERIAL NUMBER

130020

DESCRIPTION

O.C.M.

A/C REGISTRATION

G-STRY

RHI ORDER NUMBER

027270/00

CUSTOMER ORDER NO

164222

DATE ITEM RECEIVED

19-Oct-11

C.M.M. REF. NO.

25-30-134

C.M.M. DATED:

REV. N/L 4th March 1993

EFF. CODE:

N/L

ADDITIONAL C.M.M.:

C.M.M. REF. NO.

C.M.M.

DATED:

EFF. CODE:

STRIP REPORT REQD YES/NO

DATE OF LAST SHOP VISIT:

None

COPY OF LAST JOB CARD

YES / NO

LEVEL OF MAINTENANCE REQUIRED

REPAIR

EASA FORM 1 BLOCK 11 STATEMENT

AS PAID




Inspection Record Card Workshop Continuation Worksheet

Card 2 of 4	RHI ORDER NUMBER: 027270100	CUSTOMER ORDER NUMBER: 164222
WORK TO BE DONE		WORK CARRIED OUT
1 CONFIRM PART NUMBER AND SERIAL NUMBER ON DATA PLATE	PART NUMBER: HE 64102 SERIAL NUMBER: 130020	Mech Scott Insp RHI 07 Date 28/10/2011
2 CARRY OUT VISUAL INSPECTION	Visual inspection carried out	Mech Scott Insp RHI 07 Date 28/10/2011
3 CARRY OUT PRE-TEST, RECORD DATA IN ACCORDANCE WITH THE COMPONENT MAINTENANCE MANUAL (RE-TEST IF REWORK HAS BEEN CARRIED OUT)	Pre-test inconclusive due to faulty wiring review	Mech Scott Insp RHI 07 Date 28/10/2011
4 IF A FULL PRE-TEST IS NOT POSSIBLE CARRY OUT STATIC TESTS IF APPROPRIATE TO IDENTIFY DEFECTS	As static tests carried out	Mech Scott Insp RHI 07 Date 28/10/2011
5 CHECK APPLICABLE AD'S AND SB'S FOR COMPLIANCE UPON COMPLETION OF WORK	APPLICABLE AIR WORTHINESS DIRECTIVES AND SERVICE BULLETINS CHECKED FOR COMPLIANCE	Mech Scott Insp RHI 07 Date 28/10/2011
6 REMOVE ALL INSPECTION COVERS AND CARRY OUT VISUAL INSPECTION	Inspection covers removed and visual inspection carried out	Mech Scott Insp RHI 07 Date 28/10/2011



Inspection Record Card Workshop Continuation Worksheet

Card 3 of 4	RHI ORDER NUMBER: 027270/00	CUSTOMER ORDER NUMBER: 164222
WORK TO BE DONE		WORK CARRIED OUT
7. REPAIR TEMPERATURE SELECTION SWITCH - DEFECTIVE ON HIGH SIDE	TEMPERATURE SELECTION SWITCH. REPAIRS	Mech SCOTT Insp RHI 07 Date 28/10/2011
8. REPAIR DEFECTIVE TIMER TIMED STICKS.	TIMER REPAIRS	Mech SCOTT Insp RHI 07 Date 28/10/2011
9. REPAIR TIMER DIAP CUSTOMERS FAULT CONFIRMED IMBALANCE ON DIAP MISSING.	DIAP REPAIRS	Mech SCOTT Insp RHI 07 Date 28/10/2011
10. REPAIR OVERHEAT BULBS MISSING.	OVERHEAT BULBS - MISSING.	Mech SCOTT Insp RHI 07 Date 28/10/2011
11. CARRY OUT MINOR CLEAN TO UNIT INTENSION AND EXTENSION	MINOR CLEAN CARRIED OUT	Mech SCOTT Insp RHI 07 Date 28/10/2011
12. CARRY OUT FUNCTIONS TEST ON COMPLETION OF ALL WORK.	FUNCTIONS TEST COMPLETION	Mech SCOTT Insp RHI 07 Date 28/10/2011



Inspection Record Card Workshop Continuation Worksheet

Card 4 of 4

RHI ORDER NUMBER:

027270/00

CUSTOMER ORDER NUMBER:

164222

WORK TO BE DONE

WORK CARRIED OUT

13 REPAIR INSPECTION COVERS
AND CARRY OUT OPERATIONAL
CHECK

INSPECTION COVERS REPAIRED
AND OPERATIONAL CHECK
CARRIED OUT

14 TESTED IN SERVICEABLE OVER
SERIAL NUMBER 114032

NOTED

WORK CARRIED OUT		
13	REFIT INSPECTION COVERS AND CARRY OUT OPERATIONAL CHECK	Mech Scott Insp RHI 07 Date 28/10/2011 Mech Scott Insp RHI 07 Date 28/10/2011 Mech Insp Date
14	TESTED IN SERVICEABLE OVER SEVERAL OPERATIONS 114032	Mech Insp Date Mech Insp Date Mech Insp Date Mech Insp Date