AJW. TECHNIQUE

100-7055 Alexander-Fleming, Saint-Laurent, QC, H4S 2B7, Canada www.ajw-group.com

Tear Down/Inspection Report

Work Order: WO119706 Date Printed: 3/4/2022 Customer RO: R392004-1

Page: 2

REASON LEGEND

(AD) AD: Part replaced due to Air worthiness Directive that needs to be incorporated. This code will include the last digits of the "AD".

(BR)* BROKEN: Part found Broken, cracked, crushed, ruptured, split, frayed, deformed. "NOT Customer Induced".

(BU)* BURNT/MELTED: Part found burnt, overheated, scorched, seared, blistered, short circuited etc...

(CID) CUSTOMER INDUCED DAMAGED: Part which is found damaged due to lack of maintenance, incident, mishandling, FOD etc....

(CO)* CORRODED: Part found corroded, pitted, rusted, decayed, oxidized, powdery and is beyond repair.

(CMM) 100% CMM: Part which is a mandatory replacement as per CMM.

(CT)* CONTAMINATED: Part found contaminated by foreign object, debris, water, oil etc..." NOT Customer Induced".

DE)* DEFECTIVE: Part defective, intermittent or loose

(DL)* DELAMINATED: Part found delaminated.

(LE)* LEAKING: Part Leaking, seeping, porous beyond acceptable level as per CMM

(MI) MISSING: Part missing to complete a unit as per CMM. "Customer responsibility"

(MOD) MODIFICATION: Part requires modification as per CMM or other technical documentation. Part may be modified or replaced with a modified part.

(NR)* NOT REUSABLE: Part that cannot be reused EX: O-ring, rings, gaskets, packing's, retainers, stripped screws, lock nuts, seals, lock washer.

(OOS) OUT OF SCOPE: Unit discrepancy not directly caused by customer and is above and beyond normal wear and tear or excluded from applicable commercial contracts.

(OOT)* OUT OF TOLERANCE: Part did not meet the tolerance or calibration as per CMM.

(RP)* RUPTURED: Part Punctured, ripped, torn, cut, deteriorated. (For Diaphragm, bellows...)

(RW)* REWORKED: Part reworked, refurbished, balanced, machined as per CMM.

(SB) SB: Part replaced due to Service Bulletin that needs to be incorporated. This code will include the last digits of the "SB"

(SE)* SEIZED: Part seized.

(SIL) SIL: Part replaced due to Service Information Letter that needs to be incorporated. This code will include the last digits of the SIL.

(TX) TIME CONTROLED: Part reached the end of its life, it is time expired and may either be overhauled if applicable or replaced due to times or cycles.

(WO)* WORN: Part scratched, grinded, rubbed, grooved, scrapped, gouged, chipped, abrasion etc....

(WT) WARRANTY: Part replaced under warranty

(CS) CUSTOMER SUPPLIED PARTS: Part supplied by customer

(NDT) NON DESTRUCTIVE TEST

(IP) INCORRECT PART; (SS) SUPERSEDED;

(AR) AS REQUIRED;

NORMAL WEAR AND TEAR

100-7055 Alexander-Fleming, Saint-Laurent, QC, H4S 2B7, Canada www.ajw-group.com

Tear Down/Inspection Report

Work Order: WO119706 Date Printed: 3/4/2022 Customer RO: R392004-1

Page: 1

To:

A J Walter Aviation Ltd. THE HEADQUARTERS MAYDWELL AVENUE SLINFOLD, WEST SUSSEX RH13 0AS UNITED KINGDOM

Code: AJW01

Fax:

Descr: HF RECEIVER-TRANSMITTER

Phone:

P/N: 822-0330-020

CSN: N/A

Qty: 1

CSR: N/A

Email:

TSO: N/A

S/N: 112269 TSR: N/A

Mfg: ROCKWELL COLLINS

CSO: N/A

P/N Out: 822-0330-020

TSN: N/A

Serial Out: 112269

Symptoms:

CODE:

REPAIR

DETAILS:

UNIT DAMAGED.

Faults:

CODE:

CUSTOMER INDUCED DAMAGE

DETAILS:

Description of damage found: deformed dust cover.

Possible cause of damage: mishandling.

See attached pictures.

CODE:

DISASSEMBLY / INSPECTION FINDINGS

DETAILS:

During disassembly and inspection of the unit the following anomalies were found:

- deformed dust cover due to mishandling unit will be dismantled and inspected

damaged dust cover will be replaced.

CODE:

REPAIR

DETAILS:

The following tasks will be performed:

- inspection

replace dust cover.

- test per CMM.

Corrective Actions:

CODE:

REPAIRED

DETAILS:

Unit inspected, replaced dust cover, and tested.

Repaired and tested serviceable per CMM 23-10-90 Rev 09 dated 17 Feb 2021.

PN 653-2618-001

Description COVER DUST RT Reason CID

Qty Needed 1

Disposition Consumable

100-7055 Alexander-Fleming, Saint-Laurent, QC, H4S 2B7, Canada www.ajw-group.com

WO Packing Slip

WO #: WO119706

Date: 3/4/2022

Time: 6:10:46 AM

Cust Ref #: R392004-1

SM #: SH135640



To:

A J Walter Aviation Ltd. THE HEADQUARTERS MAYDWELL AVENUE SLINFOLD, WEST SUSSEX RH13 0AS UNITED KINGDOM

Ship To:

A J Walter Aviation Ltd. THE HEADQUARTERS MAYDWELL AVENUE SLINFOLD WEST SUSSEX RH13 0AS UNITED KINGDOM

Order Date: 2/16/2022 Prepared By: SYSDBA

Ship Via:

Ship Via Acc:

Customer #: AJW01

Buyer:

Part Number/Description	Qty	
22-0330-020 HF RECEIVER-TRANSMITTER Loc/Whse:	1	
Serial #: 112269		
	James and the second	

qwfwefwfqwf





\$\$\$R392004^WO119706^^Airworthy^822-0330-020^REP^TCCA+EASA+FAR^



%%112269^WO119706^AJW TECHNIQUE INC^04/03/2022^ORIGINAL CERT^ORIGINAL WORK^PACKING SLIP^