

1. CIVIL AVIATION AUTHORITY UNITED KINGDOM		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. FORM TRACKING NUMBER 80136190 / 1	
4. ORGANISATION Ipeco Holdings Ltd. Ipeco		Registered in England No. 672443 Ipeco A Division of IPECO Holdings Ltd Building 4 Aviation Way Southend-on-Sea SS2 6UN		VAT Registration No. GB 250 3726 82 Telephone: 44 (0) 1702 209329 Fax: 44 (0) 1702 540782 E-Mail: QUALITY@ipeco.co.uk	
5. WORK ORDER / CONTRACT / INVOICE 140630 A.J. Walter (Aviation) Ltd 6008332					
6. ITEM	7. DESCRIPTION	8. PART NO.	9. QTY.	10. SERIAL NO.	11. STATUS / WORK
10300	AIRCRAFT REFRIGERATOR	700-006-000	1.00	32.	REPAIRED
12 REMARKS 1.Repair report Number 6489 Issue 2. 2.Repaired in accordance with C.M.M. 25-36-25 Issue 5. 3.Under Commission Regulation (EC) No: 1702/2003 Article 2, Paragraph 13 Equipment approval No: SA00103 Applies.					
13a. Certifies that the items identified above were manufactured in conformity to ☐ approved design data and are in condition for safe operation ☐ non-approved design data specified in block 12		14a. ☒ Part 145A.50 Release to Service ☐ Other regulation specified block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12 was accomplished in accordance with Part 145 and in respect to that work the items are considered ready for release to service.			
13b. AUTHORISED SIGNATURE:		13c. APPROVAL / AUTHORISATION NUMBER: UK.21G.2071		14b. AUTHORISED SIGNATURE: <i>[Signature]</i>	
13d. NAME:		13e. DATE: (DD/MM/YYYY)		14c. CERTIFICATE / APPROVAL REF. NO.: UK. 145. 00709	
14d. NAME: D STONE		14e. DATE: (DD/MM/YYYY) 14 DEC 2010			
USERS / INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install item(s). Where the user / installer performs work in accordance with regulations of an Airworthiness Authority different from the Airworthiness Authority specified in block 1 it is essential that the user / installer ensures that his / her Airworthiness Authority accepts items from the Airworthiness Authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user / installer before the aircraft may be flown.					

**PRODUCT REPAIR SURVEY REPORT**Form H130-5
Page 1

Date:	24 November 2010	Report No:	6489
Work Order No	7008416	Issue:	2

This report is also used for estimate and quotation purposes

CUSTOMER DETAILS

Name:	A.J. WALTERS	Order No:	140630
Location:	UK	NCR No:	N/A

PRODUCT DETAILS

Received as:	700-006-000	Quantity:	1	Issue:	MD0
Description:	AIRCRAFT REFRIGERATOR			Current Issue:	1
Release as:	700-006-000	Issue:	1		
S.O.No:	6008332	GRN No:	11100432		

PRODUCT - SERVICE / HISTORY DETAILS

Time since New:	7 YRS 6 MTHS	Time Since Repaired:	1 YR 3 MTHS	Flying Hours:	N/A
Cross Ref / Serial No:	32	Ident / Manufacture Date:	15-05-2003	Original Release Note No:	N/A

APPLICABLE DRAWINGS / MANUALS / ACCEPTANCE TEST PROCEDURES

Drawing No:	700-006	Issue No:	1	C.M.M. No:	25-36-25	Issue No:	5	A.T.P No:	N/A	Issue No:	N/A
State all other applicable Design Data or Information. D.O.I.'s, S.B.'s etc.											
NONE											

Have the following Airworthiness Authority Publications been examined for applicability?

CAP 455 Airworthiness Notices	N/A	STAMP / SIGNATURE 
CAP 747 Mandatory Requirements for Airworthiness	N/A	
If any of the above Publications are Applicable, State reference numbers:		
NONE		

REPAIR / NON-CONFORMITY SURVEY

Has the Customer made a Warranty Claim?	NO	If YES, Is the Claim Valid?	N/A
Customer Reported Fault			
NOT COOLING			

ESTIMATED / ACTUAL HOURS

Estimated / Actual Time	Warranty Hours:	0	NON Warranty Hours:	6
Warranty Items are Operation Numbers				
NONE				
Approval Stamp /Signature:		DAVE FISHER		Date: 24/11/2010

Report No: 6489

Initial Inspection:

Issue: 2

NOTE: IF WARRANTY IS CLAIMED . EXPLAIN WHY THE CLAIM IS VALID,PARTIALLY VALID OR INVALID

Sales Action: REPAIR IN ACCORDANCE WITH sr 6489

Warranty Claim:

Item No. Inspection Report

- | | |
|---|---|
| 1 | 'FREEZE' thermostat, SW4, found intermittant after continuous soak testing, this would cause the reported fault of 'not cooling'. |
| 2 | 'ON/OFF' indicator lamp failed. |
| 3 | Refrigerator dirty, scratched and marked. 4 shelves and wire basket returned with refrigerator. |

Report No: 6489

Issue: 2

PART IDENTIFICATION & TRACEABILITY DETAILS

Ops:	Parts Required			Internal use only	Individual Cost	Total Cost:
	Part No:	Qty	Description	Batch No: Ref bom		
1	549-800	1	LAMP FILAMENT		£1.58	£1.58
4	547-114	1	SWITCH THERMOSTAT		£13.86	£13.86
4	559-550	6	TIE WRAP		£0.14	£0.84

	Cost of Parts:	£16.28
Labour : 6.00 Hrs x	£48.15 per Hour:	£288.90
	Total Pnds STG:	£305.18

