It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

| AAC- | 17 ∄ Nam | Sign | ₫ | | Z | Se e | ATA: E.S.N. Repair Custon | | | න ආ | | 本 | 5 | บ ฮ | 叫 |
|----------------|-------------------------------------|------------------------------------|-------------|--|--|----------------------------|--|----------------------------|-----------------|----------|-------------------------------------|--|--|----------------------|----------------|
| AAC-038(12/94) | 17 我准人姓名(t Name (Printed) | Signature | 批准人签名 | | 計畫 | Workso | I3 基註 Remarks ATA: 72-2: E.S.N. 7794 Repair Order: ERO Customer: AJ V | | ∄, | 中 | | Į a | · CIIII | D B CHINA | |
| 2/94) | 17 我准人技名(打印的) Name (Printed) | | ** | Minapa Mi | | See Workscope Report:85593 | | PANEL, ASSY-ACOUSTICAL AFT | | | | | 5 | ΙA | Country |
| | ~~~ | F | _ | | 基基 | ort : 85 | -08 }1 7455 alter Avi | ASSY-A | 0 | | | | | | N |
| | Mussie Dair | 3 | - 7 | | | 593 | arks 72-23-08 779481 ERO17455 AJ Walter Aviation Ltd | COUST | Description | 7 内容 | | | AU | | 中国民 |
| | <u>a</u> . | | 180 | | 屋 | | _ | ICAL AF | ion | | rei: 972. | 3P Aero AA Rep 1965 HA | THOR | | 2 中国民用航空总局 |
| | | / R | 37 | the app owner of | を変 | | | T | | | Tel: 972-252-2800, | BP Aero Services FAA Repair Station 4965 HANSON DR. | ZED R | | I |
| | | Date | 18 # | threes roved d | | | | | | | 0, Fax:9 | ion # | ELEA: | * | CAAC |
| * | | | 18 批准日期 | agn da | | | All wo | | | | Tel: 972-252-2800, Fax:972-252-2009 | BP Aero Services FAA Repair Station # 442R874B 4965 HANSON DR. | SE CE | ¥ t | |
| 是产品 | | Feb | | | | | к репоп | | | | 2009 | | AUTHORIZED RELEASE CERTIFICATE/AIRWORTHINESS APPROVA | 体业势年此数/许兑少年换存 | 用台性 Conformity |
| 田東海 | | Feb/09/2023 | | A SE | | | ned in a | 338-068-211-0 | Pari | 中中 | | ļ | ATE/A | t } | Confor |
| *参阅产品目录详细查找适用性 | | 23 | | /韓 | 人基 | | ccordan | 3-211-0 | Part No. | du | | | IRWO | | mity |
| 御田御 | | <u></u> | 19 | Cert accor requ for s | ा ज | | ce with C | | | | | | RTHIN | Ž. | |
| | F00100709 | sued by | 19 中国民机总局技权 | lifies that ordance sirement safe oper | 使用过的产品 Use 故声明上城产品繁新 进行了工作,该产品 | |)FM56-5 | Ç | ш (| KO Ek | | | ESS A | \$ | 多数区 |
| | 9 | or on | 机总局技 | t the wor with the s of the i | を対する | | B Manu | CFM56-5B | Eligibility | 9 勝田神 | | : | PPRO | | X 養教後 Airwor |
| | | Issued by or on behalf of the CAAC | 效 | k specif airworth mporting d consid | Used Parts 聯第13項的基 产品出于安全 | | al ID: CI | | | | | | VAL TAG | | vortuness |
| | | of the | | ied abov iness rei g country dered rea | ts 也其它被 全型用。 | | FMI-TP- | N | Q _V | 10 数量 | | | ด์ | | SS |
| | | CAAC | | e except gulations / and in ady for re | 大 | | SM.9, R | | | | | بن س < H | | _ | ω Fei |
| | | | : | Certifies that the work specified above except as specified in block 13 was carried out in accordance with the ainworthiness regulations of the stated country and the notified special requirements of the importing country and in respect to that work, the part(s) is (are) in confor safe operation and considered ready for release to service. (over) | 品 Used Parts。 "品除食13项的其它规定以外,已按照上这国家遗就条例和进口回透知的特殊奖权该产品出于安全可用状态可以批准放行使用。 | | All work performed in accordance with CFM56-5B Manual ID: CFMI-TP-SM.9, Revision #: 78, Revision Date: 3/15/2022 | | Sei | | Number of attached pages – 1 | 工作单/含题单/货单 Work Order / Contract / Invoice 85593 | 80861 | Certificate Ref. No | 证书编号 |
| | | | | cified in last tated contact when that we service | · 注题 | | : 78, Re | N/A | Serial/Batch No | 11 蒸烈导激号 | r of att | 测典/爱/ rder / (| | te Ref | |
| | | | | block 13 buntry ar ork, the (over) | ************************************** | | vision D | | ch No. | 中 | ached | 单 Contrac | | N O | |
| | | | | was car id the no part(s) is | | | ate: 3/15 | | | _ | pages | ct / Invo | | | |
| | | | | ried out tified sp s (are) in | 多数的件 | | s/2022 | OVER | Status | 12 产品安徽 | <u> </u> | oice | | | ŀ |
| | | | | Certifies that the work specified above except as specified in block 13 was carried out in accordance with the ainworthiness regulations of the stated country and the notified special requirements of the importing country and in respect to that work, the part(s) is (are) in condition for safe operation and considered ready for release to service. (over) | 海滨 | | | OVERHAULED | Status/Work | 光榜 | | | | | |
| | | | |) š | | | | | | | <u></u> | | | | |

*参阅产品目录详细查找适用性 Cross-check eligibility for more details with parts catalogue



Workscope Report

Work Order #: 85593

Date Printed: 2/9/2023

Time: 7:25:00 PM

Page: 1

To: AJ Walter Aviation Ltd THE HEADQUARTERS **MAYDWELL AVENUE** SLINFOLD, WEST SUSSEX

RH13 0AS UNITED KINGDOM

Phone #: +44 1403 711 777

Fax #: +44 1403 710 936

Ship To: Repairs Group

RH13 0AS

THE HEADQUARTERS

MAYDWELL AVENUE

UNITED KINGDOM

SLINFOLD, WEST SUSSEX

Email: stockmarket@ajw-aviation.com

Code: 12

Site: AWAL

PN: 338-068-211-0

Descr: PANEL, ASSY-ACOUSTICAL AFT

Qty: 2

Station:

Make:

Model: Mfg: CFMI

CFMI-TP-SM.9 CFM56-5B

ESN 779481

Ref #: ERO17455

Warranty Request N/A

TSN

CSN

Complies With

REF6

Entry Date: 11/28/2022

Need Date: 12/8/2022

Compl. Date: 2/9/2023 7:24:

Warranty: No Container:

Serial Numbers:

Inspection Findings:

Visual / Dimensional Findings

Defects In Protective Coating Erosion In area A

Repairs Required:

Repair 002- Repair of Protective Coating By Anti Erosion Paint

Repair 006- Erosion Repair by Epoxy Resin

Corrective Actions:

Overhauled - 8130/CAAC Issued

Repairs Performed:

Repair 002- Repair of Protective Coating By Anti Erosion Paint

| Repair U06- Erosion Repair by Epoxy Resin | | | | | | |
|--|----------|-----------|--|--|--|--|
| *Section of the section of the secti | Status | Seq 22 kg | | | | |
| RECEIVING INSPECTION | Complete | 0 | | | | |
| CFM56-5B-ESM-TASK-72-23-08-100-001 - CLEANING | Complete | 100 | | | | |
| CFM56-5B-ESM-TASK-72-23-08-200-001 - INSPECTION | Complete | 200 | | | | |
| CFM56-5B-ESM-TASK-72-23-08-300-006 - REPAIR 006 | Complete | 306 | | | | |
| CFM56-5B-ESM-TASK-72-23-08-300-002 - REPAIR 002 | Complete | 310 | | | | |
| PHASE II FINAL INSPECTION | Complete | 399 | | | | |
| FINAL CLEANING AND CONDITIONING | Complete | 00000 | | | | |
| FINAL INSPECTION | Complete | 00000 | | | | |



