

7055 Alexander-Fleming st, Suite 100, Saint-Laurent, QC, Canada, H4S 2B7 www.ajw-aviation.com

## **Tear Down/Inspection Report**

Work Order #: WO56596 Date Printed: 13/10/2017

Time: 8:37:00 AM

Page: 1

To:

A J WALTER AVIATION LIMITED THE HEADQUARTERS MAYDWELL AVENUE SLINFOLD, WEST SUSSEX RH13 0AS UNITED KINGDOM

Cust. RO: R327762-1

Phone #:

Fax #:

Email:

Code: AJW01

PN: C202163392E35

Serial #: 1412

Qty: 1

Descr: Braking Steering Control Unit

Mfg: SAFRAN LANDING

**TSN**: 0

**TSO**: 0

TSR: 0

CSN: 0

CSO: 0

CSR:

Engine #:

P/N Out: C202163392E35

Tail #:

Serial # out: 1412

Symptoms:

CODE:

REPAIR

DETAILS: TEMP FAULT IN SYS #2.

Faults:

CODE:

**FAULTS FOUND ON TEST** 

DETAILS:

No fault found on test arrival but we see in the NVM Break temp failure was recorded. BSCU show the snag but it's not the cause

of these failures.

CODE: DETAILS: TEST AND RECERTIFY

Test and recertify in accordance with the OEM CMM: 32-47-27, Rev: 13, Dated: Oct 28/2011.

**Corrective Actions:** 

CODE:

INSPECTED/ TESTED

DETAILS: Inspected and tested in accordance with the OEM CMM: 32-47-27, Rev: 13, Dated: Oct 28/2011.