Λ	_	_	1				T				
	13d Name	Author do			DETAIL	12 Remarks	-	6 Item		4. Organis	Authorty Country CAA/UNITED KI
	or or Doming	approved design data and are in a condition for safe operation non-approved design data specified in back 12 3b. Authorised Sciences.	The described main that the items identified above were manufactured in conformity to		ED WORK CONTENT IS HELD UNI	S IN ACCORDANCE WITH MANUFACTURERS	Ballast Unit LAST ITEM	7 Description	OAKENHURST AIRCRAFT SERVICES LTD Claydons Lane, Rayleigh, Essex SS6 7UP Tel: 44(0)1268 741622 Fax: 44(0)1268 741650 http://www.oakenhurst.com/avionics@oakenhurst.com/	4. Organisation Name and Address	1. Approving Competent Authorty Country CAATUNITED KINGDOM
1-2e Done (одгини ўуўў	tion Number		tenance has been performed in accordance		DETAILED WORK CONTENT IS HELD UNDER REFERENCE NUMBER INDICATED IN BOX 5	ANUFACTURERS MANUAL No 33-24-17 REVISION 5th February 2001 R4	3250-20-10	8. Part No	Trading as h, Essex 856 7UP x 44(0)1268 741650 vionics@oakenhurst.com		AUTHORISED RELEASE CERTIFICATE EASA FORM 1
14d Name	14b Authorised Signature	Certifies that unli described in block work the items a	e with the applicable C		0X5	2001 R4	_	9 Qy	OA		ASE CERTIFICA
Ken Benson	140	Release to Service use otherwise specified in blo k 12, was accomplished in ac k 12 considered ready for release	anadian airworthiness requirements u		SLINFOLD WEST SUSSEX RHI3 0AS	A J WALTE	001373	10 Senal No	KENHURST		TE
14e Date (dd/mmm/yyyy) 16/Apr/2014	14c Certificate / Approval Ref No. UK.145.00524	Other regulation specified in block 12 ck 12 the work identified in block 11 and cordance with PART-145 and in respect to that e to service	nder our approval number T.C.C.A :807-10	8	BEX	A J WALTER (AVIATION) LTD THE HEADQUARTERS MAYDWELL AVENUE	Repaired	11 Status Work	T17534	5 Work Order Contract/Invoice	3 Form Tracking Number 71187

NOTE

USER / INSTALLER RESPONSIBILITIES

- l. This certificate does not automatically constitute authority to install the item(s).
- 2 Where the user installer works in accordance with regulations of an Airworthness Authority different than the Airworthness Authority specified in block 1 it is essential that the user / installer ensures that his / her Airworthiness Authority accepts items from the Airworthiness Authority specified in block I
- 3 Statements 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user / installer before the aircraft may be flown

3. Statements 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance

with the national regulations by the user / installer before the aircraft may be flown

2. Where the user/installer works in accordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1 it is

essential that the user: installer ensures that his her Airworthiness Authority accepts items from the Airworthiness Authority specified in block I

1 This certificate does not automatically constitute authority to install the item(s)

EASA Form 1 - MF 145/21 Issue 2

The Avionics Workshop Shop **Movement Order**

Job No:	AVW WKSP 71	187	Date R	eceived:	26 March 2014		
Description: Ballast Unit			Date Required:				
Part No: 3250-20-10			Manuf	acturer:	Diehl		
Serial No:	001373		Mechanic: Manual Ref:		Charles Sharp		
Customer	A J WALTER (AVIATION)) LTD			33-24-17		
Order No:	T17534		Manua	l Date:	5th February 2001 R4		
Order Responsible Per	rson: CHARLOTTE W	/RIGHT	Date C	ompleted:	16 April 2014		
Customs No:			Despate	ch Note No:	86141		
Customs Date:							
Tail No / Type:	F-GJVB						
End Use No:							
Currency:	STERLING						
Work Required: PLEASE TEST A	CAA: ☑ FAA ND RECERT	C of C:	NONE S	A: ☑ Repoi	rted Defect: Warranty:		
Despatch: A J WALTER AV	IATION			Custome	r Coding_B		
Overha	uled: Repa	ired: 🗸 🔠 I	nspected - 7	Tested:	Modified:		
Strip Report: UNIT RECEIVED W TO CONNECTOR B	HAS BEEN PERFORMED IN ACCOR	EFECT. INSPEC	Wa TION FOUND INCTIONED	ONFLAMPH	ccepted: Denied: OLDER CRACKED AND WIRING EPLACED DAMAGED PARTS.		
Mech SigQ.C. Comments	Investigation (if w	Insp arranty clain Insp	7)	Date1 6 APR 2014		
		insh		-	Date		
Form No: AVW\Q)C\009 Pa	age 1 of 1	Issu	e: 21	Date: 3rd April 2014		

Issue: 21

Date: 3rd April 2014

History Report

Part No

3250-20-10

Serial No

001373

Job No

AVW WKSP 71187

Warranty No

Accepted No

Date Released

16 April 2014

Customer A J WALTER (AVIATION) LTD

Work Required

Tail No F-GJVB

Despatch Note No

86141

PLEASE TEST AND RECERT

Reported Defect

NONE STATED

Strip Report

UNIT RECEIVED WITHOUT A STATED DEFECT. INSPECTION FOUND ONE LAMPHOLDER CRACKED AND WIRING TO CONNECTOR BURNT. BENCH TEST FOUND UNIT FUNCTIONED NORMALLY. REPLACED DAMAGED PARTS. UNIT CLEANED AND TESTED IN ACCORDANCE WITH C.M.M.