

1. Approving Competent Authority / Country: United Kingdom Civil Aviation Authority	2	AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number: L 3331683
---	---	---	--	--


4. Organization Name and Address: Panasonic	Panasonic Avionics Corporation Quadrant House, Heron Drive, Parlaunt Road, Langley, Berks, SL3 8XP, UK			5. Work Order/Contract/Invoice EZR163708
---	---	--	--	--

6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No	11. Status / Work
1	MAIN MULTIPLEXER	RD-AX1301-5A	1	E112315	INSPECTED/TESTED

12. Remarks ALL WORK HAS BEEN CARRIED OUT AND LRU CONFORMED IAW CMM 44-22-05 REV 11 DTD JAN 2019. PLEASE REFER TO SR NUMBER 5323414.

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service. UZVY163X.

Panasonic Avionics Corporation internal reference **SR5323414**

14a. <input checked="" type="checkbox"/> PART 145.A.50 Release to Service <input checked="" type="checkbox"/> Other regulation specified in block 12 Certifies that unless otherwise specified in Block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.			
14b. Authorised Signature: 	14c. Certificate/Approval Ref No: UK.145.00297		
14d. Name Mick White	14e. Date (dd mmm yyyy) 17-APR-2019		

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Panasonic

Panasonic Avionics Corporation

Quadrant House, Heron Drive, Parlaunt Road,
Langley Berks, SL3 8XP, UK.
Tel: +44(0) 1753 741450 Fax: +44(0) 1753 741481

REPAIR REPORT / DELIVERY ORDER

SOLD TO **AJ WALTER AVIATION**
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, ENGLAND RH13 0AS, GB

SHIP TO **AJ WALTER AVIATION**
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, ENGLAND RH13 0AS, GB



PAGE 1 of 1

SHIP TRANSACTION:

CUSTOMER P.O. NUMBER EZR163708		CUSTOMER 1001	TAIL NO. SPARES	CUST PROD REF 6528951	SERVICE REQUEST 5323414	
PART NUMBER RD-AX1301-5A		NOMENCLATURE MAIN MULTIPLEXER			DATE REMOVED	DATE RECEIVED 31-DEC-2018
SERIAL NUMBER E112315		DATE OF MFG 31-DEC-2008	WTY START DATE 23-DEC-2008	WTY END DATE 22-DEC-2011	DATE REPAIRED 09-FEB-2019	SHIP DATE
MOD IN 1-5						
REASON FOR CUSTOMER REJECTION	LOAN UNIT RETURNED UNUSED. PLEASE TEST AND RECERTIFY.					
INTERNAL INSPECTION	No Physical Damage - DIRTY.					
EXTERNAL INSPECTION	Physical Damage - DIRTY. SCRATCHES AND SLIGHT DENTS ON COVER - DOES NOT AFFECT FIT, FORM OR FUNCTION - NO ACTION TAKEN.					
ACTUAL FAILURE / CORRECTIVE ACTION	UNIT PRE - TESTED PASSED ALL FUNCTIONAL TEST UNABLE TO CONFIRM CUSTOMER COMPLAINT. SOAK TESTED FOR AN HOUR PASSED. UNIT CLEANED AND TESTED PASSED ALL FUNCTIONAL TESTS. ALL WORK HAS BEEN CARRIED OUT AND LRU CONFORMED IAW CMM 44-22-05 REV 11 DTD JAN 2019.					

MOD OUT: 1-5

INSPECTED BY: **Mick White**

REPAIRED BY: **Adom, David E.**

PART NUMBER	DESCRIPTION	QTY	UNIT PRICE	EXTENDED PRICE	CHARGED AMOUNT	WTY*
NFF FEE	MOD/MUX NFF FEE	1	648.00	648.00	648.00	

Panasonic SHOP WARRANTY: All repairs referenced by this Repair Report are warranted as to parts and labor for a period of 12 months from the date of such repair. Used serviceable components may have been used in restoring this unit.

* WTY CODES NO = Not Covered FOC = SB covers as FOC SHOP = Shop Wty
WARR = Mfg Wty in Effect FIXED = Fixed Price Repair CC = Panasonic Charged

Cost of Labor 648.00
Cost of Material
Total Cost 648.00