

1. Approving Competent Authority / Country LUFTHART-BUNDESAMT Germany		2. AUTHORISED RELEASE CERTIFICATE		3. Form Tracking Number DB 90708067 1/1	
4. Organisation Name and Address: AIRBUS AIRBUS Operations GmbH Lüneburger Schanze 30 21614 Buxtehude, Germany		5. Work Order/Contract/Invoice R370077			
6. Item	7. Description	8. Part No.	9. Qty	10. Serial-No.	11. Status/Work
N/A	FAP	Z133H053351E	1	133H05005478	REPAIRED
12. Remarks: see Maintenance Report No.1055601 Work performed as per: CMM 23-77-15 Rev.05 Feb-14-2019 work accomplished: JAN-22-2020 The work identified in block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate no. K30Y905Y.					
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in a condition for safe operation ☐ non-approved design data specified in block 12					
13b. Authorised Signature:		13c. Approval/Authorisation Number:		14a. ☒ Part-145.A.50 Release to Service ☒ Other Regulation specified in block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.	
13d. Name:		13e. Date (dd/mm/yyyy):		14b. Authorised Signature: <i>[Signature]</i> 14c. Certificate/Approval Ref.No.: DE.145.0286	
				14d. Name: Kmuche 14e. Date (dd/mm/yyyy): 24.Jan.2020	
USER / INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

MAINTENANCE ORDER		V Activity Category		1055601 Maintenance Number		AIRBUS	
Customer AJW	Part Number Z133H053351E			Serial No SPEC2000 133H05005478		Amd.	
	Description FAP			Quantity 1		Repair-Station BUX	
Customer Order R370077		Cust. Order Date 17.12.2019		Work Order 1055601		Work Order Date 09.01.2020	
Prio ROUTINE							
Required Activities:	Test X	Repair X	Modify	Inspection X	Scrap	Overhaul	Entry Date 03.01.2020
							Redelivery Date 15.01.2020
Reason for Return INTERMITTENT SCREEN OPERATION HALF IMAGE INVERTER & FLICKERING							
Operator UKN	Removal Date	AC-Reg 9N-AKW	AC Type A320	Station UKN	Release Certificate EASA DUALFAA	Warranty	Chargeable X
		Operators Man	OEM-Man O.E.M.-M	Aviation Device YES	Package OK		
Administrator: Sell		Department: ECYS1			Phone: 040 743 51261		

MAINTENANCE REPORT	Preliminary Inspection/HDI	Pre- Strip-Test YES	Cond. elec. BAD	Cond. SW OK	Cond. mech. BAD	BITE N/A
	Status of Removal Confirmed Removal	Tech. warranty YES	Missing Part NO			
Findings: The upper half of the display content was mirrored into the lower half of the display. Further the blower made strange noise, because of pollution of the entire FAP. For repair the basis-kit PNR: 7001 240 08012, SNR: 710191000288 must be replaced. Note: We noticed some signs of wear on the front cover that have no effect on the function of the FAP.						
Remarks: Work performed as per: CMM 23-77-15 Rev.05 Feb-14-2019						
Work performed: Preliminary- and hidden damage inspection performed; the basis-kit PNR: 7001 240 08012, SNR: 710191000546 installed; acceptance test successfully performed.						
DA K 90						
Final Condition	PN_After Z133H053351E		SN_After 133H05005478		AMD_After	
	Tested X	Repaired X	Modified	Modified internal	Cond as is	Scrapped
	Warranty_Charge_WC C		NFF		QA-Inspected 24. Jan. 2020	
Work performed staff Geiger	Work performed department ECYS3		Work performed date 22.01.2020		DA K 85	