

1. Approving Competent Authority / Country EASA		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1			3. Form Tracking Number E3257438	
4. Organisation Name and Address: Panasonic Avionics Services Singapore Pte. Ltd No. 9 Loyang Lane, Singapore 508927 Tel: 65-6381-6101 Fax: 65-6545-7484				5. Work order/Contract/Invoice 3257438 / IFE800194		
6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status / Work	
1	TAPPING UNIT (TU)	RD-FA2051-02	1	E725371	INSPECTED/TESTED	
12. Remarks PERTINENT DETAILS OF MAINTENANCE ACTIONS ARE HELD AT THIS FACILITY UNDER WORK ORDER NO. AS STATED ABOVE. MODIFICATION STATUS : 1 CMM 44-26-44 Rev 5 Dated 28-Oct-11						
Reference Detail Work in attached Repair Report						
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in condition for safe operation ☐ non-approved design data specified in block 12				14a. ☒ Part-145, A.50 Release to Service ☐ Other regulation specified in block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.		
13b. Authorised Signature	13c. Approval/ Authorisation Number		14b. Authorised Signature		14c. Certificate / Approval Ref. No. EASA.145.0475	
13d. Name	13e. Date (dd mmm yyyy)		14d. Name LOW TECK ENG		14e. Date (dd mmm yyyy) 27 Jun 2013	
USER / INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the item(s). Where the user/ installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/ installer ensures that his/ her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in block 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must obtain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.						

Panasonic Avionics Services Singapore Pte Ltd.
9 Loyang Lane, Singapore 508927
Tel: 65-6381-6101 Fax: 65-6545-7484

SOLD TO TRANSAERO AIRLINES
11A, ZUBOVSKY BOULEVARD
MOSCOW, 119021, RU

SHIP TO TRANSAERO AIRLINES
11A, ZUBOVSKY BOULEVARD
MOSCOW, 119021, RU

REPAIR REPORT / DELIVERY ORDER

PAGE 1 of 1

SHIP TRANSACTION:

CUSTOMER P.O. NUMBER	IFE800194	CUSTOMER	1189	TAIL NO.	EI-XLP	CUST PROD REF	9666350	SERVICE REQUEST	3257438
PART NUMBER	RD-FA2051-02	NOMENCLATURE	TAPPING UNIT						
SERIAL NUMBER	E725371	DATE OF MFG	31-DEC-2010	WTY START DATE	31-DEC-2010	WTY END DATE	30-MAR-2014	DATE REPAIRED	21-JUN-2013
MOD IN	1	SHIP DATE	14-JUN-2013						

REASON FOR CUSTOMER REJECTION

INTERNAL INSPECTION: No Physical Damage, HIDDEN DAMAGE INSPECTION: NA.

EXTERNAL INSPECTION: No Physical Damage, PRELIMINARY INSPECTION: NO SEAL.

ACTUAL INSPECTION: PRETEST: PASSED, CLEANED LRU, UNIT TESTED PASSED AS PER CMM 44-26-44 REV 5, 28 OCT 2011.

ACTION
CORRECTIVE
FAILURE /

MOD OUT: 1

INSPECTED BY: LOW, TECK ENG

REPAIRED BY: Ho Kian Soon, Andy

PART NUMBER	DESCRIPTION	QTY	UNIT PRICE	EXTENDED PRICE	CHARGED AMOUNT	WTY*
-------------	-------------	-----	------------	----------------	----------------	------

A/V DISTRIBUTION N A/V DISTRIBUTION NFF FEE

Panasonic SHOP WARRANTY: All repairs referenced by this Repair Report are warranted as to parts and labor for a period of 12 months from the date of such repair. Used serviceable components may have been used in restoring this unit.

* WTY CODES
NO = Not Covered
FOC = SB covers as FOC
SHOP = Shop Wty
WARR = Mfg Wty in Effect
FIXED = Fixed Price Repair
CC = Panasonic Charged

Form PACSS-016 Rev 0, 1 May 11

Cost of Labor
300.00
Cost of Material
300.00
Total Cost
300.00