




Approving Competent Authority / Country CIVIL AVIATION AUTHORITY United Kingdom		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number BA23381067	
Organisation Name and Address BRITISH AIRWAYS British Airways Avionics Engineering, Ely Meadow, Talbot Green, Pontyclun, Cardiff CF72 8XL					
Item	7. Description	8. Part number	9. Qty	10. Serial No.	11. Status/Work
	GENERATR SYMBOL	622-8000-006	1	2509	Repaired
REMARKS : Batch No 0002969512 REPLACED POWER SUPPLY HANDLE, A6/U18, U26, U37, U38, U49, U50 AND ONE REAR COVER SCREW. UNIT TESTED IAW ATA 34-22-62(ATP 08201)VENDOR REV 5, BA REV 5J UNIT RELEASED UNDER TCCA APPROVAL No.808-04		Return to service in accordance with FAR 43.9 Certifies that the work specified in block 12 (or attached) was carried out in accordance with FAA airworthiness regulations and in respect to the work performed the part(s) is(are) approved for return to service.			
001496 24.01.2011 Original Manufacturer : Rockwell Collins Air Transport Div CMM:34-22-62-5		FAA certificate Nr : BT7Y404J Signature : 			
1. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in condition for safe operation ☐ non-approved design data specified in block 12		14a. ☒ PART-145.A.50 Release to service ☒ Other Regulation specified in block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with PART 145 and in respect to that work the items are considered ready for release to service.			
13b. Authorised Signature 		14b. Authorised Signature 		14c. Certificate/Approval Ref. no. UK.145.00142	
13e. Date (dd/mm/yyyy)		14d. Name U701496 Brinley Jones BAAE 042 CRS		14e. Date (dd/mm/yyyy) 24. Jan. 2011	
ER/INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

British Airways Avionic Engineering
Ely Meadow
Pontyclun
Talbot Green
CF72 8XL
South Wales
UK


BRITISH AIRWAYS
AVIONIC ENGINEERING

Component Strip Report

Customer: A J Walter Aviation
Viscount House
Partridge Green
West Sussex
RH13 8RA

Part Number: GENERATR SYMBOL

Serial Number: 2509

Description: 622-8000-006

Repair Order Number: 141193

Order Number: 5735692

Equipment Number: 42021318

Batch Number: 0002969512

Warranty Requested: No

Date of Receipt: 01-Dec-2010

Reason for Removal: ***ESTIMATE REQD*** **PLEASE ENSURE UNIT IS RELEASED WITH BOTH FAA AND
TRANSPORT CANADA APPROVAL*** PLEASE REPAIR UNDER FIXED PRICE RFR: INOP

Date Serviceable: 24-Jan-2011

Workshop Findings: REPLACED POWER SUPPLY HANDLE, A6/U18, U26, U37, U38, U49, U50 AND ONE REAR
COVER SCREW. UNIT TESTED IAW ATA 34-22-62(ATP 08201)VENDOR REV 5, BA REV 5J
UNIT RELEASED UNDER TCCA APPROVAL No.808-04

Warranty Decision:

Test/Calibrate ☐

Repaired ☒

Overhauled ☐

SB Embodied ☐

Certification Number: BA23381067