

Inflite MRO Services Ltd North Hangar Aviation Way Southend-on-Sea Essex SS2 6UN United Kingdom

IMRO LTD: CAA Part 145: UK.145.01438:

Tel: +44(0)1702 348601 IMRO LTD: FAA Repair Station: EGWY725K:

Workshop Report

Issue: **01**

Date: 30-May-22

A J Walter (Aviation) Limited T&M The Headquarters

Maydwell Avenue Slinfold West Sussex **RH13 0SH**

United Kingdom

Attn: repairs

Tel: 01403 711777

Fax: 01403 712135

E-Mail: repairs@ajw-aviation.com

Your Ref: T37893

Our Ref No: WP83012

Test Required: N/A

Part No: 211C223-518

Description: HYD PRESS SWITCH

No: IR84540

Serial No: V01371A

Workscope: Repair

Dept: Hydraulic Workshop

Release Type: CAA/FAA Dual + EASA S

Removed From:

Serial No:

Reg No:

Position:

Workscope Overview:

UNIT SUPPLIED FOR TEST

Technical Reference: BLW4915 ATA 29-09-05 - Issue No: N/A - Rev No: 6

Inspection Findings:

The switch has failed test requiring replacment of the electrical connector It was not possible to fully test the switch so this is a provisional quote subject to the final test being satisfactory

Repaired and tested iaw Eaton man ref 29-09-05 rev 6 dated Dec 2016

Signed:

Name:

NF3JEN Date: 25/9/22

For and on the behalf of Inflite MRO Services Ltd

Registered address:- Inflite House, Stansted Airport, Stansted, Essex, CM24 1RY

INFLITE MRO Services Ltd

North Hangar, Aviation Way, Southend, Essex, SS2 6UN Tel: 01702 348601 Email: imro.repairs@infilte.co.uk

Cert No: **ARC70485** UK.145.01438 HYD PRESS SWITCH Part No: 211C223-518 GRN: GRN115529 Project: WP83012

REPAIRED

S/N: **V01371A**

Qty: 1

Despatched:

SERVICEABLE