



1. Approving National Aviation Authority/Country FAA/United States		AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG				3. Form Tracking Number: 108824	
4. ORGANIZATION: Name and Address		2450 N.W. 110th Avenue Miami, Florida 33172 Tel.: (305) 594-7444 Fax: (305) 594-9080 F.A.A. Repair Station N° LZ4R354M				5. Work Order / Contract / Invoice Number: TM-196862	
 Med-Craft, Inc.							
6. Item:	7. Description:	8. Part Number:	9. Eligibility: *	10. Qty.:	11. Serial/Batch Number:	12. Status/Work:	
1.	Drain Valve	141885-1	N/A	1	108824	OVERHAULED	
13. Remarks: Work Order 108824 prescribing the actual work performed is attached. Certifies that the work specified in block 12/13 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number: EASA.145.4663. The work stated in Block 12 was accomplished IAW CMM 38-30-04 Rev Date: 08/15/85 Rev No.: 1							
14. *Certifies the items identified above were manufactured in conformity to: ***** Approved design data and in a condition for safe operation ***** ***** Not approved design data specified in Block 18 ***** *****				19. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input checked="" type="checkbox"/> Other regulations specified in Block 13 Certified that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
15. Authorized Signature:		16. Approval/Authorization No.:		20. Authorized Signature:		21. Approval/Certificate Number:	
						LZ4R354M	
17. Name (Typed or Printed):		18. Date (mm/dd/yy):		22. Name (Typed or Printed):		23. Date (mm/dd/yy):	
				OSCAR UZ		FEB 14 2013	
User/Installer Responsibilities							
<p>It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly.</p> <p>Where the user/installer work in accordance with national regulations of an airworthiness authority different than the airworthiness authority of the country specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in block 1.</p> <p>Statements in Block 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.</p>							

WORK ORDER

Work Order : 108824
Part Number : 141885-1
Serial Number : 108824
ATA Number : 38-30-04
Service Req. : Repair

Repair Order : TM-196862
Description : Drain Valve
Manufacturer : Weber
Revision Date : 08/15/85
Date : 01/21/13

FAA REPAIR STATION LZ4R354M

CONDITION REPORTED - CONFIRMED

Hard time service.

CONDITION AS RECEIVED

Missing ID plate.

NPN and NSN on unit.

W/O is opened with P/N stated on R/O and NSN.

HIDDEN DAMAGE INSPECTION

NONE FOUND

REMARKS

Unit does not have SN, please could you reassign a new one.

QUOTE and HOLD.

A new serial number will assigned per customer request.

Receiving Clerk: Giovanni Acosta

DATE: 01/21/2013

AD NOTES, Customer Specs


THERE ARE NO A.D. NOTES FOR THIS UNIT

Signature: _____



DATE: _____

01/21/2013



WORK ORDER

Work Order : 108824
Part Number : 141885-1
Serial Number : 108824
ATA Number : 38-30-04
Service Req. : Repair

Repair Order : TM-196862
Description : Drain Valve
Manufacturer : Weber
Revision Date : 08/15/85
Date : 01/21/13

FAA REPAIR STATION LZ4R354M

TEARDOWN REPORT

*Pretest

Upon pretest found:

1. Unit missing boot clamp.
2. Worn boot (leaking).

*Disassembly

Upon disassembly and inspection, the following discrepancies were found:

1. Missing boot clamps.
2. Worn boot and seal.
3. Damaged cable assembly (torn strands).
4. Corroded hardware.
5. Unit will be overhauled due to worn and damaged parts.

TECHNICIAN: Manuel Ignacio Collada SUPERVISOR: _____



WORK ORDER

Work Order : 108824
Part Number : 141885-1
Serial Number : 108824
ATA Number : 38-30-04
Service Req. : Repair

Repair Order : TM-196862
Description : Drain Valve
Manufacturer : Weber
Revision Date : 08/15/85
Date : 01/21/13

FAA REPAIR STATION LZ4R354M

CORRECTIVE ACTION

1. Replaced all worn and damaged parts.
2. Reassembled and tested unit in accordance with the manufacturer's specifications.
3. Unit passed all functional tests.

Unit overhauled and certified for return to service.

Tech : Jose Ares

Spvrsr : 

Date : 02/14/13

SERVICE PERFORMED

Overhauled

MAINTENANCE RELEASE

Issued with respect to job performed as checked above.
The component identified above was inspected in accordance with current regulations of the F.A.A. and is approved for return to service. Pertinent details of the repair are on file at this agency under

W.O.# 108824 Date FEB 14 2013 Signed 