

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2.		AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG				3. Form Tracking Number: 250821			
4. Organization Name and Address: Aero Accessories & Repair, Inc. FAA CERT #77AR783B 15501 SW 29TH ST. SUITE#201 MIRAMAR, FL 33027 Ph: 954-266-1300,				5. Work Order/Contract/Invoice Number: 59947 R416293							
6. Item		7. Description:		8. Part Number:		9. Quantity:		10. Serial Number:		11. Status/Work:	
1		FLOW DIVIDER ASSEMBLY		4501259C		1		96075		REPAIRED	
12. Remarks: The component identified above was REPAIRED in accordance with Federal Aviation Regulation and is approved for return to service with respect to the work performed. Pertinent details of the work accomplished are on the file at this agency under Form Tracking Number identified above. S/B and A/D: None Applicable. OEM CMM: 49-33-01, Revision#: 8, Revision Date: 10/4/2021 Certifies work specified in blocks 11/12 was carried out in accordance with EASA part 145, and with respect to that work, the component is considered ready for release to service under EASA part 145 Approval Number EASA 145-6467											
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12											
13b. Authorized Signature:				13c. Approval Authorization No.:				14a. ☒ 14 CFR 43.9 Return to Service ☐ Other regulation specified in Block 12			
13d. Name (Typed or Printed):				13e. Date (dd/mm/yyyy):				14b. Authorized Signature: <i>Wilson Romero</i>			
								14c. Approval/Certificate No.: 77AR783B			
								14d. Name (Typed or Printed): WILSON ROMERO			
								14e. Date (dd/mm/yyyy): 11-Sep-2023			
User/Installer Responsibilities											
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.											
Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.											
Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.											

**Aero Accessories & Repair, Inc.**

FAA CERT #77AR783B
15501 SW 29TH ST. SUITE#201
MIRAMAR, FL 33027
Ph: 954-266-1300,

Work Order**Work Order #: 59947**

Date Printed: 9/11/2023

Time: 12:49:46 PM

Page: 1

To:

AJW AVIATION LTD.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, SLI RH13 0AS
UNITED KINGDOM

Ship To:

AJW AVIATION LTD.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WS RH13 0AS
UNITED KINGDOM

Ref #: R416293

Phone #: 305 470 8007 Fax #: 441.403.710.936 Email: louise@ajw-group.com

Code: 45

Site: SH/DV

PN: 4501259C

Descr: FLOW DIVIDER ASSEMBLY

Qty: 1

Station: FUEL

Make:

Model:

Mfg: PRATT & WHITNEY

Repair Manual(s): 49-33-01 Rev: 8 Rev. Date: 10/4/2021

Entry Date: 9/1/2023

Need Date:

Compl. Date: 9/11/2023 11:5

Warranty: No

Container:

Serial Numbers: 96075

RECEIVING INSPECTION

P/N 4501259C and S/N 96075 verified on unit and customer RO. No external damage noted. See RO for work scope. Technician must verify.

PRELIMINARY INSPECTION

P/N 4501259C and S/N 96075 verified through the ID plate and customer RO.
Tech: H.P. # 74

HIDDEN DAMAGE

None noted.

INITIAL FINDINGS

Unit passed IAW technical data referenced above. Reason: Unit passed functional test.
Tech: H.P. # 74

TEARDOWN FINDINGS

Unit partially disassembled, cleaned, and inspected IAW technical data referenced above. Minor nicks, scratches, and dents do not affect fit, form, or function of the unit. Exposed packings require replacements. Unit quoted for repair.
Tech: H.P. # 74

CORRECTIVE ACTION

All parts listed in the teardown report were replaced and findings listed were corrected. Unit was repaired and tested IAW technical data reference above.
Tech: H.P. # 74

Authorized Signature: 

Name: WILSON ROMERO

Date: 9/11/2023