

1. Approving Civil Aviation Authority/Country: FAA / UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG			3. Form Tracking Number: 4348708	
4. Organization Name and Address: Panasonic Panasonic Technical Services 3301 Monte Villa Parkway Bothell, WA 98021 USA FAA Repair Station # HD6R583N		5. Work Order/Contract/Invoice Number: R290426				
6. Item	7. Description	8.	9. Part Number	10. Quantity	11. Serial Number	12. Status/Work
1	DVD PLAYER		RD-AV1306-01	1	D224821	REPAIRED
12. Remarks: CONFIRMED, "REASON FOR REMOVAL." TRH = 12552. REPLACED OVERTIMED DVD MECHANISM AND RESET TRH TO 00000. FIXED PROBLEM. CLEANED/TESTED. PASSED ALL F/T IAW CMM 44-21-81, REV 15. 20-DEC-2015.						
Panasonic Avionics Corporation certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the product/article is considered ready for release to service under EASA Part 145 approval number EASA 145.4437						
13a. Certifies the items identified above were manufactured in conformity to: Approved design data and are in a condition for safe operation. Non-approved design data specified in Block 12.						
13b. Authorized Signature:		13c. Approval/Authorization No.:		14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12		
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):		14b. Authorized Signature: I.M. Love		
				14c. Approval/Certificate No.: HD6R583N		
				14d. Name (Typed or Printed): I.M. Love		
				14e. Date (dd/mm/yyyy): 10/MAY/2016		
User/Installer Responsibilities It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.						

3301 Monte Villa Parkway, Bothell, WA 98021 U.S.A.
Tel: 425-415-9400 Fax: 425-482-3580 (Shop)

REPAIR REPORT / DELIVERY ORDER

SOLD TO AJ WALTER AVIATION
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, ENGLAND RH13 0AS, GB

SHIP TO AJ WALTER AVIATION
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, ENGLAND RH13 0AS, GB

PAGE 1 of 1

SHIP TRANSACTION:



CUSTOMER P.O. NUMBER R290426		CUSTOMER 1001		TAIL NO. SX-EMB	CUST PROD REF 4985648	SERVICE REQUEST 4348708	
PART NUMBER RD-AV1306-01		NOMENCLATURE DVD PLAYER				DATE REMOVED	DATE RECEIVED 27-APR-2016
SERIAL NUMBER D224821		DATE OF MFG 30-SEP-2006	WTY START DATE 18-DEC-2006	WTY END DATE 18-DEC-2011	DATE REPAIRED 10-MAY-2016	SHIP DATE	
MOD IN 1							
REASON FOR CUSTOMER REJECTION	EJECTS THE DISK.						
INTERNAL INSPECTION	Dusty						
EXTERNAL INSPECTION	Dirty						
ACTUAL FAILURE / CORRECTIVE ACTION	CONFIRMED, "REASON FOR REMOVAL." TRH = 12552. REPLACED OVERTIMED DVD MECHANISM AND RESET TRH TO 00000, FIXED PROBLEM. CLEANED/TESTED. PASSED ALL F/T IAW CMM 44-21-81, REV 15, 20-DEC-2015.						

MOD OUT: 1

INSPECTED BY: **Noel Lagman**

REPAIRED BY: Moore, Sean

PART NUMBER	DESCRIPTION	QTY	UNIT PRICE	EXTENDED PRICE	CHARGED AMOUNT	WTY*
CUST LABOR VXY1527ACK	OUT OF WARRANTY CHARGE DVD MECHANISM	210 1				NO

Panasonic SHOP WARRANTY: All repairs referenced by this Repair Report are warranted as to parts and labor for a period of 12 months from the date of such repair. Used serviceable components may have been used in restoring this unit.

Cost of Labor
Cost of Material

* WTY CODES NO = Not Covered FOC = SB covers as FOC SHOP = Shop Wty
WARR = Mfg Wty in Effect FIXED = Fixed Price Repair CC = Panasonic Charged

Total Cost