

1. Approving Competent Authority/Country EASA		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number MAS/E/20787	
4. Approved Organisation Name and Address Marilake aero systems Peartree Business Centre Cobham Road Ferndown, Dorset, England BH21 7PT Tel 00 44 (0) 1202 863747 Fax 00 44 (0) 1202 863748 Web www.marilake.com				5. Work Order/Contract/Invoice R405406 023830/	
6. Item	7. Description	8. Part Number	9. Qty	10. Serial No.	11. Status/Work
01	LIGHT	30-2506-3	1	EA 3411	Repaired
12. Remarks ALL WORK CARRIED OUT I.A.W. CMM 33-42-04 REV 9 - 19/07/22					
14a. ☒ Part-145.A 50 Release to Service ☐ Other Regulation specified in block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12 was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service					
14b. Authorised Signature 				14c. Certificate/Approval Ref No. EASA. UK.145.01186	
14d. Name Barry Garner				14e. Date (dd/mm/yyyy) 09-Feb-2023	

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s)

Where the user/installer performs works in accordance with regulations of an airworthiness authority different from the airworthiness authority specified in Block 1 it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1

Statements in 13a and 14a do not constitute installation certification. In all cases aircraft maintenance record must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown

TECHNICAL REPORT

Ref No : M 123

OWNER : QAM

DATE : SEP 2016

ISS : 3

SHT 1 OF 1

OUR REFERENCE	023830
PURCHASE ORDER	R405406
FOR THE ATTENTION OF	CHRIS BURCHELL
COMPANY	AJ WALTER AVIATION LTD
DESCRIPTION	LIGHT
PART NUMBER	30-2506-3
SERIAL NUMBER	3411
MAS RELEASE NOTE NO	MAS/C/E/20787

Reported Non Conformance	LENS CRACKED/ REPLACE DATA PLATE
FINDINGS:	FAULT CONFIRMED
ON INITIAL INSPECTION LENS FOUND TO BE CRACKED – THIS IS CONSIDERED CUSTOMER INDUCED DAMAGE UNIT ALSO FOUND TO HAVE AN AGED FLASH TUBE, MISSING LENS GROMMET, PLUG & DATA PLATE	
RECTIFICATION:	
UNIT DISASSEMBLED & CLEANED DEFECTIVE PARTS REPLACED UNIT REASSEMBLED & TESTED	
CONCLUSION:	
UNIT RECASSED, TESTED TO SPECIFICATION & RELEASED REPAIRED NO MODS EMBODIED	
Signed:	Date: 09 February 2023

Distribution: Original – Customer, Copy to Customer File.