

Combined Inventory Receipt & Dispatch Check Sheet

THIS DOCUMENT MAY ONLY BE COMPLETED BY A
PERSON THAT HAS RECEIVED TRAINING AND BEEN
ISSUED WITH AN INSPECTORS STAMP



B&H Warehouse Reference	Boxtop Job Number	Date Received
AW570853		

A visual inspection has been performed on this unit and the following information checked:

	RECEIPT			DISPATCH		
	Yes	No	N/A	Yes	No	N/A
EASA Form (8130) / Authorised Release Certificate	☒	☐	☐	☐	☐	☐
Trace Documentation	☒	☐	☐	☐	☐	☐
OEM Certification	☐	☐	☒	☐	☐	☐
DG Declaration	☐	☐	☒	☐	☐	☐
MSDS (Material Safety Data Sheet)	☐	☐	☒	☐	☐	☐
Shelf Life Applicable	☐	☐	☒	☐	☐	☐
Material Certification / ATA 106	☐	☐	☒	☐	☐	☐
US (unserviceable) Tag	☐	☐	☒	☐	☐	☐
Reason for Removal Stated on Tag	☐	☐	☒	☐	☐	☐
Packing Slip	☒	☐	☐	☐	☐	☐
Original Certificates Returned	☐	☐	☒	☐	☐	☐
Unused Statement	☐	☐	☒	☐	☐	☐
Physical Checks to be completed	RECEIPT			DISPATCH		
	Yes	No	N/A	Yes	No	N/A
Part Number on Unit Matches Paperwork	☒	☐	☐	☐	☐	☐
Serial Number on Unit Matches Paperwork	☒	☐	☐	☐	☐	☐
Description on Unit Matches Paperwork	☒	☐	☐	☐	☐	☐
All Paperwork carries the same part & serial number	☒	☐	☐	☐	☐	☐
Blanks fitted to ALL ports	☐	☐	☒	☐	☐	☐
FOD evident in ports / connectors	☐	☐	☒	☐	☐	☐
Static Sensitive	☐	☐	☒	☐	☐	☐
Warranty labels INTACT	☐	☐	☒	☐	☐	☐
Following tasks MUST be completed on Receipt AND Dispatch	RECEIPT			DISPATCH		
	Yes	No	N/A	Yes	No	N/A
Interior packaging sufficient to secure unit and weight of unit	☒	☐	☐	☐	☐	☐
Component wrapped in static sensitive bubble/pouch	☐	☐	☒	☐	☐	☐
Exterior packing condition acceptable for weight of unit	☒	☐	☐	☐	☐	☐
External Damage customer to inspect photo's	☐	☐	☒	☐	☐	☐
Photos Taken - Package Exterior	☒	☐	☐	☐	☐	☐
Photos Taken - Item and packaging	☒	☐	☐	☐	☐	☐
Photos Taken - Component(s)	☒	☐	☐	☐	☐	☐
Photos Taken - Data Plates and Connectors	☒	☐	☐	☐	☐	☐
OnTrack Updated	☒	☐	☐	☐	☐	☐
Other (Specify)	☐	☐	☒	☐	☐	☐
Customer advised / Pre alert sent	☐	☐	☒	☐	☐	☐
Completed by (Trained Inspector Stamp)	☒	☐	☐	☐	☐	☐

13.3 Combined Receipt & Dispatch Check Sheet

Uncontrolled Document When Printed

M



Version : 3
Dated : 05 NOV 20

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 228424	
4. Organization VSE Aviation Services, LLC Repair Station VKUR 823L Name and Address: 401 Freedom Drive Independence, KS 67301		Repair/Service Station : VKUR 823L FAA Certificate : VKUR 823L		5. Work Order/Contract/Invoice Number: R413578	
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	IGNITION EXCITER	3888058-7 CH92036	1 EA	1016250401242	OVERHAULED
12. Remarks: OVERHAULED REF: Champion Aerospace CMM 49-41-01 Rev. #3, November 16, 2015 A.J. Walter Aviation Ltd; ESN: Not supplied; Engine Type: Not supplied; TSO: 0.0; TSN: Not supplied; Certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release under EASA Part-145 Approval Number: "EASA 145-EASA.145.4603".					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.					
13b. Authorized Signature:		13c. Approval/Authorization No.:		14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12	
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):		14b. Authorized Signature: <i>Genevieve Martinez</i>	
				14c. Approval/Certificate No.: VKUR 823L	
				14d. Name (Typed or Printed): Genevieve Martinez	
				14e. Date (dd/mm/yyyy): 14/Aug/2023	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					



VSE Aviation Services, LLC

Repair Station VKUR 823L
401 Freedom Drive
Tel: 620-331-7716

Independence KS 67301
Fax: 620-331-6289

sales-ks@vseaviation.com
www.vseaviation.com

WORK ORDER INSPECTION REPORT

Page : 1 of 1

ESN : Not supplied
Engine Type : Not supplied
TSO : Not supplied
TSN : Not supplied
Alt. P/N : CH92036
Work Scope : TAR and Advise
quote overhaul

W/O No.
228424

P/N
3888058-7

S/N
1016250401242

For Customer : A.J. Walter Aviation Ltd
S.O. No. : 204862 Line No. : 1

Cust P.O. : R413578	P/N : 3888058-7	S/N :
Our Code : CHAMP	Desc : IGNITION EXCITER	CSO/CSN :
Work Code :	S/N: 1016250401242	Tag Info :
Work Req'd : OVERHAULED	MFG : Champion Aerospace LLC	Manual :
Contract : 651244579	Qty : 1 Cond As: OH	Revision :
Completed P/N : 3888058-7	S/N As: 1016250401242	Into Bin Loc :

Company : 1	Division : 031	Department :	
Order Date : Jul-12-2023	Received Date : Jul-12-2023	Due Date : Aug-16-2023	Print Date : Aug-14-2023

Repair/Service WORK ORDER No. 228424

Customer Comments
TAR and Advise. Cust. states: APU fault illuminated during starting APU.

Receiving Inspection
NO ABNORMALITIES.

Inspection Findings
SCRAPPED CHARGE PUMP DUE TO ELECTRICAL FAILURE.

Parts Installed
CHARGE PUMP P/N 9170083 AND ALL CONSUMABLES.

Test Comments
UNIT TESTED WITHIN LIMITS.

Comments
TEST AS RECEIVED REVEALED: UNIT FAILED LEAK TEST DUE TO LEAKING FROM SOLDER JOINT AND FAILED FUNCTION TEST DUE TO NO SPARK RATE.
RECOMMEND: OVERHAUL.

Authorized Signature

Name Genevieve Martinez

Date : Aug-14-2023