

1. Approving Competent Authority / Country: European Aviation Safety Agency		2		AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number: D 2270201A	
4. Organization Name and Address: Panasonic		Panasonic Avionics Corporation Dubai Airport Free Zone (DAFZ), PO Box 54340, Dubai UAE Telephone: + 971 (0) 4 212 3100. Fax: + 971 (0) 4 299 5652					
6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No	11. Status / Work		
1	LCD MONITOR	RD-AV9818-01	1	C550934	MODIFIED		
12. Remarks EMBODIED MOD 7 IAW SB RDAV9818-44-004 REV. 1 DTD. JUL. 2011. EMBODIED MOD 8 IAW SB RDAV9818-44-005 DTD. MAY 2007. EMBODIED MOD 10 IAW SB RDAV9818-44-006 REV. 2 DTD. OCT. 2010. UNIT REPAIRED, CHECKED AND INSPECTED IAW CMM 44-20-05 REV. 20 DTD. OCT. 2013.							
Panasonic Avionics Corporation internal reference SR3664638							
13a. Certifies the items identified above were manufactured in conformity to:		14a. ☒ PART 145.A.50 Release to Service ☐ Other regulation specified in block 12 Certifies that unless otherwise specified in Block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.					
13b. Authorised Signature:		13c. Approval/Authorization Number		14b. Authorized Signature: 		14c. Certificate/Approval Ref No: EASA 145.0480	
13d. Name		13e. Date (dd mmm yyyy)		14d. Name Suresh Nair		14e. Date (dd mmm yyyy) 11-AUG-2014	
USER/INSTALLER RESPONSIBILITIES							
This certificate does not automatically constitute authority to install the item(s).							
Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.							
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.							



Panasonic Avionics Corporation

Dubai Repair Station

PO Box 54340, Dubai Airport Free Zone, Dubai, UAE

Tel: +971 4 2123100 Fax: +971 4 2995652

REPAIR REPORT / DELIVERY ORDER

SOLD TO YEMEN AIRWAYS
FINANCE DEPARTMENT
GENERAL ACCOUNT
PO BOX 10600
SANA'A, REPUBLIC OF YEMEN , YE

SHIP TO YEMEN AIRWAYS
DIRECTOR MATERIAL
YEMEN AIRWAYS
PO BOX 10600
SAANN, , YE

PAGE 1 of 1

SHIP TRANSACTION:



CUSTOMER P.O. NUMBER RO-002456-2014		CUSTOMER 1416	TAIL NO. 70-ADT	CUST PROD REF 3484490	SERVICE REQUEST 3664638	
PART NUMBER RD-AV9818-01		NOMENCLATURE LCD MONITOR			DATE REMOVED 18-JUN-2014	DATE RECEIVED 10-JUL-2014
SERIAL NUMBER C550934		DATE OF MFG 30-APR-2004	WTY START DATE 30-MAY-2004	WTY END DATE 29-MAY-2007	DATE REPAIRED 10-AUG-2014	SHIP DATE
MOD IN 1-6						
REASON FOR CUSTOMER REJECTION	ACTUATOR BROKEN.					
INTERNAL INSPECTION	Physical Damage DUSTY, DAMAGE MECHANISM ASSY.					
EXTERNAL INSPECTION	No Physical Damage DUSTY.					
ACTUAL FAILURE / CORRECTIVE ACTION	TESTED - REPORTED FAILURE CONFIRMED.RETRACT INOPERATIVE DUE TO DAMAGE MECHANISM ASSY. ALSO FOUND WORN OUT SCREW UNIT CLEANED. REPLACED MECHANISM ASSY. SHEET, SCREW AND CABLE TIES. EMBODIED MOD 7 IAW SB RDAV9818-44-004 REV. 1 DTD. JUL. 2011. EMBODIED MOD 8 IAW SB RDAV9818-44-005 DTD. MAY 2007. EMBODIED MOD 10 IAW SB RDAV9818-44-006 REV. 2 DTD. OCT. 2010. UNIT FINAL TESTED - PASS ALL FUNCTIONAL TEST SATISFACTORY. UNIT REPAIRED, CHECKED AND INSPECTED IAW CMM 44-20-05 REV. 20 DTD. OCT. 2013.					

MOD OUT: 1-8,10

INSPECTED BY: **Suresh Nair**REPAIRED BY: **ABDULLA, Mr. AHAMMED**

PART NUMBER	DESCRIPTION	QTY	UNIT PRICE	EXTENDED PRICE	CHARGED AMOUNT	WTY*
CUST LABOR	OUT OF WARRANTY CHARGE	450	1.92	862.50	862.50	
R6HR845ZA	SHEET,POLYIMIDE	1	2.87	2.87	2.87	NO
R8U4AA7154ZA	PC BOARD W/COMPONENT	2	10.75	21.50	21.50	NO
R7APA810	GLUE	0	17.01	0.34	0.34	NO
R6HR75A	CABLE TIE	2	0.48	0.96	0.96	NO
R6XSQ28P6	SCREW	8	0.48	3.84	3.84	NO
R6XSS28P10	TERMINAL SCREW,STEEL	2	1.33	2.66	2.66	NO
R8F7AV9818ZA	PC BOARD W/COMPONENTS	1	55.75	55.75	55.75	
R8KJV981801C	MECHANISM	1	2,176.12	2,176.12	2,176.12	

Panasonic SHOP WARRANTY: All repairs referenced by this Repair Report are warranted as to parts and labor for a period of 12 months from the date of such repair. Used serviceable components may have been used in restoring this unit.

Cost of Labor 862.50

Cost of Material 2,264.04

* WTY CODES NO = Not Covered FOC = SB covers as FOC SHOP = Shop Wty
WARR = Mfg Wty in Effect FIXED = Fixed Price Repair CC = Panasonic Charged

Total Cost 3,126.54