

1. Approving Competent Authority / Country Civil Aviation Authority / United Kingdom		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1				3. Form Tracking Number ARC0095690
4. Organisation Name and Address : Panasonic Avionics Corporation Quadrant House, 50 Heron Drive, Parlaunt Road, Langley, SL3 8XP		5. Work Order/Contract/Invoice 10091124 PO Nbr: R372202				
6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status/Work	
1	LCD MONITOR	RD-AV9843-01	1	D710141	REPAIRED	
12. Remarks TASK DESC :PREINSP/FININSP PERFORMED IAW LRP 2.9 AND LRP 2.16 ISSUE 42, INITTEST/FINTEST PERFORMED IAW CMM REF 44-20-39 REV 37, PERFORMED PRELIMINARY INSPECTION, PERFORMED INITIAL TEST, EMBODIED SERVICE BULLETIN RDAV9843-44-011 REV 3 DTD 15-JUN-2011, REPLACED LINK COVER R6GE212WA, FITTED PET SHEET, SB RDAV9843-44-015 REV 2 DTD OCT 2014, REPLACED SPACER, FITTED R6XXHE4FJ SET SCREWS X2, NEW MEC ASSY INCORPORATES MOD 13 SB RDAV9843-44-012 REV 0 DTD APR 2011, AND MOD 16 REPLACED R6HR946ZA SHEET, REPLACED R6HR75A CABLE TIES X3, REPLACED SCREWS R6XHL28P10FN, CONSUMABLES USED. P/N: 1A27, LOT: HPA40013. P/N: R7AKE3494, 202006-042., UNIT CLEANED, PERFORMED FINAL TEST, WORK HAS BEEN CARRIED OUT IAW CMM 44-20-39 REV 37 DTD 20-JAN-2019, PERFORMED FINAL INSPECTION MOD Out #:1-7,12-13,16,18						
The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate no. UZVY163X. In accordance with TCCA Approval 808-03.						
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in a condition for safe operation ☐ non-approved design data specified in block 12		14a. ☒ Part-145.A.50 Release to Service ☒ Other regulation specified in block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and items are considered ready for release to service.				
13b. Authorised Signature	13c. Approval/Authorisation Number	14b. Authorised Signature		14c. Certificate/Approval Ref. No.		
13d. Name	13e. Date (dd mmm yyyy)	14d. Name		14e. Date (dd mmm yyyy)		
USER/INSTALLER RESPONSIBILITIES		Steve Sequeira		29 Sep 2020		
This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.						

Shop Work Order #: 10091124		Customer PO #: R372202		Customer: 1001-AJ WALTER AVIATION	
Part #: RD-AV9843-01		Serial #: D710141		Mod-IN: 1-7	
Part Description: LCD MONITOR		Customer Order #: CO0334157		Removed from A/C Reg.: OE-IKE	
Bill To		Ship To		Date Removed: 03 Jan 2020	
THE HEADQUARTERS MAYDWELL AVENUE SLINFOLD, ENGLAND, GB RH13 0AS		THE HEADQUARTERS MAYDWELL AVENUE SLINFOLD, ENGLAND, GB RH13 0AS		Date Received: 10 Feb 2020	
Observation:		MINOR MARKS ON TOUCH SCREEN AND FRONT / REAR CABINETS - NAT. RETRACT MECHANISM WORN, LINK ARM COVER SHEARED AND POWER SPRING WORN. SCREWS WORN ON EXTERNAL MOUNTINGS. CUSTOMER COMPLAINT CONFIRMED.,		Warranty Start Date: 06 Feb 2008	
Corrective Action:		PREINSP/FININSP PERFORMED IAW LRP 2.9 AND LRP 2.16 ISSUE 42, INITTEST/FINTTEST PERFORMED IAW CMM REF 44-20-39 REV 37; PERFORMED PRELIMINARY INSPECTION; PERFORMED INITIAL TEST; EMBODIED SERVICE BULLETIN RDAV9843-44-011 REV 3 DTD 15-JUN-2011; REPLACED LINK COVER R6GE212WA; FITTED PET SHEET; REPLACED R8KBV984301E MECHANISM ASSY; REPLACED R6US225ZB SPRING; NEW MEC ASSY INCORPORATES MOD 13 SB RDAV9843-44-012 REV 0 DTD APR 2011; AND MOD 16 SB RDAV9843-44-015 REV 2 DTD OCT 2014; REPLACED SPACER; FITTED R6XXE4FJ SET SCREWS x2; EMBODIED SERVICE BULLETIN RDAV9843-44-017 REV 1 DTD 03-FEB-2015; REPLACED R6HR946ZA SHEET; REPLACED R6HR75A CABLE TIES x3; REPLACED SCREWS R6XHL28P10FN; CONSUMABLES USED. P/N: 1A27, LOT: HPA40013. P/N: R7AKE3494, THC-202003-237. P/N: R7HRACFW06M, SIC-201912-199. R7LM0R265, 1908191.; CONSUMABLES USED. P/N: R7Z1401B, THC-202006-042; CONSUMABLES USED. P/N: R7Z1401B, LOT: THC-202006-042.; UNIT CLEANED; PERFORMED FINAL TEST; WORK HAS BEEN CARRIED OUT IAW CMM 44-20-39 REV 37 DTD 20-JAN-2019; PERFORMED FINAL INSPECTION		Date Repaired: 29 Sep 2020	
Mod-Out: 1-7, 12-13, 16, 18		Repaired By: Gavin Binning		Inspected By: Steve Sequeira	
Labor					
WTY CODE	QTY IN (HRS)	UNIT PRICE	CHARGED AMOUNT	Material	
No	5.75	USD 127.66	USD 893.62	PART #	PART DESCRIPTION
FOC	-	-	USD 0.00	C105146001	CAPACITOR
SHOP	-	-	USD 0.00	R6GE212WA	COVER
WARR	-	-	USD 0.00	R6HG760YA	RUBBER
Fixed	-	-	USD 0.00	R6HR2262ZA	SHEET
CC	-	-	USD 0.00	R6HR75A	HARDWARE, TIE WRAP - 2.5 x 100.0mm
			-	R6HR946ZA	SHEET
			-	R6US225ZB	SPRING
			-	R6XHL28P10FN	HARDWARE, SCREW, BINDING HD, 4-40 x 10mm LG
			-		10

Repair Report / Delivery Order

Panasonic Avionics Corporation
Panasonic Avionics Corporation
Quadrant House, 50 Heron Drive,
Parlaunt Road, Langley, SL3 8XP

Material

PART #	PART DESCRIPTION	QTY	UNIT PRICE	CHARGED AMOUNT	WTY CODE
R6XXEHE4FJ	SCREW	2			
R8KBV984301E	MECHANISM ASSY	1			
R8KKV984301	LINK ASSY	1			

Terms & Conditions:

Panasonic SHOP WARRANTY : All repairs reference by this Repair Report are warranted as to parts and labor for a period of 12 months from date of such repair used serviceable components may have been used in restoring this unit.
*WTY CODES: NO=Not Covered, FOC=Shop Warranty, WARR=Mfg Warranty in Effect, Fixed= Fixed Price Repair, CC= Panasonic Charged.

Labor Price	USD 893.62
Material Price	USD 2947.10
Total Repair Price	USD 3840.72

Generated on: 29 Sep 2020 10:19:29 Coordinated Universal Time Date/Time Format: dd-mmm-yyyy HH:MM:SS