

1. Approving Competent Authority/Country CAA-NL / THE NETHERLANDS		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1			3. Form Tracking Number 1316008268	
4. Approved Organisation Name and Address : Fokker Services B.V. Hoeksteen 40 2132 MS Hoofddorp THE NETHERLANDS		Location Oude Meer			5. Work Order/ Contract/ Invoice R300685	
6. Item	7. Description	8. Part No	9. Quantity	10. Serial No	11. Status/Work	
1	VHF COMM CONTROL PANEL	G6223-03	1 EA	757	REPAIRED	
12. Remarks USED MAINTENANCE DATA : CMM 23-11-03 REV.06 DATED 30-MAY 2002 - TCCA Approval No.: 813-33 - Accompanying shopfinding report is part of this EASA Form 1 -						
The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate no. NQ1Y357K. Pertinent details of the repair are on file at this repair station under the order number referenced in block 3.						
13a. Certifies that the items identified above were manufactured in conformity to: ☒ approved design data and are in condition for safe operation ☒ non-approved design data specified in block 12		14a. ☒ Part-145.A.50 Release to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.				
13b. Authorised Signature		13c. Approval/ Authorisation Number		14b. Authorised Signature		
13d. Name		13e. Date (dd MMM yyyy)		14c. Certificate/ Approval Ref. No		
		14d. Name Ronald Schoon		14e. Date (dd MMM yyyy) 14 SEP 2016		

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an airworthiness authority different that the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



Fokker Services B.V.

Location Oude Meer



Hoeksteen 40
2132 MS Hoofddorp
THE NETHERLANDS

Internet: www.fokkerservices.com

Shop Finding Report

Page: 1 of 2

Technician :

Delivery :

AJW AVIATION
Attn: ANDREW HONEYSETT, MRO Vendor Executive
MAYDWELL AVENUE, SLINFOLD
THE HEADQUARTERS,
RH13 0SH WEST SUSSEX
UNITED KINGDOM
Tel. : 000 44 1403 798684
Fax : 1403712135

For Customer :

AJW AVIATION

S.O. No.

2516023061

Line No. :

Cust P.O. : R300685

P/N : G6223-03

Our Ref# :

Desc : VHF COMM CONTROL PANEL

Batch/Lot :

Contract # :

S/N : 757

Cust.Ref :

Vend Ref # :

MFG : GABLES ENGINEERING INC

Work Perf. :

Project # : EC-ISY

Qty : 1.00000

Cond As: SV

Manual :

Completed P/N : G6223-03

S/N As : 757

Revision :

Company : 1

Division : 12

Department : 2500

Into Bin Loc :

Order Date : Sep-07-2016

Received Date : Sep-07-2016

Due Date : Sep-18-2016

Print Date : Sep-14-2016

WORK ORDER No. 1316008268

Reported By Customer

VHF CONTROL PANEL CM-2 IN BAD CONDITION

PLS REPAIR UNDER T & M - QUOTE AND HOLD

NO CONFIGURATION ALTERATION WITHOUT PRIOR APPROVAL

NO PMA ALLOWED WITHOUT PRIOR CONSENT

UNLESS OTHERWISE STATED MINIMUM STANDARD AND LATEST REVISION OF RELEASE REQUIRED,
DUAL (FAA / EASA). IF AVAILABLE ALSO RELEASE TO CAAC / TCCA & JCAB, WITH WORK REPORT

Receiving Condition

UPON RECEIPT NO VISUAL DAMAGE

Inspection

PRELIMINARY/INTERNAL INSPECTION:

- NO VISUAL DAMAGE.

FUNCTIONAL TEST:

- RFR UNCLEAR, ONLY FOUND TFR SWITCH STICKY OPERATING.

Name:

R.G. Smooren

Date:

14 Sep 2016

Sign:

[Signature]



Continued on next page...



Fokker Services B.V.

Hoeksteen 40
2132 MS Hoofddorp
THE NETHERLANDS

Location Oude Meer

Internet: www.fokkerservices.com

Shop Finding Report

Page: 2 of 2

WORK ORDER No. 1316008268

REASON FOR REMOVAL CONFIRMED IF TFR SWITCH IS MENT BY BAD CONDITION.

USED MAINTENANCE DATA : CMM 23-11-03 REV.06 DATED 30-MAY 2002

INTERNAL INSTRUCTION : AWI A-01032 REV.-

Action Taken

REPLACED:

- TFR SWITCH INCLUDING CAP AND DIODE D3.

UNIT PASSED FINAL TEST.

Item	Part Number / Description	Part Status	Qty	Cond	Discrepancy / Disposition
PARTS & MATERIALS					
1	514-0028 CAP	32 - Installed Component	1	EA NE	Disc. : _____ Disp. : _____
2	514-0064 SWITCH	32 - Installed Component	1	EA NE	Disc. : _____ Disp. : _____
3	480-0064 DIODE	32 - Installed Component	1	EA NE	Disc. : _____ Disp. : _____

Name: _____ Date: _____ Sign: _____

R.G. Simon

14 Sep 2016

[Signature]

