1. Approving National Aviation Authority/Country:

FAA / UNITED STATES

AUTHORIZED RELEASE CERTIFICATE

FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number

251722

SCHW

4. Organization Name and Address:

Gables Engineering, Inc. 247 Greco Ave. Coral Gables, FL. 33146 FAA Air Agency No.: G3ER114N 5. Work Order/Contract/Invoice Number:

4400018702

 6. Item
 7. Description
 8. Part Number
 9. Eligibility*
 10. Qty
 11. Serial/Batch #
 12. Status/Work

 1
 COMM, VHF - COMM: 25KHZ F/R: 18/36
 G6317-04
 N/A
 1
 236
 REPAIRED

13. Remarks

Repaired and inspected IAW: ATP A37040-04-4

2.

Confirmed rejection. Cleaned liquid spill of unit. Replaced intermittent TFR switch. Also, replaced damaged helical gear, fraction in S1, corroded dzus fasteners and switch cap. Lubricated COMM switch. Cleaned and touched up faceplate with paint. Final tested.

Gables Engineering, Inc. certifies that the work specified in block 12 and 13 was performed in accordance with EASA Implementation Rule part 145 approval, and with respect to that work, the aircraft component is considered ready for release to service under EASA number EASA.145.4459.

Reference Repaired Equipment Report (RER) for work performed.

14. Certifies the items identified above were manufactured in conformity to: Approved design data and are in condition for safe operation.		19. X 14 CFR 43.9 Return to Service Other regulation specified in Block 13				
Non-approved design data specified in Block 13.		Certifies that unless otherwise specified in block 13, the and described in Block 13 was accomplished in accorda Federal Regulations, part 43 and in respect to that work, return to service.	nce with Title 14, Code of			
15. Authorized Signature N/A	Authorization #		21. Certificate # G3ER114N			
17. Name (type or printed)	18. Date	22. Name (type or printed)	23. Date			
		Humberto H. Gonzalez				

User/Installer Responsibilities

It is important to understand that the existance of this Document alone does not automatically consitute authority to install the part/component/assembly.

Where the user/installer work in accordance with the national regulations of Airworthiness Authority different than the Airworthiness Authority of the country specified in block 1 it is essential that the user/installer ensures that his/her Airworthiness authority accepts parts/components/assemblies from the Airworthiness Authority of the country specified in block 1.

Statements in block 14 and 19 do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



Repaired Equipment Report Number: 251722

Gables Engineering, Inc. 247 Greco Ave. Coral Gables, FL. 33146 FAA Air Agency No.: G3ER114N Order Date: 9/27/2007

Date Required: 11/8/2007

Date Completed: 11/9/2007

MOD

A

Customer:

AVIANCA 173600

1801 N.W. 66 AVENUE

BLDG, 709-2 GATES 16/17/18

MIAMI FL 33122

Purchase Order #: 4400018702

Customer Order #: R57433

S/N

236

Ship VIA FEDX PI

Description Model Number

COMM, VHF - COMM: 25KHZ F/R: 18/36 G6317-04

Reject Tag #: **Customer Rejection**

Switch is INOP. Estimate

Repaired and inspected IAW: ATP A37040-04-4 Work Performed Confirmed rejection. Cleaned liquid spill of unit. Replaced intermittent TFR switch. Also, replaced damaged helical gear, fraction in S1, corroded dzus fasteners and switch cap. Lubricated COMM switch. Cleaned and touched up faceplate with paint. Final tested.

All materials and labor utilized in the repair of the above unit are listed below. Customer must authorize charges prior to repairs in excess of 50% of purchase price.

Part Number	Description	QTY		Price	Discount	Total
	LABOR CHARGE	5	HOUR	\$65.00	0%	\$325.00
514-0028	CAP/SW: - HDWR CAP WHT	1	EA	\$1.57	0%	\$1.57
514-0064	SWITCH: - TOG DPDT 1/4 MA/NONE/MA	1	EA	\$122.39	0%	\$122.39
600-A31591	NAMEPLATE - BLANK STANDARD	1	EA	\$22.95	0%	\$22.95
600-A09000-001	GEAR FRACTIONAL MHZ HELICAL DELRI	1	EA	\$37.65	0%	\$37.65
280-0197	HDWR: - BRN: FASTENER 0.064 THICKNE	1	EA	\$13.80	0%	\$13.80

Grand Total: \$523.36

Old Model Number:

G6317-04

236

MOD: A

Report Printed: 11/9/2007

Repaired By:

Inspected By:

HG