


1. Approving Competent Authority / Country EASA		2.		3. Form Tracking Number E3254758	
4. Organisation Name and Address: Panasonic Avionics Services Singapore Pte. Ltd No. 9 Loyang Lane, Singapore 508927 Tel: 65-6381-6101 Fax: 65-6545-7484				5. Work order/Contract/Invoice 3254758 / IFE800195	
6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status / Work
1	TAPPING UNIT (TU)	RD-FA2051-02	1	E725552	INSPECTED/TESTED
12. Remarks PERTINENT DETAILS OF MAINTENANCE ACTIONS ARE HELD AT THIS FACILITY UNDER WORK ORDER NO. AS STATED ABOVE. MODIFICATION STATUS : 1 CMM 44-26-44 Rev 5 Dated 28-Oct-11					
Reference Detail Work in attached Repair Report					
13a. Certifies that the items identified above were manufactured in conformity to: <input type="checkbox"/> approved design data and are in condition for safe operation <input type="checkbox"/> non-approved design data specified in block 12					
13b. Authorised Signature		13c. Approval/ Authorisation Number		14a. <input checked="" type="checkbox"/> Part-145, A.50 Release to Service <input type="checkbox"/> Other regulation specified in block 12	
13d. Name		13e. Date (dd mmm yyyy)		14b. Authorised Signature  3	
13f. Date (dd mmm yyyy)		14c. Certificate / Approval Ref. No.		14d. Name LOW TECK ENG	
14e. Date (dd mmm yyyy)		14f. Date (dd mmm yyyy)		14g. Date (dd mmm yyyy)	
USER / INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the item(s). Where the user/ installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/ installer ensures that his/ her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in block 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must obtain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

REPAIR REPORT / DELIVERY ORDER

SHIP TO TRANSAERO AIRLINES
11A, ZUBOVSKY BOULEVARD
MOSCOW, 119021, RU

SHIP TRANSACTION:



CUSTOMER P.O. NUMBER IFE800195		CUSTOMER 1189	TAIL NO. EI-XLP	CUST PROD REF 9658063	SERVICE REQUEST 3254758	
PART NUMBER RD-FA2051-02		NOMENCLATURE TAPPING UNIT			DATE REMOVED	DATE RECEIVED 12-JUN-2013
SERIAL NUMBER E725552		DATE OF MFG 31-DEC-2010	WTY START DATE 31-DEC-2010	WTY END DATE 30-MAR-2014	DATE REPAIRED 19-JUN-2013	SHIP DATE
MOD IN 1						
REASON FOR CUSTOMER REJECTION	THE UNIT WAS REPLACED AFTER A MODERNIZATION OF THE PASSENGER CABIN					
INTERNAL INSPECTION	No Physical Damage ,HIDDEN DAMAGE INSPECTION: NA.					
EXTERNAL INSPECTION	No Physical Damage ,PRELIMINARY INSPECTION: NO SEAL.					
ACTUAL FAILURE / CORRECTIVE ACTION	PRETEST: PASSED. CLEANED LRU. UNIT TESTED PASSED AS PER CMM 44-26-44 REV 5, 28 OCT 2011.					

MOD OUT: 1

INSPECTED BY: LOW, TECK ENG

REPAIRED BY: Ho Kian Soon, Andy

PART NUMBER	DESCRIPTION	QTY	UNIT PRICE	EXTENDED PRICE	CHARGED AMOUNT	WTY*
A/V DISTRIBUTION N	A/V DISTRIBUTION NFF FEE	1	300.00	300.00	300.00	

Panasonic SHOP WARRANTY: All repairs referenced by this Repair Report are warranted as to parts and labor for a period of 12 months from the date of such repair. Used serviceable components may have been used in restoring this unit.

Cost of Labor	300.00
---------------	--------

Cost of Material

* WTY CODES NO = Not Covered FOC = SB covers as FOC SHOP = Shop Wty
WARR = Mfg Wty in Effect FIXED = Fixed Price Repair CC = Panasonic Charged

Total Cost	300.00
------------	--------