

1. Approving Competent Authority / Country: United Kingdom Civil Aviation Authority		2			3. Form Tracking Number: L 3125248		
4. Organization Name and Address: Panasonic		AUTHORISED RELEASE CERTIFICATE EASA FORM 1			5. Work Order/Contract/Invoice T30974		
Panasonic Avionics Corporation Quadrant House, Heron Drive, Parlaunt Road, Langley Berks, SL3 8XP, UK							

6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No	11. Status / Work
1	CARD READER/DISK DRIVE ASSY	RD-AA902111	1	1357	REPAIRED

12. Remarks ALL WORK HAS BEEN CARRIED OUT AND LRU CONFORMED IAW CMM 23-33-20 REV 5 DTD AUG 2006. PLEASE REFER TO SR NUMBER 5011398.

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service. UZVY163X.

Panasonic Avionics Corporation internal reference **SR5011398**

13a. Certifies the items identified above were manufactured in conformity to:		14a. <input checked="" type="checkbox"/> PART 145.A.50 Release to Service <input checked="" type="checkbox"/> Other regulation specified in block 12	
<input type="checkbox"/> approved design data and are in a condition for safe operation. <input type="checkbox"/> non-approved design data specified in block 12.		Certifies that unless otherwise specified in Block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.	
13b. Authorised Signature:	13c. Approval/Authorization Number	14b. Authorized Signature:	14c. Certificate/Approval Ref No:
			UK.145.00297
13d. Name	13e. Date (dd mmm yyyy)	14d. Name	14e. Date (dd mmm yyyy)
		Mick White	22-MAY-2018

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

SOLD TO AJ WALTER AVIATION
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, ENGLAND RH13 0AS, GB

SHIP TO AJ WALTER AVIATION
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, ENGLAND RH13 0AS, GB

PAGE 1 of 1

SHIP TRANSACTION:



CUSTOMER P.O. NUMBER T30974		CUSTOMER 1001	TAIL NO. SPARES	CUST PROD REF 2650780	SERVICE REQUEST 5011398	
PART NUMBER RD-AA902111		NOMENCLATURE CARD READER/DISK DRIVE ASSY			DATE REMOVED	DATE RECEIVED 09-FEB-2018
SERIAL NUMBER 1357		DATE OF MFG 31-MAY-2001	WTY START DATE 13-JUN-2001	WTY END DATE 12-JUN-2004	DATE REPAIRED 30-APR-2018	SHIP DATE
MOD IN 1						
REASON FOR CUSTOMER REJECTION	TEST AND RECERT.					
INTERNAL INSPECTION	No Physical Damage					
EXTERNAL INSPECTION	No Physical Damage - MARKED AND SCRATCHED NO ACTION TAKEN. CREDIT CARD READER MISSING.					
ACTUAL FAILURE / CORRECTIVE ACTION	UNIT TESTED AND FAILED READ/WRITE TESTS. REPLACED FRONT PANEL, SCREWS AND MISSING MAGNETIC STRIP READER. REPLACED FLOPPY CARD DISK READER. UNIT TESTED AND PASSED ALL FUNCTIONAL TESTS. ALL WORK HAS BEEN CARRIED OUT AND LRU CONFORMED IAW CMM 23-33-20 REV 5 DTD AUG 2006.					

MOD OUT: 1

INSPECTED BY: Mick White

REPAIRED BY: Patel, Hitesh J

PART NUMBER	DESCRIPTION	QTY	UNIT PRICE	EXTENDED PRICE	CHARGED AMOUNT	WTY*
CUST LABOR	OUT OF WARRANTY CHARGE	150	2.02	302.50	302.50	
103592-03	PANEL, MTG, FDDU/CREDIT CARD READER	1	565.56	565.56	565.56	NO
102624-08	MAGNETIC STRIP READER W/CONNECTOR	1	805.62	805.62	805.62	NO
103601-01	SCREW, EMM LOCK, FLAT	4	0.88	3.52	3.52	NO
103429-01	FLOPPY DISK DRIVE	1	194.49	194.49	194.49	NO
101536-0002	SPRING LATCH ASSY, S/A C110279-4	2	18.42	36.84	36.84	NO

Panasonic SHOP WARRANTY: All repairs referenced by this Repair Report are warranted as to parts and labor for a period of 12 months from the date of such repair. Used serviceable components may have been used in restoring this unit.

Cost of Labor	302.50
---------------	--------

Cost of Material	1.606.03
------------------	----------

* WTY CODES NO = Not Covered FOC = SB covers as FOC SHOP = Shop Wty
WARR = Mfg Wty in Effect FIXED = Fixed Price Repair CC = Panasonic Charged

Total Cost	1,908.53
------------	----------