


1. Approving Competent Authority/Country		2.		3. Form Tracking Number	
CAA / United Kingdom		EASA FORM 1		ARC40668	
4. Organisation Name and Address		5. Work Order/Contract/Invoice		6. Item	
Oakenhurst Aircraft Services Ltd Claydon's Lane Rayleigh, Essex SS6 7UP United Kingdom Tel: +44 (0)1268741622 Fax: Email: sales@oakenhurst.com Web: www.oakenhurst.com		WP40625 / R339286		7. Description	
		8. Part No.		9. Qty.	
Navigational Strobe 30-1685-2		10. Serial No.		11. Status/Work	
1		1		0819 Repaired	
12. Remarks					
The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate no. 05KY452Y. TCCA Certificate No: 807-10 Work as stated in box 11 has been carried out in accordance with manufacturers manual No. 33-44-13 Revision 2, 15th July 1999					
13a. Certifies that the items identified above were manufactured in conformity to:		14a. ☒ Part-145.A.50 Release to Service		14c. Certificate/Approval Ref. No.	
☐ Approved design data and are in condition for safe operation ☐ Non-approved design data specified in block 12		☒ Other regulation specified in block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.		UK.145.00524	
13b. Authorised Signature		13c. Approval/Authorisation Number		14b. Authorised Signature	
					
13d. Name		13e. Date (dd mmm yyyy)		14d. Name	
				Mr Daniel Parker	
14e. Date (dd mmm yyyy)					
04 Jun 2018					
USER/INSTALLER RESPONSIBILITIES					
This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					



Oakenhurst Aircraft Services Ltd
Claydons Lane
Rayleigh, Essex
SS6 7UP
United Kingdom
Tel: +44 (0)1268741622

EASA Part 145: UK.145.00524

FAR 145: O5KY452Y

Workshop Report

No: **IR40492**

Issue: **04**

Date: **10-May-18**

AJW Aviation
The Headquarters
Maydwell Avenue
Slinfold
West Sussex
RH13 0AS
United Kingdom

Attn: Miss Abby Lewis

Tel: 0044 (0) 1403 798000 Fax:

E-Mail: Abigail.Lewis@ajw-group.com

Your Ref: R339286

Our Ref No: WP40625

Test Required: N/A

Part No: 30-1685-2

Description: Navigational Strobe

TSN: N/A

CSN: N/A

Serial No: 0819

Workscope: FP&E-M Repair

TSO: N/A

CSO: N/A

DoM:

Overhauled:

Inspected:

Removed From:

Serial No:

Reg No: EC-HDS

Position:

Inspection Findings:

Navigation Light received for repair. Inspection found 4 screws and a gasket missing. The reflector adhesive was incorrect. Sealant on trigger coil was insufficient. Unit inoperative. Fault traced to a defective lamp. Unit requires renewal of the defective and missing components plus attaching parts. Functional tests required iaw CMM.

Repaired and tested.

Signed:



Name:

D. Parker

Date: 04 JUN/2018

For and on the behalf of Oakenhurst Aircraft Services Ltd

Registered address:- Claydons Lane, Rayleigh, Essex, SS6 7UP