

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number J8895	
4. Organization Name and Address: Velocity Aerospace - Burbank, Inc. 2840 N. Ontario Street Burbank, CA 91504 Ph: 818-333-5600,		Repair Station Cert. # RB1R197K		5. Work Order/Contract/Invoice Number: R417256	
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	ELECTRCL LOAD CNTRL	3B41-3B	1	3B41-3B-09484	REPAIRED
12. Remarks: All work has been accomplished in accordance with FAA approved data: CMM: 24-21-18 Rev. 10 Dated: 9/9/2022					
Certified that the work specified in block 11/12 was carried out in accordance with EASA PART 145 at.d in respect to that work the component is considered ready for release to service under EASA Part 145 approval no. EASA.145.4002. For complete details of work accomplished reference tracking number in block (3) three or as attached.					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☒ Non-approved design data specified in Block 12		14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
13b. Authorized Signature:		13c. Approval/Authorization No.:		14b. Authorized Signature: <i>Jose Ramon Flores</i>	
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):		14c. Approval/Certificate No.: RB1R197K	
				14d. Name (Typed or Printed): Jose Ramon Flores	
				14e. Date (dd/mm/yyyy): 23/Oct/2023	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

**Velocity Aerospace - Burbank, Inc.**2840 N. Ontario Street
Burbank, CA 91504

Ph: 818-333-5600,

Repair Station: RB1R197K FAA/EASA.145.4002

RECAP**Work Order #: J8895**

Date Printed: 10/23/2023

Time: 3:07:42 PM

Page: 1

To: AJ WALTER AVIATION LTD (UK)
THE HEADQUARTERS
MAYDWELL AVE, SLINFOLD
WEST SUSSEX RH13 0AS UK
payableinvoices@ajw-group.com, UNITED
KINGDOM**Ship To:** AJ WALTER AVIATION LTD (UK)
THE HEADQUARTERS
MAYDWELL AVENUE, SLINFOLD
GB717870119000
WEST SUSSEX, RH13 0AS, UNITED
KINGDOM

Ref #: R417256

Phone #: 441403711414

Fax #:

Email: chris.copestake@ajw-aviation.com

Mfg: HONEYWELL

Serial #: 3B41-3B-09484

PN: 3B41-3B

Descr: ELCTRCL LOAD CNTRL

ATA Chapter: 24-21-18

Revision #: 10

Revision Date: 9/9/2022

Test Record: 2417

Technician: CURQUILLA

Type:

Entry Date: 10/5/2023

Need Date: 10/25/2023

Compl. Date: 10/23/2023 3:07:24 PM

Container:

Warranty: No

Symptoms:

WORKSCOPE: RP

REASON FOR REMOVAL

CENTER HYD ELEC PUMP #2 LOW PRESSURE LIGHT IS ILLUMINATED
MODS IN

24-33

Faults:

PRELIMINARY TEST & TEARDOWN

Unit fails FT, coil actuator draws high current when activated. Busbars/contacts lightly burned and require cleaning. Unit needs calibration and economizing.

Corrective Actions:

FINAL DISPOSITION: REPAIR

FINAL WORK ACCOMPLISHED

Cleaned contacts/busbars, inspected boards, calibrated, economized coil, and FT unit to the latest mfg's specs.

MODS OUT

24-33

STAMP TO THE RIGHT INDICATING THAT YOU HAVE VERIFIED THE FOLLOWING:

Purchase Order, Part Number, Serial Number, Mods, ATA Number, Revision, Date,
Customer Documents, and AD's

Final Insp.:

**Velocity Aerospace - Burbank, Inc.**

2840 N. Ontario Street
Burbank, CA 91504
Ph: 818-333-5600,
Repair Station: RB1R197K FAA/EASA.145.4002

WO Packing Slip**WO #: J8895**

Date: 10/23/2023

Time: 9:57:32 AM

Page: 1

Sold To:

AJ WALTER AVIATION LTD (UK)
THE HEADQUARTERS
MAYDWELL AVE, SLINFOLD
WEST SUSSEX RH13 0AS UK
payableinvoices@ajw-group.com
UNITED KINGDOM

Ship To:

AJ WALTER AVIATION LTD (UK)
THE HEADQUARTERS
MAYDWELL AVENUE, SLINFOLD
GB717870119000
WEST SUSSEX, RH13 0AS
UNITED KINGDOM

Order Date: 10/5/2023

Ship Via: FEDEX INT'L PRIORITY

Prepared By: GMEJIA

Ship Via Acc: 124277507

Customer #: 118204

Customer Ref #: R417256

Part Number/Description			Qty	
3B41-3B ELCTRCL LOAD CNTRL			1	
Serial #: 3B41-3B-09484				
For additional information please see our website				