


1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 172399	
4. Organization Name and Address: PHS/MWA Aviation Services 42355 Rio Nedo Rd Temecula, CA 92590 USA Ph: (951) 695-1008, FAA Approval Holder: OMXR603L				5. Work Order/Contract/Invoice Number: T105113/R369224	
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	SERVO ACTUATOR	A64982-3	1	1235	OVERHAULED
12. Remarks: All maintenance performed on WO# T105113 in accordance with CMM 49-50-04, Revision # 4, Revision Date: 6/9/2011					
Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145, and in respect to that work, the component is considered ready for release to service under EASA Part 145 Approval Number: "EASA.145.5102"					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12					
13b. Authorized Signature:		13c. Approval/Authorization No.:		14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.	
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):		14b. Authorized Signature: 	
				14c. Approval/Certificate No.: OMXR603L	
				14d. Name (Typed or Printed): Drake Radcliffe	
				14e. Date (dd/mm/yyyy): 21/Feb/2020	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					
FAA Form 8130-3 (02-14)					

WORK ORDER



T105113

PHS/MWA AVIATION SERVICES

42355 RIO NEDO

TEMECULA, CA 92590

FAA CRS No: OMXR603L

WORK ORDER: T105113

Customer: AJ WALTER AVIATION LTD.

Cust Ref #: R369224

Container: .

Quality Code: 2

Date Rcvd: 12/4/2019

Mfg: MOOG

Dept: ACTUATION

WR: No WA: No

EASA/FAA: Yes

Part No: A64982-3

Desc: SERVO ACTUATOR

S/N: 1235

Qty: 1

PUBLICATIONS

49-50-04

Rev No:4

WORK SCOPE: OVERHAUL

Revision Date:6/9/2011

Prelim. Insp

Unit received dirty with normal wear and tear. Tech to evaluate for damage and/or missing parts.

Reason For Removal:

after landing, on ecam air apu bleed fault when apu bleed switch selected on

Pre-Test

Unit failed internal leakage test at ext and ret.

Teardown Findings / Hidden Damage

Packing and back-up seals are worn and contaminated. Cover is out of scope. Due to level of disassembly needed, workscope is overhaul.


Corrective Action

Removed and replaced damaged, worn and/or required replacement parts.

PART NUMBER	DESCRIPTION	QTY ISSUED
082-45200-010	BACK UP RING	1
A64094-004F001	D.C. EXCLUDER	1
A64833-001	BACK-UP RING	1
A64842-001	COVER THREADED	1
B38160-517	PACKING	1
B38160-522	PACKING	1
B38160-546	PACKING	2
C29356-536	PACKING	1
C89050-001	GROUND WIRE ASSY	1
CB06539-001	SEAL, PISTON	1
CB07512-001	SEAL, ROD	2
M25988-1-012	PACKING	4
M25988/1-010	PACKING	1
M25988/1-019	PACKING	1
M25988/1-022	PACKING	2

MAINTENANCE RELEASE RECORD

THE COMPONENT IDENTIFIED ABOVE WAS INSPECTED AND/OR REPAIRED AND/OR OVERHAULED IN ACCORDANCE WITH THE CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION, AND IS APPROVED FOR RETURN TO SERVICE AND IS AIRWORTHY WITH RESPECT TO THE WORK PERFORMED. OTHER PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION.

Approved For Return to Service by:  Date: 2/21/20

PHS/MWA AVIATION SERVICES

A WENCOR GROUP Company

42355 Rio Nedo
Temecula, CA 92590
ph: 951.695.1008
fx: 951.695.1006

Mail Payments To:
PHS/MWA Aviation Services
Dept #409
PO Box 30015
Salt Lake City, UT 84130

Wire Transfer Address:
Zion Bank
190 N Main St
Spanish Fork, UT 84660
ABA# 124000054
Account#: 980057319
Swift#: ZFNBUS55

Packing Slip

WO #: T105113

Date: 2/21/2020

SHIP #: SH141138



sh141138

To:

AJ WALTER AVIATION LTD. ATTN:
THE HEADQUARTERS
MAYDWELL AVENUE, SLINFOLD

WEST SUSSEX RH13 0SH
UNITED KINGDOM

Ship To:

AJ WALTER AVIATION LTD.
THE HEADQUARTERS
MAYDWELL AVENUE, WEST SUSSEX
TARIFF 8412212010
SLINFOLD, RH13 0AS
UNITED KINGDOM

Order Date: 12/4/2019

Ship Via: FEDEX INTL PRIORITY

Terms: NET 30

Customer #: AJWA

Ship Via Acc: 124277507

Container:

Ship To Changed:

Customer RO#: R369224

Part Number/Description

Qty

A64982-3 SERVO ACTUATOR

1

Con. Code: Overhauled

Serial #: 1235

Notes:

qwfwefwqwf

Ship Via: Account Number:



124277507

Form: AS-4095 Rev 0