1. Approving Competent Authority/Country	2.	3. Form Tracking Number
CAA / United Kingdom	**AUTHORISED RELEASE CERTIFICATE** **EASA FORM 1**	ARC21249

4. Organisation Name and Address	5. Work Order/Contract/Invoice
OAKENHURST AIRCRAFT SERVICES LTD Oakenhurst Aircraft Services Ltd Claydons Lane Rayleigh, Essex SS6 7UP United Kingdom Tel: +44 (0)1268741622 Fax: Email: sales@oakenhurst.com Web: www.oakenhurst.com	WP21645 / R296649

6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status/Work
1	Telephone Handset	89-01-07332	1	115584	Repaired

12. Remarks

The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate no. O5KY452Y.

TCCA Certificate No: 807-10

IN ACCORDANCE WITH MANUFACTURERS MANUAL No: ATA 23-73-01 Revision 16 dated 29th May 2015.

13a. Certifies that the items identified above were manufactured in conformity to:

- ☐ Approved design data and are in condition for safe operation
- ☐ Non-approved design data specified in block 12

14a. ☑ Part-145.A.50 Release to Service ☑ Other regulation specified in block 12

Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.

13b. Authorised Signature	13c. Approval/Authorisation Number	14b. Authorised Signature	14c. Certificate/Approval Ref. No.
			UK.145.00524
13d. Name	**13e. Date (dd mmm yyyy)**	**14d. Name**	**14e. Date (dd mmm yyyy)**
		Mr Ian Burton AVW 2	25 Jul 2016

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

OAKENHURST
AIRCRAFT SERVICES LTD

Oakenhurst Aircraft Services Ltd
Claydons Lane
Rayleigh, Essex
SS6 7UP
United Kingdom
Tel: +44 (0)1268741622

EASA Part 145: UK.145.00524 FAR 145: O5KY452Y

Workshop Report No: IR21647 Issue: 04 Date: 20-Jul-16

AJW Aviation
The Headquarters
Maydwell Avenue
Slinfold
West Sussex
RH13 0AS
United Kingdom

Attn: Miss Danielle Binns
Tel: 0044 (0) 1403 798074 Fax:
E-Mail: danielle.binns@ajw-aviation.com

Your Ref: R296649	Our Ref No: WP21645	Test Required: N/A		
Part No: 89-01-07332	Description: Telephone Handset		TSN: N/A	CSN: N/A
Serial No: 115584	Workscope: I,C&N Repair		TSO: N/A	CSO: N/A
Removed From:	Serial No:	Reg No: LZ-PMZ	Position:	

Inspection Findings:

Received in damaged condition. Inspection showed cord over stretched, minor cracks on rear shell cosmetic only and do not effect form fit or function, front shell has 2 broken clips and id plate is worn and unreadable we were unable to confirm part number further inspection carried out and correct part number ascertained . Functional tests confirmed fault was traced to wire off pcb from microphone. Will repair microphone joints, replace shell, cord and ID plate. Will assemble and perform full final functional tests IAW CMM. ATA 23-73-01 Revision 16 dated 29th May 2015.

On external inspection part number was confirmed as 89-01-07332 not 89-01-07232 as per incoming paper work.

New shell, cord and ID plate fitted. Reassembled and tested.

Signed: Name: Date: 25/JUL/2016

For and on the behalf of Oakenhurst Aircraft Services Ltd