1. Approving Civil Aviation Authority/Country:	2.	3. Form Tracking Number:
FAA/United States	**AUTHORIZED RELEASE CERTIFICATE** **FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG**	106099879

4. Organization Name and Address:	5. Work Order/Contract/Invoice Number:
Rockwell Collins, Inc. 32125 32ND AVENUE SOUTH FEDERAL WAY, WA 98001-9345 USA RE3R812L	T36253

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
000010	HDD-980 / LRM, Mass Memory HDD-980	822-1197-101	1	7XWL	REPAIRED

12. Remarks:

Refer to attached Service Memorandum (referenced in block 3 above) for service details.
Tested Per: ATA 45-11-14, CMM 523-0778725, Rev. 00, Dated 28/Aug/1998, Temp. Rev. 05, Dated 24/Jun/2013.
Complied with Air Directive: N/A.
Service Bulletins Installed: None.

Item Numbers refer to numbers on Delivery Document

Rockwell Collins certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the [product/article] is considered ready for release to service under EASA Part 145 approval no. EASA.145.4336.

13a. Certifies the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation.

☐ Non-approved design data specified in Block 12.

N/A

14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:	13c. Approval/Authorization No.:	14b. Authorized Signature:	14c. Approval/Certificate No.:
			RE3R812L
13d. Name (Typed or Printed):	13e. Date (dd/mmm/yyyy):	14d. Name (Typed or printed) Richard J Carter	14e. Date (dd/mmm/yyyy): 07/JAN/2022

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintainence records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Rockwell Collins

Service Memorandum

Service Notification: 106099879

Customer: AJ WALTER AVIATION LTD

Customer P.O. Number: T36253

Contract Number : 40369785
Customer Reject Paper Number :
Government Incoming Document Number:
Date Equipment Received : 01/04/2022

Repair Station Certificate #: RE3R812L

Rockwell Collins, Inc.
32125 32ND AVENUE SOUTH
FEDERAL WAY WA 98001-9345
USA

For Questions Regarding This Service Work, Please Contact Customer Service at:
Phone : 253-733-3700
Fax : 253-733-3705

	Outgoing Equipment	Incoming Equipment
Equipment Type/Model	HDD-980	HDD-980
Part Number	822-1197-101	822-1197-101
Serial Number/MCN	7XWL	7XWL
Description	LRM, Mass Memory H	LRM, Mass Memory H
Mil Nomenclature		
Customer Part Number		
Customer Serial Number:		

Aircraft Information
Type : Not Available
Serial Number:
Tail No :
Position :
Removed at Gateway:
Date Unit Removed : 01/04/2022

Customer Complaint/Instructions
FOR TEST AND RECERT

Preliminary Inspection Results:
Normal wear and tear.

Was the Complaint Verified? NO **Were There Any Defects Found?** YES

Description of What Was Wrong with the Equipment:
Failed file system check.

Airworthiness Directives
No ADs issued against Rockwell to this product.

Description of Service Work Performed:
Reformatted unit to repair. Final test passed and formatted IAW/ACMM.
Note: HDD is blank and ready for service loading.

Service Bulletins/Mods Installed This Return:
None

Outgoing Service Bulletin Configuration:
None

Rockwell Collins

Service Memorandum

Service Notification: 106099879

This Article Has Been Certified Airworthy

On 01/07/2022 **By** Richard J Carter

FAA Repairman Certificate Number: 3857021

Preliminary Inspection : 01/06/2022 By Barry A Reeves

Service : 01/06/2022 By Barry A Reeves

Final Test : 01/06/2022 By Barry A Reeves

Tested Per 1 : 523-0778725 REV. 00 TEMP REV. 05

Final Inspection : 01/07/2022 By Richard J Carter

Defective / Failed Parts Replaced

Part Number	Description	Circuit Symbol

Rockwell Collins is in compliance with the FAA Anti-Drug and Alcohol Misuse Prevention Program for personnel engaged in specified aviation activities under FAA Registration Number CONN885A

Rockwell Collins agrees that it will correct, without charge, any defect in the material or workmanship related to the service work it has performed hereunder, provided the product is returned to the same Rockwell Collins Service Facility that performed the original service work, subject to:

A. Notice of the claimed defect must be given to Rockwell Collins within one (1) year from the date shipped.

B. The defect must be related to the original service work performed. Service work is not deemed to be defective if failure is caused by aircraft/system deficiencies, customer caused damage/misuse, shipping or handling damage, or exposure to environmental conditions in excess of those published in the equipment specifications.

C. Equipment returned to a Rockwell Collins Service Facility must be packaged in the original shipping container or equivalent.

D. Rockwell Collins' obligation shall be limited to that specified herein, and in no event will Rockwell Collins be responsible for consequential damages.

This guarantee is void if, prior to making claim, the equipment is altered or repair is attempted by parties other than Rockwell Collins.

The above guarantee is in lieu of provision 5 of the Rockwell Collins Inc., Repair, Overhaul and Modification General Conditions of Sale. All other terms and conditions of that document remain in effect.