| 1. Approving Competent Authority / Country | 2. | 3. Form Tracking Number: |
|---|---|---|
| **CAA.UK** | **AUTHORISED RELEASE CERTIFICATE**<br>EASA FORM 1 | **WAV2010880** |

| 4. Organization Name and Address: | 5. Work Order / Contract / Invoice Number: |
|---|---|
| Avia Technique<br>SK AeroSafety Group<br>**Avia Technique Ltd.**<br>**Unit 1,3,4 & 6 Fishponds Estate**<br>**Fishponds Road**<br>**Wokingham, Berkshire, United Kingdom RG41 2QJ**<br>**Ph: +441189789789, Fax: +441189794511** | **WAV2010880**<br>**R378160** |

| 6. Item | 7. Description: | 8. Part Number: | 9. Quantity: | 10. Serial Number: | 11. Status / Work: |
|---|---|---|---|---|---|
| 1 | Fire Extinguisher | 472088-2 | 1.00 | 5715C | Repaired |

12. Remarks:

CMM: 26-20-79 Revision: 18

"The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR Part 43 and in respect to that work, the items are approved for return to service under certificate no. I8QY183X"

Next Overhaul/Hydrostatic Test Due: 05/2024.
Last Overhaul/Hydrostatic Test: 05/2019.
Checked Weight: 17.72 Lbs.
Cartridge P/N: 446158. S/N: 31804141. Life Expires: 03/2028. Re-Fitted.

Avia Technique have checked and verified that there are no pertinent AD's or SB's relevant.

**"TCCA approval no. 808-16.**

13a. Certifies that the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation.

☐ Non-approved design data specified in Block 12

14a. [X] Part-145.A.50 Release to Service [X] Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Part-145, and in respect to that work the items are considered ready for release to service.

| 13b. Authorised Signature: | 13c. Certificate /Approval Ref No.: | 14b. Authorised Signature: | 14c. Certificate /Approval Ref No.: |
|---|---|---|---|
| | | AVIA 44 | UK.145.00846 |
| **13d. Name** | **13e. Date (dd/mmm/yyyy):** | **14d. Name** | **14e. Date (dd/mmm/yyyy):** |
| | | Jack West | 30/Oct/2020 |

**USER / INSTALLER RESPONSIBILITIES**

This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts items from the Airworthiness Authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Avia Technique
SK AeroSafety Group

**Avia Technique Ltd.**
**Unit 1,3,4 & 6 Fishponds Estate**
**Fishponds Road**
**Wokingham, Berkshire, United Kingdom**
**RG41 2QJ**
**Ph: +441189789789, Fax: +441189794511**

# Tear Down/Inspection

**Work Order #:** WAV2010880
**Date Printed:** 20/10/2020
**Page:** 1

***To:***
**A.J. Walter Aviation Ltd.**
**Maydwell Avenue**
**The Headquarters**
**Slinford RH13 0AS**
**United Kingdom**

***Ship To:***
**A.J. Walter Aviation Ltd.**
**Maydwell Avenue**
**The Headquarters**
**Slinford RH13 0AS**
**United Kingdom**

**Reference:** R378160
**Date Received:** 02/10/2020
**Part Number:** 472088-2
**Description:** Fire Extinguisher
**Serial Number:** 5715C

**Customer Remarks:**

Test

**Results from inspection:**

Faults:

Overhaul is not due till: 05/2024.

Weight check is ok.

Ground lug is damaged.

Cartridge P/N: 446158. S/N: 31804141. Life expires: 03/2028.

Date of manufacture

03/2008

Pressure switch functional tests

The Pressure Switch passed functional testing when full but may fail when removed/fully tested. In this case, the customer will be re-quoted for the full cost of a new Pressure Switch

**Corrective actions:**

Repair and Test with reference to correct CMM

Replace ground lug.

Inspection report generated by: Luke Houghton