D.4.6

1. Approving Civil Aviation Authority/Country:	2.	3. Form Tracking Number:
FAA/United States	**AUTHORIZED RELEASE CERTIFICATE** FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG	104847312

4. Organization Name and Address:	5. Work Order/Contract/Invoice Number:
Rockwell Collins, Inc. 2051 Airport Road WICHITA, KS 67209-1949 USA NZ2R049L	PO No: RO103208

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
000010	ILS-900 / RECEIVER- ILS-900	822-0298-020	1	863	TESTED

12. Remarks:

Serviced IAW EO # N/A.
S.B.s installed: N/A.
CW A.D.: N/A.
Tested Per CMM: 34-36-90 Ed.1 Rev.13

Refer to attached Service Memorandum (referenced in block 3 above) for service details.
Item Numbers refer to numbers on Delivery Document

Rockwell Collins Wichita certifies that the work specified in Blocks 11/12 was carried out in accordance with EASA part 145, and with respect to that work, the component is considered ready for release to service under EASA Part 145 Approval Number 145.4334.

13a. Certifies the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation.

☐ Non-approved design data specified in Block 12

N/A

14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:	13c. Approval/Authorization No.:	14b. Authorized Signature:	14c. Approval/Certificate No.:
		K. R. Patten	NZ2R049L
13d. Name (Typed or Printed):	**13e. Date (dd/mmm/yyyy):**	**14d. Name (Typed or printed)**	**14e. Date (dd/mmm/yyyy):**
		Kevin R. Patten	16/JAN/2015

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintainence records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Rockwell Collins

Service Memorandum

Service Notification: 104847312

Customer: INTERTRADE LTD (LOC 627)

Customer P.O. Number: RO103208

Contract Number :
Customer Reject Paper Number :
Government Incoming Document Number:
Date Equipment Received : 12/04/2014

Repair Station Certificate #: NZ2R049L

Rockwell Collins, Inc.
2051 Airport Road
WICHITA KS 67209-1949
USA

For Questions Regarding This Service Work, Please Contact Customer Service at:
Phone : 316-677-4808
Fax : 316-677-4853

	Outgoing Equipment	Incoming Equipment
Equipment Type/Model :	ILS-900	ILS-900
Part Number :	822-0298-020	822-0298-020
Serial Number/MCN :	863	863
Description :	RECEIVER- ILS-900	RECEIVER- ILS-900
Mil Nomenclature :		
Customer Part Number :		
Customer Serial Number:		

Aircraft Information

Type : Not Available
Serial Number:
Tail No :
Position :
Removed at Gateway:
Date Unit Removed :

Customer Complaint/Instructions

Evaluate for repair and return.

Preliminary Inspection Results:

Unit is dirty but no physical defects found. Unit is missing the dust cap for the rear connector.

Hidden Damage Inspection Results

N/A

Was the Complaint Verified? N/A **Were There Any Defects Found?** NO

Description of What Was Wrong with the Equipment:

No fault found.

Airworthiness Directives

NO EASA or FAA AD's applicable to this article.

Description of Service Work Performed:

No fault found. Installed a new dust cap. Unit passed final test. Inspected ok.

Service Bulletins/Mods Installed This Return:

None

Outgoing Service Bulletin Configuration:

1,2,B

Rockwell Collins

Service Memorandum

Service Notification: 104847312

This Article Has Been Certified Airworthy
On 01/16/2015 **By** Kevin R. Patten
FAA Repairman Certificate Number: 3397819

Preliminary Inspection : 01/15/2015 By Brian R Hazen

Final Test : 01/15/2015 By Brian R Hazen
Tested Per 1 : 34-36-90 ED. 1 REV. 13

Final Inspection : 01/16/2015 By Kevin R. Patten

Defective / Failed Parts Replaced

Part Number	Description	Circuit Symbol

Rockwell Collins is in compliance with the FAA Anti-Drug and Alcohol Misuse Prevention Program for personnel engaged in specified aviation activities under FAA Registration Number CONN885A