1. Approving Civil Aviation Authority/Country	2.	3. Form Tracking Number.
Transport Canada	**AUTHORIZED RELEASE CERTIFICATE** *FORM ONE*	**WO122401**

4. Organization Name and Address.

AJW Technique Inc
7055, rue Alexander Fleming
Saint-Laurent QC H4S-2B7
Canada

AJW technique

5. Work Order, Contract or Invoice Number:
R394044-1

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial/Batch Number:	11. Status/Work:
1	VALVE-CONDITIONER LOW LIMIT	810214-1	1.00	2013060014	INSPECTED/TESTED

12. REMARKS

INSPECTED AND TESTED IN ACCORDANCE WITH CMM 21-52-04 REVISION NO. 22 DATED 29 SEPT. 2021.

FOR ADDITIONAL INFORMATION REFER TO THE TEAR DOWN / INSPECTION REPORT.

EASA Approval No.: EASA.145.7260
Maintenance performed in accordance with FAR 43.17

13a. Certifies the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation.

☐ Non-approved design data specified in Block 12

14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations.

☒ CAR 571.10 Maintenance Release

☒ Other regulation specified in Block 12

13b. Signature:	13c. Approved Organization Number	14b. Signature	14c. Approval Organization Number
			33-12
13d. Name (Typed or Printed):	**13e. Date**	**14d. Name (Typed or Printed)**	**14e. Date (dd/mmm/yyyy)**
		Noel Lucas	02/May/2022

Installer Responsibilities

This certficate does not constitute authority to install the part.

Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified.
Statements in blocks 13a or 14a do not constitute installation certification. In all cases,the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.

AJW TECHNIQUE

100-7055 Alexander-Fleming, Saint-Laurent, QC, H4S 2B7, Canada
www.ajw-group.com

Tear Down/Inspection Report

Work Order: WO122401
Date Printed: 02/05/2022
Customer RO: R394044-1

To:
A J Walter Aviation Ltd.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM

Code: AJW01 **Fax:**
Phone:
Email:

Descr: VALVE-CONDITIONER LOW LIMIT
P/N: 810214-1 **Qty:** 1
S/N: 2013060014 **Mfg:** HAMILTON SUNDSTRAND

TSN: UNK **TSO:** UNK **TSR:** UNK **CSN:** UNK **CSO:** UNK **CSR:** UNK

P/N Out: 810214-1 **S/N Out:** 2013060014

Symptoms:

CODE: REASON FOR REMOVAL
DETAILS: AIR CYCLE MACHINE RH INOP.

Faults:

CODE: NORMAL ON TEST
DETAILS: Unit passed functional tests. No Fault Found.

CODE: CLEANING
DETAILS: Cleaning is required due to excessive accumulation carbon and hardened dust.

CODE: TEST ONLY
DETAILS: Unit tested in accordance with CMM 21-52-04 revision no. 22 dated 29 Sept. 2021.

Corrective Actions:

CODE: INSPECTED/ TESTED
DETAILS: INSPECTED AND TESTED IN ACCORDANCE WITH CMM 21-52-04 REVISION NO. 22 DATED 29 SEPT. 2021.

Form created with Quantum Control(tm) technology. Product Licensed to: AJW Technique Inc.