Authority/Country	AUTHORIZED RELEASE CERTIFICATE *FORM ONE*	3. Form Tracking Number:
Transport Canada		**WO29942**

4. Organization Name and Address.

AJW Technique Inc
7055, rue Alexander Fleming
Saint-Laurent QC H4S-2B7
Canada

AJW technique

5. Work Order, Contract or Invoice Number:
R280976-1

6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial/Batch Number:	11. Status/Work:
1	FLIGHT AUGMENTATION COMPUTER - F/	B397BAM0515	1.00	Q00140006896	REPAIRED

12. REMARKS

UNIT REPAIRED AND TESTED SERVICEABLE AS PER CMM 22-66-32A REV N:27 DATED FEB 06/14 . FOR MORE INFORMATION REFER TO TEAR DOWN REPORT.

PRINTED FROM ELECTRONIC FILE

EASA Approval No.: EASA.145.7260
Maintenance performed in accordance with FAR 43.17

13a. Certifies the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation.

☐ Non-approved design data specified in Block 12

14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations.

☒ CAR 571.10 Maintenance Release

☒ Other regulation specified in Block 12

13b. Signature:	13c. Approved Organization Number	14b. Signature	14c. Approval Organization Number
			33-12
13d. Name (Typed or Printed):	13e. Date	14d. Name (Typed or Printed)	14e. Date (dd/mmm/yyyy)
		Aili Abdeljalil	11/Jan/2016

Installer Responsibilities

This certficate does not constitute authority to install the part.

Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified.
Statements in blocks 13a or 14a do not constitute installation certification. In all cases,the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.

AJW technique

7055 Alexander-Fleming st, Suite 100, Saint-Laurent, QC, Canada, H4S 2B7
www.ajw-aviation.com

Tear Down/Inspection Report

Work Order #: WO29942
Date Printed: 11/01/2016
Customer RO: R280976-1
Page: 1

To:
A J WALTER AVIATION LIMITED
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM

Phone #: **Fax #:** **Email:**

Code: AJW01 **PN:** B397BAM0515 **Serial # :** Q00140006896 **Qty:** 1

Descr: FLIGHT AUGMENTATION COMPUTER - FAC **Mfg:** THALES

TSN: UNK **TSO:** UNK **TSR:** 0 **CSN:** UNK **CSO:** UNK **CSR:** 0

P/N Out: B397BAM0515 **Serial # out:** Q00140006896

Symptoms:

CODE: REPAIR
DETAILS: YAW DAMPER INOP.

Faults:

CODE: QUOTE
DETAILS: PRELIMINARY INSPECTION (VISUAL):

PART MISSING:	NO
DAMAGE FOUND (CID):	NO
HRS/CYCLE RECEIVED:	N/A

ADDITIONAL REQUIREMENT:

AD, SB, MOD, SIL	NO
ADD.CUST. REQUEST	NO

WARRANTY REQUESTED? NO

TEST ARRIVAL:

INITIAL TEST FAIL? YES

REASON FOR REMOVAL CONFIRMED: YES

DISASSEMBLY/INSPECTION:

ANY ANOMALIES FOUND DURING DISASSEMBLY/INSPECTION NO

WORK TYPE: REPAIR

WORKSCOPE:

CALIBRATION	NO
CLEANING	NO
OUT OF SCOPE	NO
OVERHAUL	NO
PAINTING	NO
PCBR	NO