1. Approving Competent Authority/Country	2.	3. Form Tracking Number
CAA/UK	**AUTHORISED RELEASE CERTIFICATE EASA FORM 1**	ARC47398

4. Organisation Name and Address	5. Work Order/Contract/Invoice
INFLITE MRO SERVICES [Formerly Inflite (Southend) Ltd] WAS (COMPONENTS) LTD North Hangar Aviation Way Southend-on-Sea Essex SS2 6UN United Kingdom Tel: +44(0)1702 348601 Fax: +44(0)1702 541534 Email: Web:	7116TEL

6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status/Work
1	EXCITER IGNITION	3603281-6	1	980218013329	INSPECTED/TESTED

12. Remarks

- WS64258 -
INSPECTED & TESTED IAW UNISON MAN. REF. 49-40-33, REV. 1 DATED 30 SEP 2002

- TCCA No. : 816-06 -

Return to Service in accordance with FAR 43.9. Certificate No: EGWY725K

Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Title 14, Code of Federal Aviation Regulations, part 43 and in respect to that work, the items are approved for return to service. Pertinent details of the repair are on file at this repair station under order:

No: 7116TEL

Sign: _____ Date: 28 Jan 19

13a. Certifies that the items identified above were manufactured in conformity to:

- ☐ Approved design data and are in condition for safe operation
- ☐ Non-approved design data specified in block 12

14a. ☑ Part-145.A.50 Release to Service ☑ Other regulation specified in block 12

Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.

13b. Authorised Signature	13c. Approval/Authorisation Number	14b. Authorised Signature	14c. Certificate/Approval Ref. No.
		WAS 93	UK.145.00579
13d. Name	**13e. Date (dd mmm yyyy)**	**14d. Name**	**14e. Date (dd mmm yyyy)**
		-	28 Jan 2019

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).
Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

INFLITE
MRO SERVICES [Formerly Inflite (Southend) Ltd]

Inflite MRO Services Ltd
North Hangar
Aviation Way
Southend-on-Sea
Essex
SS2 6UN
United Kingdom
Tel: +44(0)1702 348601

WAS (COMPONENTS) LTD: EASA Part 145: UK.145.00579: WAS (COMPONENTS) LTD: FAA Repair Station: EGWY725K:

Workshop Report No: IR64843 Issue: 01 Date: 19-Dec-18

TAG Aviation (Stansted)
The Diamond Hangar
Long Border Road
Stansted Airport
Essex
CM24 1RE
United Kingdom

Attn:
Tel: **Fax:**
E-Mail:

Your Ref: 7116TEL	**Our Ref No:** WS64258	**Test Required:** N/A
Part No: 3603281-6	**Description:** EXCITER IGNITION	
Serial No: 980218013329	**Workscope:** Inspect	
Dept: APU Workshop	**Release Type:** Dual	

Removed From:	**Serial No:**	**Reg No:**	**Position:**

Workscope Overview:

Inspection Findings:

Clean, inspect and test. No faults found.

Unit to be released.

Inspect and test in accordance with Unison Manual 49-40-33 Revision 1 September 30th 2002

Signed: Name: Date: 28 Jan /2019

For and on the behalf of Inflite MRO Services Ltd