1. Approving Civil Aviation Authority/Country:

FAA/UNITED STATES

2.

AUTHORIZED RELEASE CERTIFICATE

FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number

G1857

4. Organization Name and Address:

Velocity Aerospace - Burbank, Inc.
2840 N. Ontario Street
Burbank, CA 91504
Ph: 818-333-5600,

Repair Station Cert. # RB1R197K

5. Work Order/Contract/Invoice Number:

R379178

6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	SMOKE DETECTOR	PPC1200-00	1	3664	REPAIRED

12. Remarks:

All work has been accomplished in accordance with FAA approved data: CMM: 26-18-18 Rev: 6 Dated: 3/15/2019

Certified that the work specified in block 11/12 was carried out in accordance with EASA PART 145 and in respect to that work the component is considered ready for release to service under EASA Part 145 approval no. EASA.145.4002. For complete details of work accomplished reference tracking number in block (3) three or as attached.

13a. Certifies the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation.

☐ Non-approved design data specified in Block 12

14a. [X] 14 CFR 43.9 Return to Service [X] Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:	13c. Approval Authorization No.:	14b. Authorized Signature:	14c. Approval/Certificate No.:
			RB1R197K
13d. Name (Typed or Printed):	13e. Date (dd/mmm/yyyy):	14d. Name (Typed or Printed):	14e. Date (dd/mmm/yyyy):
		Mark A. Fisher	03/Dec/2020

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Velocity Aerospace - Burbank, Inc.
2840 N. Ontario Street
Burbank, CA 91504
Ph: 818-333-5600,

Repair Station: RB1R197K FAA/EASA.145.4002

RECAP

Work Order #: G1857

Date Printed: 12/3/2020
Time: 9:10:25 AM
Page: 1

To: AJ WALTER AVIATION LTD (UK)
THE HEADQUARTERS
MAYDWELL AVE, SLINFOLD
WEST SUSSEX RH13 OAS UK
payableinvoices@ajw-group.com, UNITED KINGDOM

Ship To: AJ WALTER AVIATION LTD (UK)
THE HEADQUARTERS
MAYDWELL AVENUE, SLINFOLD
WEST SUSSEX, RH13 0AS
UNITED KINGDOM

Ref #: R379178 **Phone #:** 441403711414 **Fax #:** **Email:** chris.copestake@ajw-aviation.com
Mfg: SIEMENS SAS **Serial #:** 3664 **PN:** PPC1200-00 **Descr:** SMOKE DETECTOR

TSN: UNKNOWN **TSO:** UNKNOWN **TSR:** UNKNOWN

ATA Chapter: 26-18-18 **Revision #:** 6 **Revision Date:** 3/15/2019
Test Record: 2439 **Technician:** MLOMBERA **Type:**
Entry Date: 11/25/2020 **Need Date:** 11/28/2020 **Compl. Date:** 12/3/2020 9:10:03 AM **Container:** **Warranty:** No

Symptoms:

WORKSCOPE: TEST

REASON FOR REMOVAL

CLEANING

Faults:

NO COMPLAINT GIVEN

PRELIM TEST & EXAM

Unit tested ok. Visually inspect unit is dirty, requires internal inspection.

TEARDOWN INSPECTION

Labyrinth and PCB are dusty, requires cleaning.

Corrective Actions:

FINAL DISPOSITION: RP

FINAL WORK ACCOMPLISHED

Cleaned labyrinth, housing and PCB assy. Reassembled, calibrated and FT'D per MFG'S SPECS.

TEST EQUIPMENT:

ABI976, ABI834A, ABI947, ABI1619

Final Inspector Signature: Mark A. Fisher Certificate Number: 2556696

1. Authority/Country:	AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG	3. Form Tracking Number
FAA/UNITED STATES		**G1857**

4. Organization Name and Address:	5. Work Order/Contract/Invoice Number:
Velocity Aerospace - Burbank, Inc. **2840 N. Ontario Street** **Burbank, CA 91504** **Ph: 818-333-5600,** **Repair Station Cert. # RB1R197K**	**R379178**

6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	SMOKE DETECTOR	PPC1200-00	1	3664	REPAIRED

12. Remarks:

All work has been accomplished in accordance with FAA approved data: CMM: 26-18-18 Rev: 6 Dated: 3/15/2019

Certified that the work specified in block 11/12 was carried out in accordance with EASA PART 145 and in respect to that work the component is considered ready for release to service under EASA Part 145 approval no. EASA.145.4002. For complete details of work accomplished reference tracking number in block (3) three or as attached.

13a. Certifies the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation.

☐ Non-approved design data specified in Block 12

14a. [X] 14 CFR 43.9 Return to Service [X] Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:	13c. Approval Authorization No.:	14b. Authorized Signature:	14c. Approval/Certificate No.:
			RB1R197K
13d. Name (Typed or Printed):	13e. Date (dd/mmm/yyyy):	14d. Name (Typed or Printed):	14e. Date (dd/mmm/yyyy):
		Mark A. Fisher	03/Dec/2020

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.