1. Approving Competent Authority / Country	2.	3. Form Tracking Number
CAA/UNITED KINGDOM	**AUTHORISED RELEASE CERTIFICATE** **EASA FORM 1**	104097937

4. Organisation Name and Address : Tel: +44(0)118 926 1111 Fax: +44(0)118 966 8543	ROCKWELL COLLINS UK LIMITED SUTTONS PARK AVENUE READING,BERKSHIRE,RG6 1LA,UNITED KINGDOM	5. Work Order / Contract / Invoice PO No: 164664

6. Item	7. Description	8. Part No	9. Qty	10. Serial No	11. Status / Work
	14 MONITOR	600958-0001	1	00004983	REPAIRED

12. Remarks

Service Notification 104097937 refers
Repaired & tested IAW CMM 100470-001. Ed-1, Rev 1, Jul 15/1998.
ACCORDING TO THE LETTER OF ACCEPTANCE No 807-24 ISSUED BY TCCA
DATE OF ISSUE 11 DEC 2009
DATE OF EXPIRY 01 JAN 2012

13a. Certifies that the items identified above were manufactured in conformity to : ☐ approved design data and are in condition for safe operation ☐ non-approved design data specified in block 12 N/A		14a. ☒ Part-145.A.50 Release to Service ☒ Other regulation specified in block 12 Certifies that unless otherwise specified in block 12, the workidentified in block 11 and described in block 12, was accomplished in accordance with Part 145 and in respect to that work the items are considered ready for releaseto service.	
13b. Authorised Signature	13c. Approval/Authorisation No	14b. Authorised Signature 58 R.C.U.K	14c. Certificate/Approval Ref.No UK.145.00237
13d. Name	13e. Date (dd mmm yyyy)	14d. Name Andrew Robinson	14e. Date (dd mmm yyyy) 02/NOV/2011

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in block 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

1. Approving National Aviation Authority/Country:	2.	3. Form Tracking Number
FAA/United States	**AUTHORIZED RELEASE CERTIFICATE** **FAA FORM 8130-3,AIRWORTHINESS APPROVAL TAG**	104097937

4. Organization Name and Address:	5. Work Order/Contract/Invoice Number:
ROCKWELL COLLINS UK LIMITED SUTTONS PARK AVENUE READING,BK RG6 1LA UNITED KINGDOM BZ5Y 771M	PO No: 164664

6. Item:	7. Description:	8. Part Number:	9. Eligibility:*	10. Quantity:	11. Serial/Batch Number:	12. Status/Work:
000010	14 MONITOR	600958-0001	N/A	1	00004983	REPAIRED

13. Remarks:

1. Service notification number 104097937 refers.
2. Repaired & tested IAW CMM 100470-001. Ed-1, Rev 1, Jul 15/1998.

Item Numbers refer to numbers on Delivery Document

14. Certifies the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation.

☐ Non-approved design data specified in block 2.

N/A

15. Authorized Signature:	16. Approval/Authorization No.:
17. Name (Typed or Printed):	18. Date (m/d/y):

19. ☒ 14 CFR 43.9 Return to Service ☐ Other regulation specified in Block 13

Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13, was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

20. Authorized Signature:	21. Approval/Certificate No.:
	BZ5Y 771M
22. Name (Typed or printed) Andrew Robinson	23. Date (m/d/y): NOV/02/2011

58 R.C.U.K

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in block 1 it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in block 1.

Statements in block 14 and 19 do not constitute installation certification. In all cases, aircraft maintainence records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Rockwell Collins

Service Memorandum

Service Notification: 104097937

Customer: AJ WALTER AVIATION LTD

Customer P.O. Number: 164664

Contract Number :
Customer Reject Paper Number :
Government Incoming Document Number:
Date Equipment Received : 01.11.2011

Repair Station Certificate #:
BZ5Y771M UK.145.00237

ROCKWELL COLLINS UK LIMITED
SUTTONS PARK AVENUE
READING RG6 1LA
UNITED KINGDOM

For Questions Regarding This Service Work, Please Contact Customer Service at:
Phone : +44 (0) 118 935 9246
Fax : +44 (0) 118 966 8543

	Outgoing Equipment	Incoming Equipment
Equipment Type/Model :		
Part Number :	600958-0001	600958-0001
Serial Number/MCN :	00004983	00004983
Description :	14 MONITOR	14 MONITOR
Mil Nomenclature :		
Customer Part Number :		
Customer Serial Number:		

Aircraft Information
Type :
Serial Number:
Tail No :
Position :
Removed at Gateway:
Date Unit Removed :

Customer Complaint/Instructions
Picture keeps disappearing.

Preliminary Inspection Results:
RCUK warranty seals intact, essd caps fitted and unit received dirty.

Hidden Damage Inspection Results
N/A

Was the Complaint Verified? YES
Were There Any Defects Found? YES

Description of What Was Wrong with the Equipment:
Monitor has an intermittent picture.

Airworthiness Directives
N/A

Description of Service Work Performed:
Dismantled monitor and reworked degraded solder joints on the motherboard to address customer complaint. Cleaned and humisealed reworked areas. Checked set-up levels, cleaned unit, reassembled and soak tested. Repaired and tested iaw CMM 100470-001, Ed-1, Rev 1, Jul 15/1998.

Service Bulletins/Mods Installed This Return:
None

Outgoing Service Bulletin Configuration:
None

Rockwell Collins

Service Memorandum

Service Notification: 104097937

This Article Has Been Certified Airworthy
On 02.11.2011 **By** A. Robinson

Preliminary Inspection : 02.11.2011 By Harjit Chaddha

Final Test : 02.11.2011 By Harjit Chaddha
Tested Per 1 : CMM 100470-001 ED. 1 REV. 01 TEMP REV. 5

Final Inspection : 02.11.2011 By Andrew G Robinson

Defective / Failed Parts Replaced

Part Number	Description	Circuit Symbol

The supplier agrees that it will correct, without charge, any defect which is related to the original repair work performed, provided the customer gives the supplier prompt written notice of such defect and the equipment involved is returned to the supplier where repair work was performed. The period of the guarantee in the servicing of the product shall be one year from the date of despatch. Failures which are caused by aircraft/system deficiencies, customer damage/misuse, shipping or handling damage or exposure to environmental conditions in excess of those published in the equipment specifications are not covered by this guarantee. Warranty will be void if Rockwell Collins inspection seals are broken.

Rockwell Collins obligation shall be limited to that specified herein, and in no event will Rockwell Collins be responsible for consequential damages.

(For Airworthiness Release)
The work recorded above has been carried out in accordance with the requirements of the Air Navigation Order for the time being in force and in that respect the aircraft/equipment is considered fit for release to service.
ROCKWELL COLLINS UK LIMITED
E.A.S.A. APPROVAL UK.145.00237
F.A.A. APPROVAL BZ5Y 771M