1. Approving Civil Aviation Authority/Country: **FAA/United States**	2. **AUTHORIZED RELEASE CERTIFICATE** **FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG**	3. Form Tracking Number: 20200008187225Y15 339141018
4. Organization Name and Address: Honeywell International Inc. 23500 W 105th Street Olathe KS 66061	Repair Station PR2R093L	5. Work Order/Contract/Invoice Number: 9801018 339132123 Page 1 of 1

6.Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status / Work:
001	OUTLINE ASSEMBLY MULTI-MODE RECEIVER, RM	066-50029-1201	1	RMA55B-06113	REPAIRED

12. Remarks:

THE SERVICE SPECIFIED HAS BEEN ACCOMPLISHED IN ACCORDANCE WITH:
CMM 34-55-51 Rev 5, MAR/26/2019

THIS DOCUMENT HAS BEEN ISSUED ACCORDING TO AN APPROVED COMPUTER GENERATED SIGNATURE PROCEDURE
MODS: 1-8
SW VERS: N/A

SEE ATTACHED DOCUMENTS AS APPLICABLE FOR WORK PERFORMED

CERTIFIES THAT THE WORK SPECIFIED IN BLOCK 11/12 WAS CARRIED OUT IN ACCORDANCE WITH EASA PART 145 AND IN RESPECT TO THAT WORK THE COMPONENT IS CONSIDERED READY FOR RELEASE TO SERVICE UNDER EASA PART 145 APPROVAL NO. EASA 145.4140

13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.		14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12. Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.	
13b. Authorized Signature:	13c. Approval/Authorization No.:	14b. Authorized Signature:	14c. Approval/Certificate No.: **PR2R093L**
13d. Name (Typed or Printed):	13e. Date(dd/mmm/yyyy):	14d. Name (Typed or Printed): **Deislyn Edwards**	14e. Date(dd/mmm/yyyy): **18/MAY/2020**

User / Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

1. 国家 Country	2. 中国民用航空总局 CAAC ☐ 符合性 Conformity ☒ 适航性 Airworthiness	3. 证书编号 Certificate Ref. No.
中国 China	批准放行证书/适航批准标签 AUTHORIZED RELEASE CERTIFICATE/AIRWORTHINESS APPROVAL TAG	20200008187262Y05 339141018

4. 单位 Organization	5. 工作单/合同单/货单 Work Order/Contract/Invoice
Honeywell International Inc 4150 Lind Avenue SW RENTON WA 98057	9801018 339132123 Page 1 of 1

6. 序号 Item	7. 内容 Description	8. 件号 Part No.	9. 适用性 Eligibility	10. 数量 Qty	11. 系列号/批号 Serial/Batch No.	12. 产品状态 Status/Work
001	OUTLINE ASSEMBLY MULTI-MODE RECEIVER, RM	066-50029-1201	NOT KNOWN	1	RMA55B-06113	REPAIRED

13 备注 Remarks

THE SERVICE SPECIFIED HAS BEEN ACCOMPLISHED IN ACCORDANCE WITH:
CMM 34-55-51 Rev 5, MAR/26/2019

NOTE: THIS PART WAS WORKED UNDER THE AUTHORITY OF THE RENTON REPAIR STATION (F00100101) AT THE HONEYWELL OLATHE MRO (F00100519), WITH SPECIAL PERMISSION FROM THE CAAC AS PART OF A RELOCATION PROJECT.

ACTUAL REPAIR STATION ADDRESS:

23500 W 105TH STREET
TEXT CONTINUED ON RIGHT SIDE

SEE ATTACHED DOCUMENTS AS APPLICABLE FOR WORK PERFORMED

CONTINUED:
OLATHE, KS 66061

MODS: 1-8
SW VERS: N/A

14. 新产品 New Parts

~~兹声明上述产品除第13项的其它规定以外,~~
~~已按照上述国家适航条例进行制造/检查,~~
~~并且该产品(出口产品)符合经批准的型号设计资料和进口国提出的专用要求。~~

~~Certifies that the part(s) identified above except as otherwise specified in block 13 was (were) manufactured / inspected in accordance with the airworthiness regulations of the stated country and / or in the case of parts to be exported with the approved design data and with the notified special requirements of the importing country.~~

15. 使用过的产品 Used Parts

兹声明上述产品除第13项的其它规定以外,
已按照上述国家适航条例和进口国通知的特殊要求进行了工作,
该产品处于安全可用状态可以批准放行使用。

Certifies that the work specified above except as specified in block 13 was carried out in accordance with the airworthiness regulations of the stated country and the notified special requirements of the importing country and in respect to that work, the part(s) is(are) in condition for safe operation and considered ready for release to service. (over)

16. 批准人签名 Signature	18. 批准日期 Date	19. 中国民航总局授权 Issued by or on behalf of the CAAC
[signature]	MAY/18/2020	F00100101

17. 批准人姓名(打印的) Name (Printed): Jason Holsclaw

AAC - 038(12/94)

* 参阅产品目录详细查找适用性
Cross - check eligibility for more details with parts catalogue

中 国 民 用 航 空 局 飞 行 标 准 司

Flight Standards Department
Civil Aviation Administration of China

中国北京东四西大街155号
邮政编码：100710

155 Dongsi Street, West
Beijing, P.R. China, 100710

To:	Honeywell (Renton)
Address:	4150 Lind Ave SW Renton Washington 98057 USA
Tel:	425/251-9511
Fax:	425/251-9368
Date:	Dec. 10, 19
Doc. No.	SA-20190588

Subject: Notification of CAAC Special Approval

To Whom it may concerns:

Your application for the maintenance work at your new location has been received and reviewed.

Based on the detailed move plan and supporting documents provided in your letter for how to make sure comply with CAAC regulation requirements during movement, the purpose of this letter is to formally inform you that your company, Honeywell (Renton) , (Certificate No. F00100101), is authorized to perform maintenance work temporarily at your proposed new location, 23500 W, 105th St, Olathe, KS, 66061, USA. Please keep us update for your movement schedule changes, CAAC will perform on site audit to the new location as scheduled.

This temporary approval is valid until you have received any other formal approval issued by CAAC or before the day June 30, 2020, which comes earlier. Your company may release Component after the maintenance work finished during this period by this Special Approval, and the working scope is limited to the Rating specified on the MOC and latest Maintenance Capability List approved by CAAC.

The copy of this letter shall be attached with the releasing document.

Yours Sincerely,

LI Heping
Director
Continuous Airworthiness & Maintenance Division

Honeywell
Aerospace-Olathe
Honeywell International Inc.
23500 W 105th Street
Olathe KS 66061

SERVICE REPORT

HAT - Phoenix

SR NUMBER: 5014707527 339141018		FAA: PR2R093L	EASA: EASA.145.4140
PO: 9801018	CUSTOMER PART NUMBER:	CONTRACT NUMBER:	
DATE REJECTED: 06 MAR 2020	DATE RECEIVED: 06 MAR 2020	DATE COMPLETED: 18 MAY 2020	
A/C TYPE: UNK	A/C TAIL NUMBER:	A/C SERIAL NUMBER:	
PACKING STATUS: No	SEALS INTACT: Intact	PHYSICAL DAMAGE: No	

REASON FOR REMOVAL:
(SEE PURCHASE ORDER FOR COMPLETE INSTRUCTIONS)

	AS RECEIVED:	AS RELEASED:
PART NUMBER	066-50029-1201	066-50029-1201
DESCRIPTION:	OUTLINE ASSEMBLY MULTI-MODE RECEIVER,	OUTLINE ASSEMBLY MULTI-MODE RECEIVER,
SERIAL NUMBER	RMA55B-06113	RMA55B-06113
UID(MFR/SPL PNO SER/UCN)	22373 33850531	22373 33850531
HW MOD STATUS:	1-8	1-8
SW MOD STATUS:	01/02	01/02
SOFTWARE LOAD:	N/A	N/A

REASON FOR REMOVAL CONFIRMED: Rejection Confirmed
ESTIMATE SUPPLIED: No

PRIMARY SHOP FINDING: Hardware Fault Found
WARRANTY:

TYPE OF SERVICE: REPAIRED
TECHNICIAN: Charles Sims

MAINTENANCE STATEMENT:
PAGE DETAILING WORK PERFORMED, ALONG WITH MATERIALS USED, IS ATTACHED IN PAGE 2.

SIGNATURE BELOW REQUIRED ONLY WHEN RETURN TO SERVICE IS NOT ISSUED: **DATE:**_____

SIGNATURE OF AUTHORIZED PERSON:_____

Complied With
CMM/Eng Documentation: 34-55-51/Rev 5/Rev Date 26 MAR 2019;
Service Bulletins:
Customer Manuals/Documentation:

SHOULD YOU REQUIRE ANY FURTHER INFORMATION REGARDING THIS SERVICE REPORT, OR HAVE ANY QUESTIONS, PLEASE CONTACT OUR CUSTOMER RESPONSE CENTER AT 1-800-601-3099 OR VISIT OUR CUSTOMER PORTAL AT www.MyAerospace.com TO SUBMIT AN INQUIRY.

Honeywell

Aerospace-Olathe
Honeywell International Inc.
23500 W 105th Street
Olathe KS 66061

SERVICE REPORT

HAT - Phoenix

SR NUMBER: 5014707527		FAA: PR2R093L	EASA: EASA.145.4140
PO: 9801018	CUSTOMER PART NUMBER:	CONTRACT NUMBER:	

Previously Complied With
CMM/Eng Documentation:
Service Bulletins:
Customer Manuals/Documentation:

Evaluation Findings
INCOMING STATEMENT:
Unit failed incoming test due to fault codes "Ka,D7" logged in BITE Memory.
REPAIR ACTIONS REQUIRED:
Will replace GNSS Module to correct failures.
Will replace C2010, C2012, & Y2001 to correct failures.
MODIFICATION ACTIONS REQUIRED:
N/A
REQUOTE COMMENTS:
N/A

Work performed / Comments to Customer
Confirmed customer reason for return.
Unit passed final test. Test equipment calibration dates checked and final Tested by Charles Sims on 05/18/2020. This component is airworthy with respect to the work performed.

DISPOSITION	REF DSG	P/N Installed	S/N Installed	P/N Removed	S/N Removed	Qty	Primary Failure	SB
Exchange	GNSS MODULE	722-4374-002	07092922	722-4374-002	06082239	1		
Replaced GNSS Module due to fault codes "Ka" logged in BITE Memory.								
Exchange	MAIN BOARD	30090240-0591	PLP143000722	30090240-0591	PLX081813818	1		
BER (Beyond Economical Repair)								

MEASUREMENT DESCRIPTION	MEAS. VALUE (DECIMAL)	MEAS. VALUE (HH:MM)
Time Since Repair		0:00
Cycles Since Repair		