1. Approving Competent Authority / Country CIVIL AVIATION AUTHORITY United Kingdom	2. **AUTHORISED RELEASE CERTIFICATE** **EASA FORM 1**	3. Form Tracking Number BA32874521

4. Organisation Name and Address BRITISH AIRWAYS	British Airways Avionics Engineering. Ely Meadow, Talbot Green, Pontyclun, Cardiff CF72 8XL	5. Work Order/Contract/Invoice 4518094 W40726

6.Item	7.Description	8.Part number	9.Qty	10.Serial No.	11.Status/Work
1.	SMOKE DETECTOR (VITAL)	2156-204A	1	8284	Repaired

12.REMARKS : Batch No 0005824926
Unable to confirm reason for removal - '..CARGO SMOKE DET 2'
Spare lamp missing.
Replaced: lamp.
Unit given final test - satisfactory IAW ATA:26-16-04 ATP:07546 REV:9
Unit released under TCCA Approval No. 808-04

U129340 13.10.2017 Original
Manufacturer : AUTRONICS CORP&space(5)

The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate no. BT7Y404J

13a.Certifies that the items identified above were manufactured inconformity to:	14a. ☒ PART-145.A.50 Release to service ☒ Other Regulation specified in block 12
☐ approved design data and are in condition for safe operation ☐ non-approved design data specified in block 12	Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with PART 145 and in respect to that work the items are considered ready for release to service.

13b.Authorised Signature	13c.Approval/Authorisation Number	14b.Authorised Signature	14c.Certificate/Approval Ref. no. UK.145.00142
13d.Name	13e.Date(dd/mmm/yyyy)	14d.Name U129340 Ian Williams Clement BAAE 416 CRS	14e.Date(dd/mmm/yyyy) 13.Oct.2017

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

British Airways Avionics Eng

Ely Meadow, Talbot Green,
Pontyclun, Cardiff
CF72 8XL
GB

BRITISH AIRWAYS ENGINEERING

Component Strip Report

Customer: AJW AVIATION

The Headquarters, Maydwell Avenue
Slinfold, West Sussex
RH13 0AS

Part Number: 2156-204A:03972 Serial Number:8284
Description: SMOKE DETECTOR (VITAL)
Repair Order Number: W40726 Order Number: 4518094
Equipment Number: 42064760 Batch Number: 0005824926 Warranty Requested:

Customer WORK REQUIRED :

Date of Receipt: 09.10.2017
Reason for Removal:
Removal Code: W474 FE
Reason for removal: STATUS MSG FWD CARGO SMOKE DET 2

Date Serviceable: 13.10.2017
Unable to confirm reason for removal - '..CARGO SMOKE DET 2'
Spare lamp missing. Replaced: lamp.
Unit given final test - satisfactory IAW ATA:26-16-04 ATP:07546 REV:9
Unit released under TCCA Approval No. 808-04

Warranty Decision:

Tested ☐ Repaired ☒ Overhauled ☐ Inspected ☐
Re-manufactured ☐ New ☐ Modified ☐

Certification Number: BA000032874521