1. Approving Civil Aviation Authority/Country	2.	3. Form Tracking Number.
Transport Canada	**AUTHORIZED RELEASE CERTIFICATE** *FORM ONE*	**WO37450**

4. Organization Name and Address.

AJW Technique Inc
7055, rue Alexander Fleming
Saint-Laurent QC H4S-2B7
Canada

AJW technique

5. Work Order, Contract or Invoice Number:
R294583-1

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial/Batch Number:	11. Status/Work:
1	FLIGHT AUGMENTATION COMPUTER - F,	B397BAM0510	1.00	5554	REPAIRED

12. REMARKS

Repaired and tested serviceable in accordance with CMM 22-66-32A , Rev 27 . Dated: FEB 06/14

For more information refer to the Teardown / Inspection report.

PRINTED FROM ELECTRONIC FILE

EASA Approval No.: EASA.145.7260
Maintenance performed in accordance with FAR 43.17

13a. Certifies the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation.

☐ Non-approved design data specified in Block 12

14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations.

☒ CAR 571.10 Maintenance Release

☒ Other regulation specified in Block 12

13b. Signature:	13c. Approved Organization Number	14b. Signature	14c. Approval Organization Number
			33-12
13d. Name (Typed or Printed):	13e. Date	14d. Name (Typed or Printed)	14e. Date (dd/mmm/yyyy)
		Mehran Mohammady	21/Jun/2016

Installer Responsibilities

This certficate does not constitute authority to install the part.

Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified.
Statements in blocks 13a or 14a do not constitute installation certification. In all cases,the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.

AJW technique

7055 Alexander-Fleming st, Suite 100, Saint-Laurent, QC, Canada, H4S 2B7
www.ajw-aviation.com

Tear Down/Inspection Report

Work Order #: WO37450
Date Printed: 21/06/2016
Customer RO: R294583-1
Page: 1

To:
A J WALTER AVIATION LIMITED
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM

Phone #: **Fax #:** **Email:**
Code: AJW01 **PN:** B397BAM0510 **Serial # :** 5554 **Qty:** 1
Descr: FLIGHT AUGMENTATION COMPUTER - FAC **Mfg:** THALES

TSN: N/A **TSO:** N/A **TSR:** N/A **CSN:** N/A **CSO:** N/A **CSR:** N/A

P/N Out: B397BAM0510 **Serial # out:** 5554

Symptoms:

CODE: REPAIR
DETAILS: INSTALLED ON SECOND POS. AND GENERATES ECAM YAW DAMPER 2 FAULT - SUSPECTED FAC CAUSING FMGC #2 FAULT.

Faults:

CODE: QUOTE
DETAILS: PRELIMINARY INSPECTION (VISUAL):

PART MISSING:	NO
DAMAGE FOUND (CID):	NO
HRS/CYCLE RECEIVED:	NO

ADDITIONAL REQUIREMENT:

AD, SB, MOD, SIL	NO
ADD.CUST. REQUEST	NO

WARRANTY REQUESTED? NO

TEST ARRIVAL:

INITIAL TEST FAIL? NO

REASON FOR REMOVAL CONFIRMED: NO, Unit passed test

DISASSEMBLY/INSPECTION:

ANY ANOMALIES FOUND DURING DISASSEMBLY/INSPECTION NO

WORK TYPE: REPAIR

WORKSCOPE:

CALIBRATION	NO
CLEANING	YES
OUT OF SCOPE	NO
OVERHAUL	NO

Form created with Quantum Control(tm) technology. Product Licensed to: AJW Technique Inc.

PAINTING		NO
PCBR		NO
REPAIR		YES
REWORK	NO	
TIME CONTROLLED/TX		NO
RE-QUOTE:		NO

CODE: CLEANING

DETAILS: Cleaning is required due to reducing possible intermittent problem on the aircraft.

CODE: REPAIR

DETAILS: The following repairs will be performed:
Cleaning the unit.
Unit will be repaired and tested in accordance with CMM.

Corrective Actions:

CODE: REPAIRED

DETAILS: Cleand the unit.
The unit is repaired and tested serviceable in accordance with CMM 22-66-32A , Rev 27 . Dated: FEB 06/14