1. Approving Competent Authority / Country	2.	3. Form Tracking Number:
CAA/UK	**AUTHORISED RELEASE CERTIFICATE** CAA FORM 1	**WAV2205699**

4. Organization Name and Address:	5. Work Order / Contract / Invoice Number:
Avia Technique SK AeroSafety Group **Avia Technique Ltd.** **Unit 1,3,4, 6 Fishponds Estate** **Fishponds Road** **Wokingham, Berkshire, United Kingdom RG41 2QJ** **Ph: +441189789789, Fax: +441189794511**	**WAV2205699** **T37325**

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status / Work:
1	Fire Extinguisher	473957	1.00	57520EL	Repaired

12. Remarks:

CMM: 26-21-63 Revision: 20

"The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR Part 43 and in respect to that work, the items are approved for return to service under certificate no. I8QY183X"

Next Overhaul / Hydrostatic Test: 09/2023.
Last Overhaul/Hydrostatic Test: 09/2018.
Checked Weight: 43.24 Lbs.
Cartridge P/N: 446616. S/N: ADC9363. Service Life Start: 01/2014. Service Life Ends: 01/2024.
Cartridge P/N: 446617. S/N: ADD5307. Service Life Start: 03/2014. Service Life Ends: 03/2024.
Avia Technique have checked and verified compliance with all applicable AD's and SB's.

13a. Certifies that the items identified above were manufactured in conformity to:	14a. [X] Part-145.A.50 Release to Service [X] Other regulation specified in Block 12
☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12	Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Part-145, and in respect to that work the items are considered ready for release to service.

13b. Authorised Signature:	13c. Certificate /Approval Ref No.:	14b. Authorised Signature: AVIA 44	14c. Certificate /Approval Ref No.: **UK.145.00846**
13d. Name	13e. Date (dd/mmm/yyyy):	14d. Name Jack West	14e. Date (dd/mmm/yyyy): 29/Apr/2022

USER / INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts items from the Airworthiness Authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

1. Approving Competent Authority / Country	2.	3. Form Tracking Number:
EASA	**AUTHORISED RELEASE CERTIFICATE** EASA FORM 1	**WAV2205699**

4. Organization Name and Address:

Avia Technique
SK AeroSafety Group

Avia Technique Ltd.
Unit 1,3,4, 6 Fishponds Estate
Fishponds Road
Wokingham, Berkshire, United Kingdom RG41 2QJ
Ph: +441189789789, Fax: +441189794511

5. Work Order / Contract / Invoice Number:
WAV2205699 / T37325
T37325

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status / Work:
1	Fire Extinguisher	473957	1.00	57520EL	Repaired

12. Remarks:

CMM: 26-21-63 Revision: 20

Next Overhaul / Hydrostatic Test: 09/2023.
Last Overhaul/Hydrostatic Test: 09/2018.
Checked Weight: 43.24 Lbs.
Cartridge P/N: 446616. S/N: ADC9363. Service Life Start: 01/2014. Service Life Ends: 01/2024.
Cartridge P/N: 446617. S/N: ADD5307. Service Life Start: 03/2014. Service Life Ends: 03/2024.
Avia Technique have checked and verified compliance with all applicable AD's and SB's.

13a. Certifies that the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation.

☐ Non-approved design data specified in Block 12

14a. ☒ Part-145.A.50 Release to Service ☐ Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Part-145, and in respect to that work the items are considered ready for release to service.

13b. Authorised Signature:	13c. Certificate /Approval Ref No.:	14b. Authorised Signature:	14c. Certificate /Approval Ref No.:
		AVIA 44	**EASA.UK.145.00846**
13d. Name	13e. Date (dd/mmm/yyyy):	14d. Name Jack West	14e. Date (dd/mmm/yyyy): 29/Apr/2022

USER / INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts items from the Airworthiness Authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Avia Technique Ltd.
Unit 1,3,4, 6 Fishponds Estate
Fishponds Road
Wokingham, Berkshire, United Kingdom
RG41 2QJ
Ph: +441189789789, Fax: +441189794511

Tear Down/Inspection

Work Order #: WAV2205699
Date Printed: 21/04/2022
Page: 1

To:
A.J. Walter Aviation Ltd.
Maydwell Avenue
The Headquarters
Slinford RH13 0AS
United Kingdom

Ship To:
A.J. Walter Aviation Ltd.
Maydwell Avenue
The Headquarters
Slinford RH13 0AS
United Kingdom

Reference: T37325
Date Received: 07/04/2022
Part Number: 473957
Description: Fire Extinguisher
Serial Number: 57520EL

Customer Remarks:

Test

Results from inspection:

Unit requires Repair and Recertification

Repair Required.

DOM: 12/2000.

Next Overhaul Due: 09/2023.

Handle Damaged.

Cartridge PN: 446617. SN: ADD5307. Life Exp: 03/2024.
Cartridge PN: 446616. SN: ADC9363. Life Exp: 01/2024.

Corrective actions:

Repair and Test with reference to correct CMM

Replace Cartridges.

Replace Handle.

Inspection report generated by: Mark Northway