1. Approving National Aviation Authority/Country:
FAA/UNITED STATES

2.

AUTHORIZED RELEASE CERTIFICATE

FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:
SO 31998087-1.000

4. Organization Name and Address:
B/E AEROSPACE, INC.
10800 PFLUMM RD. LENEXA, KS 66215-4061

FAA REPAIR STATION # PB9R229N
EASA REPAIR STATION # EASA.145.5461

5. Work Order/Contract/Invoice number:
PO W16901

6. Item:	7. Description:	8. Part Number:	9. Eligibility: *	10. Quantity:	11. Serial/Batch Number:	12. Status/Work:
1.000	**WATER BOILER**	**3510-0030-03**	**N/A**	**1**	**S/Ns 474958101**	**REPAIRED**

13. Remarks:

B/E Aerospace Inc. Repair Station certifies work was performed in accordance with FAA approved data. The full details of work carried out, including all service documentation and Engineering data used to perform the work, is specified on attached work order number 5535800.

B/E Aerospace Inc. Repair Station Certifies that the work specified in blocks 12 & 13 was performed in accordance with EASA Part 145, and with respect to that work, the component is considered ready for release to service under EASA Part 145 Approval Number EASA 145-5461.

14. Certifies the items identified above were manufactured in conformity to:

- ☐ Approved design data and are in a condition for safe operation.
- ☐ non-approved design data specified in block 13.

15. Authorized Signature:

16. Approval/Authorization No.:

17. Name (Typed or Printed):

18. Date (m/d/y):

19. ☑ 14 CFR 43.9 Return to Service ☑ Other regulation specified in Block 13 Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

20. Authorized Signature:
Patricia A. Titmus

21. Approval/Certificate No.:
PB9R229N

22. Name (Typed or Printed):
Patricia A. Titmus

23. Date(m/d/y):
Mar/18/2013

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

B/E AEROSPACE, INC.

10800 Pflumm Road, Lenexa, KS 66215

FAA Repair Station No. PB9R229N, EASA Repair Station No. EASA.145.5461

WORK ORDER FORM

Repair Id No:	130311-0030	Sales Order No:	31998087
Work Order No:	05535800	Customer:	A J WALTER AVIATION LTD
Received Date:	03/11/2013	Ship To No:	201824
Part Number:	3510-0030-03	Part Description:	WATER BOILER
Customer PO:	W16901	Serial No:	474958101
Customer Part No:	-	Manuf. Date:	01/2012
Reason For Return:	INOP	Flight Hours:	
Part Status Code (8130):	Repaired		

Reason for Removal Confirmed(X if confirmed): X

Warranty(X if warranted): X

Preliminary Inspection Notes

NO/CUP.VENT VALVE STICKING.USED TEST VALVE FOR PRELIM.BREWED UNIT X2.CLEAN,REPAIR AND TEST PER CMM OR LATEST DRAWINGS.

Parts List

PART #	DESCRIPTION	QTY	REPLACE REASON	LOT CODE	SCRAP
3520-0483-01	FLOAT ASSY, VENT VALVE	1.0	Degraded - STICKING	10394813	☑
OR-0941-98	SSP>O-RING (UNPACKAGED)	1.0	Degraded - WORN	10347671	☑

Repair Notes

REPLACED STICKING FLOAT ASSY AND WORN O-RING.CLEANED UNIT PER B/E CMM 25-30-40 REV 1 1/31/97.REF B/E DRAWING 3510-003 REV B 2/18/90.B/E DCR # 101029-8244 C.W.

TECHNICIAN: Elizabeth Szczepaniak

TESTED BY:

DATE: 03/14/2013 08:48:55

DATE: 3/15/13

INSPECTOR:

DATE: MAR 16 2013

Print BACK