1. Approving Civil Aviation Authority/Country:	2.	3. Form Tracking Number:
FAA/United States	**AUTHORIZED RELEASE CERTIFICATE** FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG	T30896

4. Organization Name and Address:

Air Transport Components ATC

900 N. Fiesta Blvd.
Gilbert, AZ 85233
480-831-1268 FAX 480-831-1314

Z6AR209Y

5. Work Order/Contract/Invoice Number: W0105755

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	#5 FLAP TRANSMISSION	256A3410-6	1	1069/3410	OVERHAULED

12. Remarks:

OVERHAULED UNIT IAW BOEING CMM 27-55-70, REV #26 DATED NOV 01/17.
TSO:00.00, CSO:00.00.

"AIR TRANSPORT COMPONENTS CERTIFIES THAT THE WORK SPECIFIED IN BLOCK 11/12 WAS CARRIED OUT IN ACCORDANCE WITH PART-145 AND IN RESPECT TO THAT WORK THE AIRCRAFT COMPONENT IS CONSIDERED READY FOR RELEASE TO SERVICE UNDER EASA APPROVAL CERTIFICATE NO: EASA.145.5116."

13a. Certifies the items identified above were manufactured in conformity to:	14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.	
☐ Approved design data and are in a condition for safe operation ☐ Non-approved design data specified in Block 12		
13b. Authorized Signature:	14b. Authorized Signature:	14c. Approval/Certificate No: Z6AR209Y
13d. Name (Typed or Printed):	14d. Name (Typed or Printed): ROGER TEMPLETON	14e. Date (dd/mmm/yyyy): 25/JUN/2018

13c. Approval/Authorization No:

13e. Date (dd/mmm/yyyy):

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Air Transport Components ATC

900 N. Fiesta Blvd.
Gilbert, AZ 85233
Ph: 480-831-1268

FAA Repair Station #
Z6AR209Y
Fx: 480-831-1314

COMPONENT TEARDOWN/CONDITION REPORT

Customer 10109 AJ WALTER AVIATION LTD. WORK ORDER# W0105755
Nomenclature #5 FLAP TRANSMISSION MFG CUST-PO# T30896
Part Number 256A3410-6 S/N 1069/3410 A/C

Reason For Removal/Customer Instructions Modifications/S.B/A.D Compliance
OVERHAUL AS REQUIRED IAW MFG SPECS.
DUAL RELEASE REQUIRED.

Visual Inspection Prior To Teardown:
UNIT DIRTY. PAINT CHIPPED / WORN.

Preliminary Test Results:
TESTED IAW CURRENT OEM/MFG SPECS.
ALL TESTS PASSED.

Teardown And Inspection Findings:
HARDWARE WORN, SEALS WORN, PACKINGS WORN, LUBE FITTINGS WORN, SPRINGS WORN, BEARINGS WORN, MARKER WORN, PAWLS WORN, SHIMS WORN, SHAFT WORN, PLATING WORN, REFINISH REQUIRED.

Corrective Action Taken:
OVERHAULED UNIT IAW BOEING CMM 27-55-70, REV #26 DATED NOV 01/17.
TSO:00.00, CSO:00.00.

Final Disposition: OVERHAULED

TECH JLR JOSE ROBLEDO INSPECTOR RT ROGER TEMPLETON DATE JUN/25/2018

For further info contact Mike Charron at 480-831-1268 FAX 480-831-1314

ATC009

Air Transport Components

900 N. Fiesta Blvd.
Gilbert, AZ 85233
Ph: 480-831-1268

FAA Repair Station #
Z6AR209Y
Fx: 480-831-1314

COMPONENT TEARDOWN/CONDITION REPORT

Customer 10109 AJ WALTER AVIATION LTD. WORK ORDER# W0105755
Nomenclature #5 FLAP TRANSMISSION MFG CUST-PO# T30896

**** PARTS REPLACEMENT RECORD ****

QTY	Item #	Part Number	Nomenclature
7	296,15	BACB30NT3K2	BOLT
11	85,15,25,297	BACW10BP3CD	WASHER
1	35	M25988-1-024	PACKING
1	50	M25988-1-149	PACKING
16	330,150,410	BACW10BN4AC	WASHER
1	13S	AS5169D04L	PLUG
1	140	M25988-1-110	PACKING
16	225,30,243	BACW10BP5CD	WASHER
1	190	M25988-1-150	PACKING
2	215	M25988-1-127	PACKING
4	240	BACB30VF3K1	BOLT
2	295	M25988-1-136	O-RING
1	310	M25988-1-153	RING
2	415	BACW10BN4AP	WASHER
2	420	BACN11Z4CD	NUT
1	620	256W3052-2	LOCKWASHER
1	625	BACN10RF12	NUT
1	555	M25988-1-259	PACKING
1	540	S256W410-20	SEAL
1	545	M25988-1-151	PACKING
4	400	1728B	FITTING
1	685B	256A3195-46	MARKER NAMEPLATE
1	25	M25988-1-016	ORING
1	20A	M25988-1-008	PACKING
1	260	256A3175-2	LOCK WASHER CUP
1	265	BACN10RF10	NUT
1	90	M25988-1-117	PACKING
4	325	BACB30MR4HK3	BOLT
2	705	251N4119-1	SPRING
2	50	256W3050-41	SHIM
2	80	BACB30MR3AH4	BOLT
1	320	256A3175-1	LOCK WASHER
1	335	BACN10HY8M	NUT
2	390,365	251N4105-1	BEARING
2	710	251N4117-3	PAWL
1	10	BACB30MR3HK2	BOLT
1	10	BACB30MR3HK2	BOLT
1	60	700-869-2272-99	SEAL
1	125	256W3098-1	SHAFT
1	75	256W3093-1	SPRING

Air Transport Components

900 N. Fiesta Blvd.
Gilbert, AZ 85233
Ph: 480-831-1268

FAA Repair Station #
Z6AR209Y
Fx: 480-831-1314

COMPONENT TEARDOWN/CONDITION REPORT

Customer 10109 AJ WALTER AVIATION LTD. WORK ORDER# W0105755
Nomenclature #5 FLAP TRANSMISSION MFG CUST-PO# T30896

**** PARTS REPLACEMENT RECORD ****

QTY	Item #	Part Number	Nomenclature
1		BACN10RF20	NUT