1. Approving Competent Authority / Country: United Kingdom Civil Aviation Aurthority	2	**AUTHORISED RELEASE CERTIFICATE EASA FORM 1**	3. Form Tracking Number: **L 2527341**
4. Organization Name and Address: **Panasonic**	**Panasonic Avionics Corporation** Quadrant House, Heron Drive, Parlaunt Road, Langley Berks, SL3 8XP, UK		5. Work Order/Contract/Invoice T27007

6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No	11. Status / Work
1	ZONE MULTIPLEXER	RD-AX2001-A	1	201235	INSPECTED/TESTED

12. Remarks PLEASE REFER TO SR NUMBER 4160864.

Certifies that unless otherwise specified in Block 12. the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service. UZVY163X.

Panasonic Avionics Corporation internal reference **SR4160864**

13a. Certifies the items identified above were manufactured in conformity to: ☐ approved design data and are in a condition for safe operation. ☐ non-approved design data specified in block 12.		14a. ☒ PART 145.A.50 Release to Service ☒ Other regulation specified in block 12 Certifies that unless otherwise specified in Block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.	
13b. Authorised Signature:	**13c. Approval/Authorization Number**	**14b. Authorized Signature:**	**14c. Certificate/Approval Ref No:** **UK.145.00297**
13d. Name	**13e. Date (dd mmm yyyy)**	**14d. Name** Sham Harrar	**14e. Date (dd mmm yyyy)** 17-NOV-2015

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

REPAIR REPORT / DELIVERY ORDER

Panasonic

Panasonic Avionics Corporation
Quadrant House, Heron Drive, Parlaunt Road,
Langley Berks, SL3 8XP, UK.
Tel: +44(0) 1753 741450 Fax: +44(0) 1753 741481

SOLD TO AJ WALTER AVIATION
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, ENGLAND RH13 0AS, GB

SHIP TO AJ WALTER AVIATION
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, ENGLAND RH13 0AS, GB

SHIP TRANSACTION:

CUSTOMER P.O. NUMBER	CUSTOMER	TAIL NO.	CUST PROD REF	SERVICE REQUEST
T27007	1001	NOT FOUND	12731143	4160864

PART NUMBER	NOMENCLATURE	DATE REMOVED	DATE RECEIVED
RD-AX2001-A	ZONE MULTIPLEXER		02-NOV-2015

SERIAL NUMBER	DATE OF MFG	WTY START DATE	WTY END DATE	DATE REPAIRED	SHIP DATE
201235	31-JAN-1990	31-JAN-1990	29-APR-1993	13-NOV-2015	

MOD IN: 1,2

REASON FOR CUSTOMER REJECTION	PLEASE TEST AND REPAIR
INTERNAL INSPECTION	No Physical Damage
EXTERNAL INSPECTION	No Physical Damage - DIRTY.
ACTUAL FAILURE / CORRECTIVE ACTION	UNIT PASSED ON TEST. NO FAULT FOUND. UNIT CLEANED, TESTED AND PASSED ALL FUNCTIONAL TESTS. ALL WORK HAS BEEN CARRIED OUT AND LRU CONFORMED IAW CMM 23-34-02 REV 15 DTD OCT 2014.

MOD OUT: 1,2

INSPECTED BY: Sham Harrar

REPAIRED BY: Blackwell, Gary

PART NUMBER	DESCRIPTION	QTY	UNIT PRICE	EXTENDED PRICE	CHARGED AMOUNT	WTY*
NFF FEE	AREA CONTROLLERS NFF FEE	1				
FREIGHT CHARGE	FREIGHT CHARGE	1				

Panasonic SHOP WARRANTY: All repairs referenced by this Repair Report are warranted as to parts and labor for a period of 12 months from the date of such repair. Used serviceable components may have been used in restoring this unit.

Cost of Labor
Cost of Material
Total Cost

* WTY CODES NO = Not Covered FOC = SB covers as FOC SHOP = Shop Wty
WARR = Mfg Wty in Effect FIXED = Fixed Price Repair CC = Panasonic Charged