Combined Inventory Receipt & Dispatch Check Sheet

THIS DOCUMENT MAY ONLY BE COMPLETED BY A PERSON THAT HAS RECEIVED TRAINING AND BEEN ISSUED WITH AN INSPECTORS STAMP

B&H WORLDWIDE
LEADERS IN AEROSPACE LOGISTICS

B&H Warehouse Reference	Boxtop Job Number	Date Received
FW301710		10/5/18

A visual inspection has been performed on this unit and the following informationchecked:

	RECEIPT ✓ for yes / ✗ for no		DISPATCH ✓ for yes / ✗ for no	
EASA Form (8130)	✓			
Trace Documentation				
OEM Certification				
DG Declaration				
MSDS (Material Safety Data Sheet)				
Shelf Life Applicable				
Material Certification / ATA 106				
US (unserviceable) Tag				
Reason for Removal Stated on Tag				
Packing Slip	✓			
Original Certificates Returned	✓			
Unused Statement				
Physical Checks to be completed	**RECEIPT ✓ for yes / ✗ for no**		**DISPATCH ✓ for yes / ✗ for no**	
Part Number on Unit Matches Paperwork	✓			
Serial Number on Unit Matches Paperwork	✓			
Description on Unit Matches Paperwork	✓			
All Paperwork carries the same part & serial number	✓			
Blanks fitted to ALL ports	✓			
FOD evident in ports / connectors				
Static Sensitive	✓			
Warranty labels INTACT	✓			
Following tasks MUST be completed on Receipt AND Dispatch	**RECEIPT ✓ for yes / ✗ for no**		**DISPATCH ✓ for yes / ✗ for no**	
Interior packaging sufficient to secure unit and weight of unit	✓			
Component wrapped in static sensitive bubble/pouch	✓			
Exterior packing condition acceptable for weight of unit	✓			
External Damage customer to inspect photo's				
Photos Taken – Package Exterior	✓			
Photos Taken – Item and packaging	✓			
Photos Taken – Component(s)	✓			
Photos Taken – Data Plates and Connectors	✓			
OnTrack Updated	✓			
Other (Specify)				
Customer advised / Pre alert sent		B&H		
Completed by (Trained Inspector Stamp)		21		

AJW technique

7055 Alexander-Fleming st, Suite 100, Saint-Laurent, QC, Canada, H4S 2B7
www.ajw-aviation.com

WO Packing Slip

WO #: WO71437

Date: 04/10/2018 **Time:** 10:12:55 AM

Cust Ref #: R346784-1

SM #:SH79717

SH79717

To:
A J Walter Aviation Ltd.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM

Ship To:
B AND H WORLDWIDE INC DORAL
8000 NW, 25TH STREET
SUITE 300
DORAL, FL 33122
UNITED STATES OF AMERICA

Order Date: 17/09/2018
Prepared By: SYSDBA
Customer #: AJW01
Buyer:


Ship Via:

Ship Via Acc:

Part Number/Description	Qty
PPA1101-00 Smoke Detector Loc/Whse: Serial #: 4497	1

DOCKED

Form created with Quantum Control(tm) technology. Product Licensed to: AJW Technique Inc.



ORIGIN ID:YULA (514) 339-5095
SHIPPING
AJW-TECHNIQUE INC
7055 RUE ALEXANDER-FLEMING

ST-LAURENT, PQ H4S2B7
CANADA CA

SHIP DATE: 04OCT18
ACTWGT: 1.00 KG MAN
CAD: 0682462/CAFE3111
DIMS: 29x24x22 CM

BILL RECIPIENT

TO

A J WALTER AVIATION INC C/O
B & H WORLDWIDE INC
8000 NW 25TH STREET SUITE 300
DORAL FL 33122 (US)

(305) 471-0444 TEMPORARY EXPORT OTHER:NOT SOLD

INV:
PO: DEPT:

946C1/88FB/53C1

FedEx Express

J171016102002uv

10:30A
INTL PRIORITY
ETD

TRK# 0430 4626 9551 1485

NF CTYA

33122
FL-US MIA

12x10x9 1kg

1. Approving Civil Aviation Authority/Country	2.	3. Form Tracking Number.
Transport Canada	**AUTHORIZED RELEASE CERTIFICATE** ***FORM ONE***	WO71437

4. Organization Name and Address.

AJW Technique Inc
7055, rue Alexander Fleming
Saint-Laurent QC H4S-2B7
Canada

5. Work Order, Contract or Invoice Number:
R346784-1

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial/Batch Number:	11. Status/Work:
1	Smoke Detector	PPA1101-00	1.00	4497	REPAIRED

12. REMARKS

Unit repaired as per CMM 26-16-16 rev.6 nov 16/10 specifications.

For complete information, refer to tear down/inspection report.

EASA Approval No.: EASA.145.7260
Maintenance performed in accordance with FAR 43.17

13a. Certifies the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation.

☐ Non-approved design data specified in Block 12

14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations.

☒ CAR 571.10 Maintenance Release

☒ Other regulation specified in Block 12

13b. Signature:	13c. Approved Organization Number	14b. Signature	14c. Approval Organization Number
		Tek Chak	33-12
13d. Name (Typed or Printed):	**13e. Date**	**14d. Name (Typed or Printed)**	**14e. Date (dd/mmm/yyyy)**
		Tek Chak	04/Oct/2018

Installer Responsibilities

This certificate does not constitute authority to install the part.

Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified.
Statements in blocks 13a or 14a do not constitute installation certification. In all cases,the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.

AJW technique
7065 Alexander-Fleming st, Suite 100, Saint-Laurent, QC, Canada, H4S 2B7
www.ajw-aviation.com

Tear Down/Inspection Report

Work Order #: WO71437
Date Printed: 04/10/2018
Customer RO: R346784-1

To:
A J Walter Aviation Ltd.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM

Phone #: Fax #: Email:
Code: AJW01 PN: PPA1101-00 Serial # : 4497 Qty: 1
Descr: Smoke Detector Mfg: SIEMENS SAS

TSN: 8895 TSO: 8895 TSR: 0 CSN: 6268 CSO: 6268 CSR: 0

P/N Out: PPA1101-00 Serial # out: 4497

Symptoms:


CODE: REMOVED FOR CLEANING
DETAILS: Unit removed for cleaning.

Faults:

CODE: DISASSEMBLY & INSPECTION FINDINGS
DETAILS: Unit very dirty, need to be cleaned
Labyrinthe very dirty, need to be cleaned
Unit tested as per CMM 26-16-16 rev.6 nov 16/10
CODE: CLEANING
DETAILS: Cleaning is required due to
Unit and Labyrinthe cleaned
CODE: REPAIR
DETAILS: The following repair(s) will be performed:
Unit very dirty, need to be cleaned
Labyrinthe very dirty, need to be cleaned
Unit tested as per CMM 26-16-16 rev.6 nov 16/10

Corrective Actions:


CODE: REPAIRED
DETAILS: Unit very dirty, cleaned
Labyrinthe very dirty, cleaned
Unit repaired as per CMM 26-16-16 rev.6 nov 16/10 specifications.




AJW


AJW
AMENDT


CERBERUS SA
MFR F4885
AMBIANT SMOKE DETECTOR
PNR PIA11 01.00
SER 4497
DMF 072001


CERBERUS SA
MFR F4885
AMBIANT SMOKE DETECTOR
PNR PPA11 01-00
C-W
SER 4497
DMF 072001






AJW
ajw-group.com
METTLER


B AND H WORLDWIDE INC DORAL
8000 NW. 25TH STREET
SUITE 200
SH79717
DORAL, FL 33122
UNITED STATES OF AMERICA
FRI
aiw-group.com