1. Approving Civil Aviation Authority/Country:	2.	3. Form Tracking Number:
FAA/UNITED STATES	**AUTHORIZED RELEASE CERTIFICATE** **FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG**	078249

4. Organization Name and Address:	5. Work Order/Contract/Invoice Number:
AirCo Services, LLC. 1851 S. Eisenhower Ct. Wichita KS 67209 FAA Certified Repair Station No.TI2R188L	078249


6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	AIR CONDITIONING MODULE	69-37319-308	1	D05542	REPAIRED

12. Remarks: REFERENCE WORK ORDER REPORT FOR WORK PERFORMED. ALL WORK PERFORMED i/a/w CMM NO. 31-37-07 Rev:48 Dt:04/10/18

MODS INSTALLED: NONE

Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the product/article is considered ready for release to service under EASA Part 145 approval no. EASA.145.4100.

13a. Certifies the items identified above were manufactured in conformity to:	14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12
☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.	Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:	13c. Approval/Authorization No.:	14b. Authorized Signature:	14c. Approval/Certificate No:
			TI2R188L
13d. Name (Typed or Printed):	**13e. Date (dd/mmm/yyyy):**	**14d. Name (Typed or Printed):**	**14e. Date (dd/mmm/yyyy):**
		ADAM HOLSTINE	20/Jun/2018

User/Installer Responsibilities

It is important to understand that the existence of this Document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

AIRCO SERVICES LLC.

AirCo Services, LLC
1851 S. Eisenhower Ct. Wichita, KS 67209
PH: (316) 945-9820 (800) 972-7626
FAX: (316) 945-8014
FAA REPAIR STATION #TI2R188L

WORK ORDER TEARDOWN

Work Order No. 078249

ORIGINAL PN:	69-37319-308
REVISED PN:	69-37319-308
DESC:	AIR CONDITIONING MODULE
SN:	D05542
MODEL:	
TECH:	GRANT
INSP:	ADAM

BILL TO:
A J WALTER AVIATION LTD
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 OSH
ENGLAND

SHIP TO:
AJ WALTER AVIATION LTD.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UK

Date	Cust No.	Terms	Customer Contact	Cust PO
06/20/18	01489	NET 45 DAYS BY W/T	BEN HOLMWOOD	R340765

F.O.B.	Ship Via	Manual	Rev	Rev Dt	Box #
COLLECT	FED EX INTERNATIONAL PRIORITY - 124277507	31-37-07	48	04/10/18	

Description	Qty
Action Requested: PART REQUIRES TESTING. ADVISE COST TO REPAIR IAW MFG SPECS.	
Preliminary Inspection/Defects Found: PERFORMED PRELIMINARY INSPECTION AND TESTING. FOUND INDICATOR LAMPS BURNED OUT, SWITCH CAPS AND BOOTS ARE WORN. NEED TO REPLACE ALL LAMPS, SWITCH CAPS, AND BOOTS. NEED TO CLEAN AS REQUIRED AND PERFORM FULL FUNCTIONAL TEST IAW MFG SPECS.	
Parts Required: LABOR 387 6832AS15 15PA90-6W 69-44578-2 SS	1.0 24.0 12.0 7.0 2.0 1.0
Action Taken: REPAIRED IAW MFG SPECS. CLEANED AND INSPECTED AS REQUIRED. REPLACED ALL LAMPS, SWITCH CAPS, AND BOOTS. PERFORMED FULL FUNCTIONAL TEST IAW MFG SPECS. TAGGED REPAIRED. TESTED AND CERTIFIED AIRWORTHY IAW CMM 31-37-07, REV 48, 04/10/18.	
By [signature] Date 06/20/2018	
TARIFF: 8537101010	