1. Approving Competent Authority/Country: Civil Aviation Authority/ United Kingdom	2. **AUTHORISED RELEASE CERTIFICATE EASA FORM 1**	3. Form Tracking Number REP360041/5018570 REV:1.0

4. Organisation Name and Address	5. Work Order/Contract/Invoice
GE AVIATION SYSTEMS LIMITED. T/A GE AVIATION. BISHOPS CLEEVE CHELTENHAM GLOUCESTERSHIRE GL52 8SF. T:+44(0)1242 673333, F:+44(0)1242 661661	R364191

6. Item	7. Description	8. Part No.	9. Qty	10. Serial No.	11. Status/Work
1	AUTOTHROTTLE SERVO MOTOR	305RAA1	1	AS05238	Inspected / Tested

12. Remarks: **Modifications**: NIL

SPECIFICATION : CMM 22-30-15 REVISION 13

TCCA Certificate No : 899-10

The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate no. XSMY589K

If you have any query with this document please contact the Quality Department at the above address.

13a. Certifies the items identified above were manufactured in conformity to:

☐ approved design data and are in a condition for safe operation

☐ non-approved design data specified in block 12

14a. ☒ **Part 145.A.50 Release to Service** ☒ **Other regulation specified in block 12**

Certifies that unless otherwise specified in block 12 the work identified in block 11 and described in block 12 was accomplished in accordance with Part – 145 and in respect to that work the items are considered ready for release to service.

13b. Authorised Signature	13c. Approval/ Authorisation No	14b. Authorised Signature	14c. Certificate/Approval Ref. No.
		S. Eyles Electronic Signature on File	UK.145.00083
13d. Name	**13e. Date (dd-mmm-yyyy)**	**14d. Name**	**14e. Date (dd-mmm-yyyy)**
		SEAN EYLES	10-SEP-2019

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with the regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts item from the airworthiness authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

PRINTED FROM ELECTRONIC FILE

WORKSHOP REPORT NUMBER
REP360041/5018570 REV 1.0

DATE RECEIVED	CUSTOMER	CUSTOMER ORDER NO.
28-AUG-2019 13:50:49	AJ WALTER AVIATION LTD	R364191

	AS RECEIVED	AS RELEASED
CODE	305RAA1	305RAA1
DESCRIPTION	AUTOTHROTTLE SERVO MOTOR	AUTOTHROTTLE SERVO MOTOR
SERIAL NO.	AS05238	AS05238
MOD STATE	NIL	NIL

CUSTOMER REPORTED DEFECT
Failed. Servo test not passed.

CUSTOMER REPORTED FAULT CONFIRMED
No

STATUS/WORK
Inspected / Tested

RESULTS OF EXAMINATION
1. UNIT FULLY TESTED WITH NO FAULTS FOUND.

REPAIR ACTION
1. CHECKED AND TESTED I.A.W. CMM 22-30-15 REVISION 13.

APPROVED	NAME	DATE
S. Eyles	SEAN EYLES	10-SEP-2019

WORKSHOP REPORT NUMBER
REP360041/5018570 REV 1.0

DATE RECEIVED	CUSTOMER	CUSTOMER ORDER NO.
28-AUG-2019 13:50:49	AJ WALTER AVIATION LTD	R364191

PARTS REPLACED

PART NUMBER	DESCRIPTION	QUANTITY	QUALITY RELEASE