1. Approving Competent Authority / Country	2.	3. Form Tracking Number
LUFTFAHRT-BUNDESAMT **Germany**	**AUTHORISED RELEASE CERTIFICATE** **EASA FORM 1**	**DB 90467512 1/1**

4. Organisation Name and Address:	5. Work Order/Contract/Invoice
AIRBUS Operations GmbH Cabin Electronics Lüneburger Schanze 30 21614 Buxtehude, Germany	**W27957**

6. Item	7. Description	8. Part No.	9. Qty	10. Serial-No.	11. Status/Work
N/A	CIDS CAM	Z050H6033100	1	050H60008272	REPAIRED

12. Remarks: see Maintenance Report No.1024553
Work performed as per: C.M.M. 23-73-19 Rev. 12 OCT-20-2014 and Production Release Document Z050H6033100, Spec. Issue:1, FEB-06-2007
work accomplished: APR-28-2015

The work identified in block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate no. K30Y905Y.

13a. Certifies that the items identified above were manufactured in conformity to:

☐ approved design data and are in a condition for safe operation

☐ non-approved design data specified in block 12

14a. ☒ Part-145.A.50 Release to Service ☒ Other Regulation specified in block 12

Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.

13b. Authorised Signature:	13c. Approval/Authorisation Number:	14b. Authorised Signature:	14c. Certificate/Approval Ref.No.: **DE.145.0286**
13d. Name:	13e. Date (dd/mmm/yyyy):	14d. Name: **Mäckelmann**	14e. Date (dd/mmm/yyyy): **28.Apr.2015**

USER / INSTALLER RESPONSIBILITIES
This certificate does not automatically constitute authority to install the item(s).
Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

1 国家 Country	2. 中国民用航空总局 CAAC ☐符合性 Conformity ☒适航性 Airworthiness	3 证书编号 Certificate Ref. No.
China	批准放行证书/适航批准标签 **AUTHORIZED RELEASE CERTIFICATE/AIRWORTHINESS APPROVAL TAG**	**DB 90467511**

4 单位 Organization		5 工作单/合同单/货单 Work Order/Contract/Invoice
AIRBUS	AIRBUS Operations GmbH Cabin Electronics Lüneburger Schanze 30 21614 Buxtehude, Germany Plant Werk Buxtehude	**W27957**

6 序号 Item	7 内容 Description	8 件号 Part No.	9 适用性 Eligibility	10 数量 Qty	11 系列号/批号 Serial/Batch No.	12 产品状态 Status/Work
0001	**CIDS CAM**	**Z050H6033100**	**A320-200**	**1**	**050H60008272**	**REPAIRED**

13 备注 Remarks

see Maintenance Report No.1024553 Work performed as per: C.M.M. 23-73-19 Rev. 12 OCT-20-2014 and Production Release Document Z050H6033100, Spec. Issue:1, FEB-06-2007 work accomplished: APR-28-2015

14 新产品 New Parts

兹声明上述产品除第13项的其它规定以外，已按照上述国家适航条例进行制造/检查，并且该产品（出口产品）符合经批准的型号设计资料和进口国提出的专用要求。

Certifies that the Part(s) identified above except as otherwise specified in block 13 was(were) manufactured/inspected in accordance with the airworthiness regulations of the stated country and/or in the case of parts to be exported with the approved design data and with the notified special requirements of the importing country.

15 使用过的产品 Used Parts

兹声明上述产品除第13项的其它规定以外，已按照上述国家适航条例和进口国通知的特殊要求进行了工作，该产品处于安全可用状态可以批准放行使用。

Certifies that the work specified above except as specified in block 13 was carried out in accordance with the airworthiness regulations of the stated country and the notified special requirements of the importing country and in respect to that work, the part(s) is (are) in condition for safe operation and considered ready for release to service. (over)

16 批准人签名 Signature

18 批准日期 Date **28.Apr.2015**

17 批准人姓名（打印的） Name(Printed) **Mäckelmann DA_K_9**

19 中国民航总局授权 Issued by or on behalf of the CAAC

F04900446

AAC-038(12/94)

BXP-MD100

*参阅产品目录详细查找适用性

Cross-check eligibility for more details with parts catalogue

批准放行证书/适航批准标签
AUTHORIZED RELEASE CERTIFICATE/AIRWORTHINESS APPROVAL TAG

使用者/安装者职责
USER/INSTALLER RESPONSIBILITIES

(1)必须明确：本文件并不批准零件/组件/部件可以装到有关产品上。
(2)当使用者/安装者使用的是所在国适航当局的条例，而不是本表第1项中所指国家适航当局的条例时，使用者/安装者必须保证所在 国的适航当局能接受所指国家适航当局批准出口的零件/组件/部件。
(3)表中第14项、第15项的陈述，并不说明本表是安装批准。在所有情况下，航空器使用前，航空器使用者/安装者应把按本国适航 条例颁发的安装批准放入维修记录中。

(1)It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly.
(2)Where the user/installer works in accordance with the national regulations of an Airworthiness Authority different than the Airworthiness Authority of the country specified in block 1 it is essential that the user/installer ensure that his/her Airworthiness Authority accepts parts/components/assemblies from the Airworthiness Authority of the country specified in block 1.
(3)Statements 14 and 15 do not constitute installation certification. In all cases the aircraft maintenance record must contain an installation certification issued in accordance with the national regulation by the user/installer before the aircraft may be flown.

MAINTENANCE ORDER	V Activity Category	1024553 Maintenance Number	FSCM C9072 AIRBUS

Customer	Part Number	Serial No SPEC2000	Amd.
AJW	Z050H6033100	050H60008272	
	Description: CIDS CAM	Quantity: 1	Repair-Station: BUX

Customer Order	Cust. Order Date	Work Order	Work Order Date	Prio
W27957	14.04.2015	1024553	17.04.2015	ROUTINE

Required Activities:	Test	Repair	Modify	Inspection	Scrap	Overhaul	Entry Date	Redelivery Date
	X	X		X			17.04.2015	23.04.2015

Reason for Return: **NO CAM DATA.**

Operator	Removal Date	AC-Reg	AC Type	Station	Release Certificate	Warranty	Chargeable
LTC		YL-LCD	A320	UKN	AAC038/EDUAL	X	

	Operators Man	OEM-Man	Aviation Device	Package
		O.E.M.-M	YES	OK

Administrator:	Department:	Phone:
Seckerdieck	ECYS1	(0)40 743 54998

MAINTENANCE REPORT	Preliminary Inspection/HDI	Pre- Strip-Test	Cond. elec.	Cond. SW	Cond. mech.	BITE
		YES	OK	BAD	OK	N/A

Status of Removal	Tech. warranty	Missing Part
Confirmed Removal	YES	NO

Findings: **The CAM was found not loadable due to corrupted software.**

Remarks: **Work performed as per:**
C.M.M. 23-73-19 Rev. 12 OCT-20-2014 and
Production Release Document Z050H6033100, Spec. Issue:1, FEB-06-2007

Work performed: **Preliminary- and hidden damage inspection performed.**
CAM reprogrammed.
Acceptance test successfully performed.

33 012 Bredow

Final Condition	PN_After	SN_After	AMD_After
	Z050H6033100	050H60008272	

Tested	Repaired	Modified	Modified internal	Cond as is	Scrapped	Overhauled
X	X					

Warranty_Charge_WC	NFF	QA-Inspected
W		28. April 2015

Work performed staff	Work performed department	Work performed date
Bredow	ECYS3	28.04.2015